

ENCLOSURE 1

SHINE MEDICAL TECHNOLOGIES, LLC

SHINE MEDICAL TECHNOLOGIES, LLC OPERATING LICENSE APPLICATION SUPPLEMENT NO. 6 AND RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

FINAL SAFETY ANALYSIS REPORT CHANGE SUMMARY

Summary Description of Changes	FSAR Impacts
Administrative corrections including clarification of the aging factor applied for battery sizing and correction of the revision year for a referenced industry standard.	Section 8a2.2, Table 8a2.2-2, Section 8a2.3
Update to incorporate normal electric power supply system (NPSS) design changes including changes to the off-site power service supplies as well as changes to the on-site distribution service design.	Section 8a2.1, Figure 8a2.1-1, Section 8a2.2
Update to incorporate uninterruptable electrical power supply system (UPSS) design changes including updates to UPSS electrical loading to include data from equipment vendor specifications and UPSS load list calculation updates.	Section 8a2.2, Table 8a2.2-1, Table 8a2.2-2

Final Safety Analysis Report (FSAR) mark-ups related to the SHINE Medical Technologies, LLC (SHINE) responses to requests for additional information are provided as Attachment 1 to Enclosure 2 (non-public version) and Enclosure 3 (public version). FSAR mark-ups associated with the above FSAR changes are included with those mark-ups provided as Attachment 1 to Enclosure 2 and Enclosure 3.