NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION				
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
1. LICENSEE:		2. NRC/REGIONAL OFFICE		
Raba Kistner Consultants, Inc. Remote Inspection from office, licensee address: 12821 West Golden Lane, San Antonio, Texas REPORT NO.: 2020-001		U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd Arlington, Texas 76011-4511		
3. DOCKET NUMBER 4. LICENSE NUMBER		5. DATES OF INSPECTION		
030-31691	42-27031-01		Octobe	r 29 - November 10, 2020
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X				
Licensee's Statement of Corrective Actions for Item 4, above.				
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.  Title Printed Name Signature Date				
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR Jason D	ykert			
BRANCH CHIEF Dan Bra	adley			
NRC FORM 591M PART 1				
Non-Public Sensitive – Se	ecurity-Related	x	Public	X Non-Sensitive