

**From:** Thacker, Bobby Henry <bhthacker@tva.gov>  
**Sent:** Thursday, December 21, 2017 4:46 AM  
**To:** Thompson, Russell R  
**Subject:** RE: NRC Submittal Regarding Anchor Darling Double Disc Gate Valves

The pressed on collar is a real issue with Regulator, thanks o LaSalle. However, there is no current requirement to do anything with them other than monitor.

If SQN did this now it would just be proactive.

BFN is not necessarily going down the correct road either since we started we would monitor stem rotation.

This is the first I have heard of this.

I will check with the sites first and then get back to you. This should not affrec our submittal.

Thanks, Russell.

Sent from VMware Boxer

On Dec 20, 2017 11:10 AM, "Thompson, Russell R" wrote:

Can you pulse some of your industry MOV program peers, please?

For SQN, we're making commitments to repair some valves in the next outage, consistent with the template response.

For BFN, there is a paperwork exercise to be performed regarding pressed-on collars that may lead to future field work.

Is there another plant in this same status, and if so, are they making any commitments regarding completion of the paperwork task?

Thanks.....

Russell Thompson

Corporate Nuclear Licensing

W: 423/751-2567

C: 423/285-3405

**This electronic message transmission contains information which may be TVA SENSITIVE, TVA RESTRICTED or TVA CONFIDENTIAL. Any misuse or unauthorized disclosure can result in both civil and criminal penalties. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the content of this information is prohibited. If you have received this communication in error, please notify me immediately by email and delete the original message.**

---

**From:** Thacker, Bobby Henry

**Sent:** Wednesday, December 20, 2017 9:52 AM

**To:** Thompson, Russell R

**Subject:** RE: NRC Submittal Regarding Anchor Darling Double Disc Gate Valves

Looks good.

---

**From:** Thompson, Russell R

**Sent:** Tuesday, December 19, 2017 2:43 PM

**To:** Thacker, Bobby Henry; Derriso, Patrick M

**Subject:** FW: NRC Submittal Regarding Anchor Darling Double Disc Gate Valves

**From:** Thompson, Russell R

**Sent:** Tuesday, December 19, 2017 2:19 PM

**To:** Douglas, Steven M; Noe, P Todd; Meisner, Erik Charles; Moore, Gerald Dwayne; Reneau, William Christopher; Henderson, Michael Ryan; Jenkins, Beth Ann; Rymer, Stuart Loveridge

**Cc:** Wetzel, Beth A; Paul, Jamie Lee; Oliver, Michael W; Johnson, Jonathan Thornton; Hulvey, Kimberly Dawn; Pate, Anthony Lee; Nicely, Jeff A; Wilson, Donald Eugene Jr.

**Subject:** NRC Submittal Regarding Anchor Darling Double Disc Gate Valves

In accordance with the attached NSIAC direction, TVA is preparing to submit to NRC a listing of each site's active safety function Anchor Darling DDGV valve population with relevant valve information, including the results of the evaluation of these valves to the industry guidance.

Identification of valves considered susceptible will include the repair status. A repair schedule for each susceptible valve not yet repaired will be provided. Formal commitments will be made to track these repairs.

The concurrence by each site's Engineering director and program manager is for the completeness and accuracy of their respective site's information. Note that WBN is concurring that the site doesn't have any active safety-function ADDDGVs.

For the commitments, it's my intent that the Engineering Program Managers should sign for them. I intend to have the submittal distributed for concurrence reviews no-later-than Thursday. I would appreciate feedback regarding everyone's availability this week and next for their review and concurrence. If there are times that you will not be available, please let me know who will have signature authority for you.

I've also attached a draft of the letter with the SQN valve information included.

Please let me know if you have any questions, and thanks.....

Russell Thompson

Corporate Nuclear Licensing

W: 423/751-2567

C: 423/285-3405



**MSM - UMR**

**This electronic message transmission contains information which may be TVA SENSITIVE, TVA RESTRICTED or TVA CONFIDENTIAL. Any misuse or unauthorized disclosure can result in both civil and criminal penalties. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the content of this information is prohibited. If you have received this communication in error, please notify me immediately by email and delete the original message.**

**Hearing Identifier:** JShea\_IA\_NonPublic  
**Email Number:** 1038

**Mail Envelope Properties** (deeb08f5-7f49-43aa-9410-89e42bd9621c)

**Subject:** RE: NRC Submittal Regarding Anchor Darling Double Disc Gate Valves  
**Sent Date:** 12/21/2017 4:46:17 AM  
**Received Date:** 12/21/2017 4:46:18 AM  
**From:** Thacker, Bobby Henry

**Created By:** bhthacker@tva.gov

**Recipients:**  
"Thompson, Russell R" <rrthompson@tva.gov>  
Tracking Status: None

**Post Office:** tva.gov

<b>Files</b>	<b>Size</b>	<b>Date &amp; Time</b>
MESSAGE	4500	12/21/2017 4:46:18 AM
image001.jpg	5163	

**Options**  
**Priority:** Normal  
**Return Notification:** No  
**Reply Requested:** No  
**Sensitivity:** Normal  
**Expiration Date:**



**MSM - UMR**