## **FEDERAL NOTIFICATION LETTER**

Monday, January 25, 2021

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

LDS-Jadwin 1321 Jadwin Ave. Richland, WA 99352

To Specific Licensee:

SRB Technologies, Inc. 2580 Landmark Drive Winston-Salem, NC 27103 (336)-659-2610

Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)

2/09/21

**Description of Device(s) Transferred:** 

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name:	Melissa Rosenlund
Signature:	Melieu Md
Phone Number:	360-546-5155

PHYT BULLDOON TYPET

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

Sales Order #: 2194481

Case #: 00030566

Box 1 of 3

RGA#: 998743

RGA # Expiration Date: 3/22/2021

UCN: 3G51384H-2I56868J

Fedex Tracking #: 691191700098599

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
150LITE	20/10	A282172	08.02	11.5
3. ISOLITE	7040	A 282168	08-02	11.5
3. ISOLITE	2040	A282167	08-02	11.5
4. ISOLITE	2040	A272276	07-02	11.5
5. ISOLITE CORP	Z040	A 26443	06-02	11.5
6. SAB TECHNOLOGIES	B100	664119	D/A	DIA
5. SEB TECHNOLOGIES	B 160	665379	D/A	NA
8. 190LITE CORP	9 LX - 60	11-45415	05-11	20
9. I SOLITE CORP	91x-60	11-45271	05-11	20
10. 15 OLITE CORP	9LX -60	11-45421	05-11	Zø

Describe any damaged units:	
Please email pictures of damaged signs to	
pak.ts@veolia.com	
	-
=	

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION				
Generator Signature:	Milwallad	Title: Service Coordinator		
Přiňt Name:	Melissa Rosenlund	Date: 11/05/2020		

	VEOLIA INFORMATIO	N – DO NOT WRITE IN THIS BOX
Date Received:	11-6-20	Checked in by: Angie Kum

VEOLIA

Sales Order #: 2194481 Case #: 00030566 Box 2 of 3

The state of the earth of

RGA#: 998743

RGA # Expiration Date: 3/22/2021

UCN: 4K51381L-2M56876N

Fedex Tracking #: 691191700098612

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL GIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

* DESCRIPTION/AVERUS	· heaventedom:	SERVINOVIRES	A LEFTERANDE LEFTERAND	Ceunispans Dubracklis Sidenlye
2 IGOLITE COUP	5LX-60	11-45414	5/11	100 - 4mo
2. ISOLITE CORP	SLX-60	11- 45:416	05 - 11	20
3. ISOLITE CORP	SLX - 60	11-45 274	05-11	70
. Shield	SLX-60	11-45270	01/2012	20
S Shield	SLX-60	11-452-72	01/2012	20
& Shield	SLX-60	11-45273	01/2012	20
7. Sheild	SLX-60	11-45275	01/2012	20
g Shield	SLX-60	11-45276	01/2012	20
g Shield	SLX-60	11-45277	01/2012	20
O. Shield	SLX-60	11-45417	01/2012	20

Describe any damaged units:	,
Plaase email pictures of damaged signs to	
pak.ts@vealia.com	
	. 1

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

		HILIDE
Generator Signature:	Miliah 1	Title: Service Coordinator
Print Name:	Melissa Rosenlund	Date: 11/05/2020

Marin School and State Control of the State		
4.16 - 12.6	AOIRAWRIORINIAIROBAY.	I–IDO NOTAWRITE INITHIS BOX
Date Received:	11-1-20	Checked in by: angie Kung

**VEOLIA USE ONLY** 

Sales Order #: 2194481

Case #: 00030566

Box 3 of 3

VEOLIA USE ONLY

RGA#: 998743

RGA # Expiration Date: 3/22/2021

UCN: 9051383P-7Q56884R

Fedex Tracking #: 691191700098605

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN, ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN, DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
5 Shield	SLX-60	11-45418	01/2012	.37
2 Shield	SLX-60	11-45419	01/2012	.37
3. Shield	SLX-60	11-45420	01/2012	. 37
SRB Tech	в100	664095	01/2001	20
5. SRB Tech	в100	664096	01/2001	20
SRB Tech	B100	664097.	01/2001	20
SRB Tech	B100	664118	01/2001	20
		-		

Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com		
	· · · ·	

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

	GENERATOR CER	RTIFICATION	<u> </u>
Generator Signature:	Mul d	Title: Service Coordinator	
Print/Name:	Melissa Rosenlund /	Date: 12/17/2020	

	VEOLIA INFORMATION -	DO NOT WRITE IN THIS BOX	
Date Received:	12-21-20	Checked in by:	

VEOLIA