

A written notification to your radioactive materials regulatory agency for the transfer of exit signs is required. The notification must be either be made to the US Nuclear Regulatory Commission (NRC) and/or an Agreement State authorized to implement the NRC regulations. You can determine if you are in a NRC or Agreement State by going to <http://www.crcpd.org/Map/> and clicking on your state. Below the address listed, it will specify if that state is an Agreement State. If this not specified, then the state does not regulate transfer of exit signs and is considered a NRC State.

Use this general license transfer notification if you are in a NRC State. If you are in an agreement state, just insert your state radiation agency address obtained from the website referenced above. The transfer notification is required to be filed no later than 30 days after the transfer to Curie. You may use the date the shipment is received by Curie as the transfer date.

Use the completed and approved Curie exit sign inventory as the backup and attachment to the transfer notification. If you are a specific licensee, refer to your license for transfer requirements. Contact Curie Customer Service at 505.888.9392 with any questions.

Note that if you are transferring general licensed luminous safety devices for use in aircraft (10 CFR 31.7) that a notification is not required.

(TO BE WRITTEN ON YOUR LETTERHEAD & FORWARDED TO THE ADDRESS LISTED BELOW or YOUR AGREEMENT STATE AGENCY)



2801 CRESTVIEW DR. • NEWBERG, OR 97132

(CURRENT DATE) 5-6-2021

Director, Office of Nuclear Safeguards
Attn: Document Control Desk/GLTS
US Nuclear Regulatory Commission
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) (8), we hereby notify you that on (DATE) we transferred the self-luminous exit signs listed on the attached spreadsheet to Curie Environmental Services, 4020 Vassar Drive NE, Suite D, Albuquerque NM 87107, State of New Mexico Specific License RS500-03.

4-14-2021

As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact (FULL NAME AND PHONE NUMBER)

Darren William Dorman 503-819-2067

Sincerely,

(NAME)

Darren Dorman
Dan W Dorman

Encl.

NMSS10
NMSS



General Licensed Exit Signs

TRITIUM (H-3) EXIT SIGN INVENTORY

Generator: A-DEC Customer: Act Enviro
 Curie RMA#: A210401 Unique ID #:
 Receipt Date: 4/14/2021 UPS/FedEx #
 Curie Cont. # Box Number: 2 of 2

Item #	Manufacturer Name	Mfg. Date	Model #	Serial #	Reference Activity (Ci)	Decayed Activity (Ci) as of April 19, 2021	Comments
1	ISOLITE	2/1/99	2000	A921122	9.500	2.72	
2	ISOLITE	3/1/99	2000	A932981	9.500	2.74	
3	ISOLITE	2/1/99	2000	A921121	9.500	2.72	
4	ISOLITE	2/1/99	2000	A921120	9.500	2.72	
5	ISOLITE	2/1/99	2000	A921124	9.500	2.72	
6	ISOLITE	3/1/99	2000	A932980	9.500	2.74	
7	ISOLITE	2/1/99	2000	A921123	9.500	2.72	
8	ISOLITE	2/1/99	2000	A921125	9.500	2.72	
9	0					0.00	
10						0.00	
11						0.00	
12						0.00	
13						0.00	
14						0.00	
15						0.00	
16						0.00	
17						0.00	
18						0.00	
19						0.00	
20						0.00	
21						0.00	
22						0.00	
23						0.00	
24						0.00	
25						0.00	
26						0.00	
27						0.00	
28						0.00	
29						0.00	
30						0.00	
31						0.00	
Total Package Activity (must be <100 Ci per Curie return kit. Refer to instructions.)						21.81	

NOTES:

For standard architectural exit signs, a maximum of 10 sign faces per box are allowed. Only aircraft articles may be >10 per box.

The customer/generator certifies there are no damaged or compromised exit signs in this container and all Curie packaging procedures have been followed. Additional surcharges will be assessed if undeclared damaged or compromised exit signs are present in the container upon receipt by Curie.