

National Aeronautics and
Space Administration

John H. Glenn Research Center
Lewis Field
Cleveland, OH 44135-3191



July 23, 2021

Reply to Attn of: QSH

Document Control Desk/ GLTS
Director, Office of Nuclear Materials Safety and Safeguards
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Subject: Notification of Generally Licensed Device Transfer

Ref: License #34-00507-16, Docket #030-05626

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on July 6, 2021, the NASA Research Center (GRC) transferred 50 self-luminous exit signs listed on the enclosure to Isolite Corporation, SRB Technologies Inc., 320 Boundary Road, Suite 140, Pembroke, ON, CANADA K8A6W5, holding Import License #IL-AI-5194.1/2020. As available, the listing includes the manufacturer, model number and serial number for each device.

If you should have any questions, please contact Mr. Christopher J. Blasio, Radiation Safety Officer, at (216) 433-6520.

**CHRISTOPHER
BLASIO**

Digitally signed by CHRISTOPHER
BLASIO
Date: 2021.07.23 10:32:01 -04'00'

A handwritten signature in black ink that reads "CJB" followed by a long horizontal line.

Christopher J. Blasio, CHP, CIH
Radiation Safety Officer

Enclosure:
Isolite Return Spreadsheet for RMA 15544 – 2 pages

bcc: (w/o encl.)
QSH/C. J. Blasio
QS/Official File

NM5510
NM55

Enclosure

Serial Number Spreadsheet 1

Company Name	NASA Glenn Research Center	Contact Name	Rod Case
Address 1	21000 Brookpark Rd	Contact Phone	216-433-6245
Address 2	MS 6-4	Contact Fax	N/A
City/State	Cleveland Ohio	Contact Email	roderick.c.case@nasa.gov
Zip Code	44135	Today's Date	7/1/2021

**Please completely fill out the above fields*

Line	Manufacturer Name	Manufacturer Date	Model Number	Serial Number	Original Activity (Ci)
1	SRB	6/1992	2000	157696	20
2	SRB	6/1992	2000	157704	20
3	SRB	6/1992	2000	157698	20
4	SRB	6/1992	2000	157699	20
5	SRB	6/1992	2000	157700	20
6	SRB	6/1992	2000	157701	20
7	SRB	6/1992	2000	157702	20
8	SRB	6/1992	2000	157706	20
9	SRB	6/1992	2000	157705	20
10	SRB	6/1992	2000	157697	20
11	SRB	6/1992	2040	157716	20
12	SRB	6/1992	2000	157715	20
13	SRB	6/1992	2000	157709	20
14	SRB	6/1992	Missing	157710	20
15	SRB	6/1992	Missing	157718	20
16	SRB	6/1992	Missing	157717	20
17	SRB	6/1992	Missing	157695	20
18	SRB	6/1992	Missing	157712	20
19	SRB	6/1992	Missing	157711	20
20	SRB	6/1992	Missing	157714	20
21	SRB	6/1992	Missing	157713	20
22	SRB	6/1992	Missing	157707	20
23	SRB	6/1992	Missing	157708	20
24	Isolite	6/1992	2000	A54831	11.5
25	Isolite	6/1992	2000	A62656	11.5

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs, not "ONE" Please make note of this. The company & address information, should belong to the End-User (location the signs have physically been removed from).*

Enclosure

Serial Number Spreadsheet 2

Line	Manufacturer Name	Manufacturer Date	Model Number	Serial Number	Original Activity (Ci)
26	Isolite	4/2006	2000	A63591	11.5
27	Isolite	1/2007	2000	A711677	11.5
28	Isolite	4/2006	2000	A62651	11.5
29	Isolite	4/2006	2000	A62647	11.5
30	Isolite	1/2009	2000	A55125	11.5
31	Isolite	5/2008	2000	A852548	11.5
32	Isolite	10/2008	2000	A852549	11.5
33	Isolite	10/2008	2000	A852550	11.5
34	Isolite	7/2006	2000	A64325	11.5
35	Isolite	4/2006	2000	A62646	11.5
36	Isolite	1/2007	2000	A711671	11.5
37	Isolite	8/1996	2000	A681766	11.5
38	Isolite	10/2003	2000	A239361	11.5
39	Isolite	11/2000	2000	AON654	11.5
40	Isolite	12/2000	2000	AOD1375	11.5
41	Isolite	3/1996	2000	A63593	11.5
42	Isolite	1/1997	2000	A711684	11.5
43	SLC	4/2000	missing	24676	11.5
44	SLC	4/2000	missing	804055	11.5
45	SRB	7/2000	missing	188097	20
46	SRB	7/2000	missing	illegible	20
47	Isolite	5/1997	2000	A751283	11.5
48	Isolite	2/1996	2000	A62652	11.5
49	Isolite	5/1995	2000	A55128	11.5
50	Isolite	7/1994	2000	A471026	11.5

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs, not "ONE" Please make note of this. The company & address information, should belong to the End-User (location the signs have physically been removed from).*