NRC FORM 591M PAR	٢1		U	U.S. NUCLEAR REGULATORY COMMISSION			
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
1. LICENSEE/LOCATIC TEAM Industrial Se 200 Hermann Drive TJS at P-66 Refiner FO at 2596 Enterpri REPORT NO.: 2021-0	rvices, Inc. , Alvin, TX y, Billings, MT se Avenue, Bays 4,5	,6, Billings, MT	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd. Arlington, Texas 76011-4511				
3. DOCKET NUMBER 4. LICENSE NUMBER 5. DATE(S) (NSPECTION		
030-35252		42-32219-01		June 2 – September 2, 2021			
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: 1. Based on the inspection findings, no violations were identified.							
X 2. Previous violation(s) closed.							
 3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied. 							
Non-Cited Violation(s) was/were discussed involving the following requirement(s):							
 A. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions) 10 CFR 19.13(b)(1) requires, in part, that the licensee shall provide an annual report to each individual monitored under 10 CFR 1502 of the dose received in that monitoring year if the individual's occupational dose exceeds 100 millirem. Contrary to the above, as of the date of the onsite inspection on August 24, 2021, the licensee failed to provide an annual report to each individual report to each individual monitored under 10 CFR 1502 of the dose received in that monitoring year [calendar year 2020] if the individual's occupational dose exceeded 100 millirem. Specifically, the Site Lead radiographer working for the licensee at the P-66 refinery in Billings, Montana was reading the radiation exposure information but not sharing that information with 14 of the radiographers and assistant radiographers. Subsequently, the annual report of each individual's exposure for calendar year 2020 was not provide as 							
required by 10 CFR 19.13(b)(1). The licensee corrected this violation on August 25, 2021, by performing an investigation to determine if this practice was isolated to this work location only. When it was determined to indeed be an isolated event, the licensee provided the annual report of the dose received to each individual for calendar year 2020. Further, the licensee provided refresher training on the use of the monitoring badges and the expectation that each individual review their dose information at least monthly.							
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.							
TITLE	PRINTE	DNAME	SIGNATURE		DATE		
LICENSEE'S REPRESENTATIVE	DAVID P.7	1230	Den Dela	To	9/2/2021		
NRC INSPECTOR		Thompson	James L. Thompson Thompson	igned by James L. n 1.09.02 15:27:03 -05'00'	9/2/2021		
BRANCH CHIEF	Lizette Roldar	-Otero, PhD	Lizette Roldan-O		signed by Lizette Roldan-Otero 21.09.04 13:45:59 -05'00'		
NRC FORM 591M PART 1 (07-2012)							

From:	Thompson, James
То:	Tebo, David
Subject:	NRC Inspection Report 2021-001
Date:	Thursday, September 2, 2021 3:31:00 PM
Attachments:	591M for TEAM Industrial Services.pdf
Importance:	High

Mr. Tebo,

Please find enclosed the report for the NRC inspection performed, starting remotely on June 2, 2021, and ending with today's exit meeting on September 2, 2021. You should sign this report if you agree with the findings and send it back to me. Call if you have any questions.

Thank you for you and your staff's cooperation in performing this inspection, -James