

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION I 2100 RENAISSANCE BOULEVARD, SUITE 100 KING OF PRUSSIA, PENNSYLVANIA 19406-2713

September 23, 2021

Mr. David P. Rhoades Senior Vice President Exelon Generation Company, LLC President and Chief Nuclear Officer Exelon Nuclear 4300 Winfield Road Warrenville, IL 60555

SUBJECT: CALVERT CLIFFS NUCLEAR POWER PLANT, UNITS 1 AND 2 -

EMERGENCY PREPAREDNESS BIENNIAL EXERCISE INSPECTION REPORT

05000317/2021501 AND 05000318/2021501

Dear Mr. Rhoades:

On September 16, 2021, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at Calvert Cliffs Nuclear Power Plant, Units 1 and 2 and discussed the results of this inspection with Mr. Thomas Haaf, Site Vice President and other members of your staff. The results of this inspection are documented in the enclosed report.

No findings or violations of more than minor significance were identified during this inspection.

This letter, its enclosure, and your response (if any) will be made available for public inspection and copying at http://www.nrc.gov/reading-rm/adams.html and at the NRC Public Document Room in accordance with Title 10 of the *Code of Federal Regulations* 2.390, "Public Inspections, Exemptions, Requests for Withholding."

Sincerely,

Fred L. Bower, III, Chief Security, Emergency Preparedness, and Incident Response Branch Division of Radiological Safety and Security

Docket Nos. 05000317 and 05000318 License Nos. DPR-53 and DPR-69

Enclosure: As stated

cc w/ encl: Distribution via LISTSERV®

SUBJECT: CALVERT CLIFFS NUCLEAR POWER PLANT, UNITS 1 AND 2 -

EMERGENCY PREPAREDNESS BIENNIAL EXERCISE INSPECTION REPORT 05000317/2021501 AND 05000318/2021501 DATED SEPTEMBER 23, 2021

DISTRIBUTION:

MYoung, DORS
LCline, DORS
RRolph, DORS, SRI
SObadina, DORS, RI
CFragman, DORS, AA
RWilliams, RI OEDO
RidsNrrPMCalvertCliffs Resource
RidsNrrDorlLpl1 Resource
ROPReports Resource

DOCUMENT NAME: https://usnrc.sharepoint.com/teams/RI.DRS.PSB.EP/Shared Documents/EP Inspection Reports/Calvert Cliffs/Calvert Cliffs EP EX IR 2021-501.docx

ADAMS ACCESSION NUMBER: ML21266A306

X SUNSI Review		X Non-Sensitive☐ Sensitive		X Publicly AvailableNon-Publicly Available		
OFFICE	RI/DRSS	RI/DORS	RI/DRSS			
NAME	JRady	MYoung	FBower			
DATE	9/23/21	9/23/21	9/23/21			

OFFICIAL RECORD COPY

U.S. NUCLEAR REGULATORY COMMISSION Inspection Report

Docket Numbers: 05000317 and 05000318

License Numbers: DPR-53 and DPR-69

Report Numbers: 05000317/2021501 and 05000318/2021501

Enterprise Identifier: I-2021-501-0000

Licensee: Exelon Generation Company, LLC

Facility: Calvert Cliffs Nuclear Power Plant, Units 1 and 2

Location: Lusby, MD

Inspection Dates: September 13, 2021 to September 16, 2021

Inspectors: J. Rady, Senior Emergency Preparedness Inspector

J. Schoppy, Senior Reactor Inspector

S. Seeley, Health Physicist

Approved By: Fred L. Bower, III, Chief

Security, Emergency Preparedness and Incident Response Branch

Division of Radiological Safety and Security

SUMMARY

The U.S. Nuclear Regulatory Commission (NRC) continued monitoring the licensee's performance by conducting an emergency preparedness biennial exercise inspection at Calvert Cliffs Nuclear Power Plant, Units 1 and 2, in accordance with the Reactor Oversight Process. The Reactor Oversight Process is the NRC's program for overseeing the safe operation of commercial nuclear power reactors. Refer to https://www.nrc.gov/reactors/operating/oversight.html for more information.

List of Findings and Violations

No findings or violations of more than minor significance were identified.

Additional Tracking Items

None.

INSPECTION SCOPES

Inspections were conducted using the appropriate portions of the inspection procedures (IPs) in effect at the beginning of the inspection unless otherwise noted. Currently approved IPs with their attached revision histories are located on the public website at http://www.nrc.gov/readingrm/doc-collections/insp-manual/inspection-procedure/index.html. Samples were declared complete when the IP requirements most appropriate to the inspection activity were met consistent with Inspection Manual Chapter (IMC) 2515, "Light-Water Reactor Inspection Program - Operations Phase." The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel to assess licensee performance and compliance with Commission rules and regulations, license conditions, site procedures, and standards. Starting on March 20, 2020, in response to the National Emergency declared by the President of the United States on the public health risks of the coronavirus (COVID-19), inspectors were directed to begin telework. In addition, regional baseline inspections were evaluated to determine if all or a portion of the objectives and requirements stated in the IP could be performed remotely. If the inspections could be performed remotely, they were conducted per the applicable IP. In some cases, portions of an IP were completed remotely and on site. The inspections documented below met the objectives and requirements for completion of the IP.

REACTOR SAFETY

71114.01 - Exercise Evaluation

Inspection Review (IP Section 02.01-02.11) (1 Sample)

(1) The inspectors evaluated the biennial emergency plan exercise. The exercise scenario simulated an anticipated transient without scram (ATWS), loss of coolant accident, fuel clad damage, and loss of containment integrity on September 14, 2021. Exelon onsite emergency responders also participated in a simulated large-scale fire exercise scenario which damaged the spent fuel pool in order to demonstrate the extensive damage mitigation guidelines described in Title 10 of the *Code of Federal Regulations* (10 CFR) 50.155(b)(2) as required by 10 CFR Part 50, Appendix E.IV.F.2.j on September 15, 2021.

71114.04 - Emergency Action Level and Emergency Plan Changes

Inspection Review (IP Section 02.01-02.03) (1 Sample)

- (1) The inspectors evaluated the following submitted Emergency Action Level and Emergency Plan changes:
 - EP-AA-112-200-F-04, Security Coordinator Checklist, Revision J
 - EP-AA-112-200-F-29, Electrical Engineer Checklist, Revision E
 - EP-AA-112-300-F-01, Operations Support Center Director Checklist, Revision S
 - EP-AA-112-400-F-04, Emergency Operations Facility Logistics Manager Checklist, Revision R

This evaluation does not constitute NRC approval.

71114.08 - Exercise Evaluation Scenario Review

Inspection Review (IP Section 02.01 - 02.04) (1 Sample)

(1) The inspectors reviewed and evaluated the proposed scenario for the biennial emergency plan exercise on August 9, 2021.

OTHER ACTIVITIES - BASELINE

71151 - Performance Indicator Verification

The inspectors verified licensee performance indicators submittals listed below:

EP01: Drill/Exercise Performance (DEP) Sample (IP Section 02.12) (1 Sample)

(1) July 1, 2020 – June 30, 2021

<u>EP02: Emergency Response Organization (ERO) Drill Participation (IP Section 02.13)</u> (1 Sample)

(1) July 1, 2020 – June 30, 2021

EP03: Alert And Notification System (ANS) Reliability Sample (IP Section 02.14) (1 Sample)

(1) July 1, 2020 – June 30, 2021

INSPECTION RESULTS

No findings were identified.

EXIT MEETINGS AND DEBRIEFS

The inspectors verified no proprietary information was retained or documented in this report.

• On September 16, 2021, the inspectors presented the emergency preparedness biennial exercise inspection results to Mr. Thomas Haaf, Site Vice President and other members of the licensee staff.

DOCUMENTS REVIEWED

Inspection	Туре	Designation	Description or Title	Revision or
Procedure				Date
71114.01	Miscellaneous		Calvert Cliffs Nuclear Power Plant 2021 Emergency	July 15,
			Preparedness Biennial Exercise Scenario Package	2021
71151	Corrective Action	IR 04446500		
	Documents			
	Resulting from			
	Inspection			