



NOTES
 1 (31-B) REMOVABLE COVER FOR HYDRAZINE FILL
 2 ALL PIPING RG E CLASS EXCEPT INSIDE DOTTED LINE
 3 (30-C) 1" HANDLE ANGLE VALVE NO. 5505
 4 (30-F) SECOND GATE VALVE LOCATED NEAR TANK
 5 (37-C) ITEM 15 DC 663037-2
 6 (36-C) ITEM 14 DC 663037-2

PIPING CONFORMS WITH ASME BOILER CODE SECT. I 1968
 8 (30-D) ELECTRICALLY INSULATING FLANGES
 9 (35-B) INSTRUMENT VALVE 45VI
 10 2" 900° RF FLANGES 33-B
 11 TRAP USED TO INDICATE FAILURE OF PCV-18 DIAPHRAGM

| | | |
|-------------------|----------------|----------|
| UNIT - 2 | | |
| P.G. & E. CO. | DRAWING NUMBER | REVISION |
| SHEET 5 OF SHEETS | 108006 | 10 |
| | MICROFILM | 10 |

RM INDEXED REV -10-

SCAN 10