FEDERAL NOTIFICATION LETTER

Thursday, March 04, 2021

Director of FSME Attn: GLTS U.S. Nuclear Regulatory Commission Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Moog Inc. 20263 Western Ave. Torrance, CA 90501

To Specific Licensee:

SRB Technologies, Inc. 2580 Landmark Drive Winston-Salem, NC 27103 (336)-659-2610 Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)

04/13/2021

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name:	Juan Canlos Ruiz
Signature:	Jeem Calm May
Phone Number:	(310) 618 - 7639

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

VEOLIA USE ONL	Y	ľ	VEOLIA USE ONLY
Sales Order #: Case #: 000379 Box 1 of 1			RGA #: 998904 RGA # Expiration Date: 6/2/2021 UCN: 5W51382X-8Y57816Z Fedex Tracking #: 691191700135645

سرار-

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing, if you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR	MODEL NÛMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1. Herit Lynning , che	ft=924=0-15- 4	15681	08-13-	
2. Perm - Ex MFD	T -4001	AZBKS19	09/2001	2 S C;
	ann an Ar Charles ann an Ar An Ar An Ar An Ar An Ar An Ar An			
		-		
				-
			Vir Classific Cl	· · · · · · · · · · · · · · · · · · ·
999 - 200 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201 - 201		Second		· · · · · · · · · · · · · · · · · · ·

Describe any damaged units:	
Uesciba sou demand with	
I acadine allà daugado nullo	
and a second sec	
Please amaliation and	
Cicuse empli dictures of damagand class to	
Please email pictures of damaged signs to	,
and the second	
pak.ts@veolia.com	
a condición de la contra de la	
· · · ·	1 7
4	
	r
/I // // // // // // // // // // // // /	1
/I // // // // // // // // // // // // /	1
1	
4 7	1
(<u> </u>	
	1
The second se	
the second second second second second second sector second sector second second second second second second se	

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs. S SINGLASS

	GENERATOR CE	ERTIFICATION
Generator Signature:	Jean Carly Rig	
Print Name:	Juan Canlor Ryit	Date: 01/28/202)

and the second state of th	VEOLIA INFORMATION	- ĐỘ NOT WRITE IN THIS BOX	
1	and the second state of th	EO NOT WRITE IN THIS BOX	
Date Received:	2-20-21	Checked in by: amarice, Klippe	-
		LATER AUM	
hard and the second sec			
Customer Service Toli Fre	e: 1-888.560.0775 54		ľ

8-669-9725 Monday-Friday – 8am to 5pm CST Tritium Exit Sign Disposal Box | REV 06/2016

VEOLIA