NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION				
	ETY INS	PECTION REPORT	AND COM	IPLIANCE IN	SPECTION	
1. LICENSEE/LOCATION INSPECTED: Del Valle Group Road 865, Km. 0.3 Campanilla Ward Toa Baia. PR REPORT NUMBER(S) 2021001			NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713			
3. DOCKET NUMBER(S) 4. LICENSE NUMBE		4. LICENSE NUMBER(, , ,			
030-38392		52-31423-01			December 8, 2021	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X						
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken,						
date when full compliance will be achie						
Title LICENSEE'S REPRESENTATIVE		Printed Name			Signature	Date
NRC INSPECTOR						
BRANCH CHIEF						
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WBL Documents\WBL Inspection Records\52-31423-01.2021001.591M-Part1.doc						
SUNSI Review Completed By:	/RA/	R. Ragland			x Public	Non-Sensitive