



December 29, 2021
L-2021-250
10 CFR 50.4
10 CFR 50 Appendix E

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555-0001

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Radiological Emergency Plan Revision 70

The Turkey Point Plant Radiological Emergency Plan, Revision 70 was implemented on December 21, 2021.

A summary of the changes to the revised document is attached. FPL has determined that the changes described do not result in a decrease in the effectiveness of the Emergency Plan.

Sincerely,

A handwritten signature in blue ink, appearing to be 'R. Hess', is written over a horizontal blue line.

Robert J. Hess
Licensing Manager
Turkey Point Nuclear Plant

Attachment

cc: Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

Summary of Changes to Turkey Point Plant Radiological Emergency Plan, Revision 70

EC 291559 EC 291563 AR 02410974

Revision 70 Implementation Date: 12/21/2021

The Turkey Point Plant Radiological Emergency Plan was revised to implement Engineering Changes 291559/291563 that replaces the plant containment air particulate and gas monitors, R-3/4-11 and R-3/4-12, with new Mirion detectors. Additional administrative changes were made based on the review of the Radiological Emergency Plan.