

NRC FORM 591M PART 1
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

American Engineering Testing, Inc.
1669 Samco Road
Rapid City, South Dakota

REPORT NO.: 2021-002

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

3. DOCKET NUMBER

030-18180

4. LICENSE NUMBER

22-20271-01

5. DATE OF INSPECTION

October 22, 2021

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.
2. Previous violations closed.
3. The violations, specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation was/were discussed involving the following requirement(s) and Corrective Action(s):
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Luis Nieves	<i>Jason Dykert for Luis Nieves</i>	December 3, 2021
BRANCH CHIEF	Lizette Roldan-Otero	Lizette Roldan-Otero	Digitally signed by Lizette Roldan-Otero Date: 2021.12.30 13:19:07 -06'00'

From: [Michlig, Paul](#)
To: [Bischoff, Kyle](#)
Cc: [Lensegrav, Joel](#)
Subject: [External_Sender] RE: NRC Inspection of American Engineering Testing
Date: Friday, December 3, 2021 12:23:54 PM
Attachments: [image001.png](#)
[image002.png](#)
[image003.png](#)
[image004.png](#)
[image005.png](#)

Received thank you.

Paul A. Michlig
Construction Services Manager
Direct: 715-359-3534 | **Cell:** 715-571-7309



American Engineering Testing, Inc.
4203 Schofield Avenue, Suite 1
Schofield, WI 54455

www.teamAET.com

Follow us on Social Media:



Please read our email disclaimer at this [link](#) on our website.

From: Bischoff, Kyle <Kyle.Bischoff@nrc.gov>
Sent: Friday, December 3, 2021 11:09 AM
To: Michlig, Paul <pmichlig@teamAET.com>
Cc: Lensegrav, Joel <jlensegrav@teamAET.com>
Subject: NRC Inspection of American Engineering Testing

[Warning - External Source] Please be careful about responding to or opening any attachments or links in this message, as it did not originate from within the company.

Paul,

As discussed the NRC conducted an inspection of AET on October 22, 2021, no violations were identified. An inspection report is attached to this email, please retain a copy for your records.

Please reply to the email acknowledging your receipt.

Thank you,

Kyle Bischoff
Health Physicist
U.S. Nuclear Regulatory Commission
Region IV
Division of Nuclear Materials Safety
Materials Inspection Branch
Office: 817-200-1259
Email: Kyle.Bischoff@nrc.gov