

**St. Lucie SLRA: Breakout Questions**  
 SLRA Section B.2.3.32, Masonry Walls  
 TRP: 045

Note: Breakout Questions are provided to the applicant and will be incorporated into the publicly-available audit report.

<b>Technical Reviewer</b>	Zuhan Xi	12/09/2021
<b>Technical Branch Chief</b>	Joseph Colaccino	12/10/2021
<b>Breakout Session</b>	<i>Date/Time</i>	<i>To be filled in by PM</i>

Applicant Staff	NRC staff
<i>To be filled out by PM during breakout</i>	

Question Number	SLRA Section	SLRA Page	Background / Issue (As applicable/needed)	Discussion Question / Request	Outcome of Discussion
1	B.2.3.32	B-245	<p>GALL-SLR XI.S5 – Acceptance Criteria recommends that observed degradation is assessed against the evaluation basis to confirm that the degradation has not invalidated the original evaluation assumptions or impacted the capability to perform the intended functions.</p> <p>GALL-SLR XI.S5 also states, in part, that “[t]he U.S. Nuclear Regulatory Commission (NRC) Inspection and Enforcement Bulletin (IEB) 80-11, “Masonry Wall Design,” and NRC Information Notice (IN) 87-67, “Lessons Learned from Regional Inspections of Licensee Actions in Response to IE</p>	<p>Confirm whether the evaluation basis used for acceptance criteria for the Masonry Walls program is adequate and meets NUREG-2921 XI.S5.</p>	

		<p>Bulletin 80-11," constitute an acceptable basis for a masonry wall aging management program (AMP)."</p> <p>In the St. Lucie Units 1 and 2 Subsequent License Renewal Aging Management Program Basis Document – Masonry Walls (NEESL00008-REPT-072, Rev. 0), Section 4.6, Acceptance Criteria, states that masonry block walls are inspected using evaluation basis established in response to <u>IE Bulletin 80-11</u>. It appears that the evaluation basis of the acceptance criteria only come from the established response to NRC IEB 80-11, and no other evaluation basis is involved.</p>		
--	--	---	--	--