



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532-4352

March 21, 2022

Mr. Daniel Cunningham
Radiation Safety Officer
Central Missouri Professional Services, Inc.
2500 E. McCarty St.
Jefferson City, MO 65101

SUBJECT: NRC ROUTINE INSPECTION REPORT NO. 03038236/2021001(DNMS) AND
NOTICE OF VIOLATION – CENTRAL MISSOURI PROFESSIONAL SERVICES,
INC.

Dear Mr. Cunningham:

On December 15, 2021, an inspector from the U.S. Nuclear Regulatory Commission (NRC) conducted a routine inspection at your Jefferson City, MO locations, with continued in-office review through March 1, 2022. The purpose of the inspection was to review activities performed under your NRC license to ensure that activities were being performed in accordance with NRC requirements. The in-office review included a review of the new Radiation Safety Officer (RSO) qualifications. Mr. Luis Nieves of my staff conducted a final exit meeting by telephone with you on March 1, 2022, to discuss the inspection findings. This letter presents the results of the inspection.

During this inspection, the NRC staff examined activities conducted under your license related to public health and safety. Additionally, the staff examined your compliance with the Commission's rules and regulations as well as the conditions of your license. Within these areas, the inspection consisted of selected examination of procedures and representative records, observations of activities, and interviews with personnel.

Based on the results of this inspection, the NRC has determined that one Severity Level IV violation of NRC requirements occurred. The violation was evaluated in accordance with the NRC Enforcement Policy. The current Enforcement Policy is included on the NRC's website at <http://www.nrc.gov/about-nrc/regulatory/enforcement/enforce-pol.html>. The violation concerned the licensee's failure to have the individual named on the license serve as the RSO, as required by License Condition (LC) 12 of NRC License Number 24-32774-01. The violation is cited in the enclosed Notice of Violation (Notice). The NRC is citing the violation in the enclosed Notice because the inspector identified the violation. The former RSO departed in November 2021, and the new RSO was not approved by the NRC until January 20, 2022, when an amendment to the license was issued.

The inspector determined that the root cause of the violation was licensee oversight, specifically the licensee was not aware that the NRC had to review and approve, through the issuance of an amendment to the license, a new RSO. As corrective actions to restore compliance and to prevent recurrence, the licensee will revise its annual audit template to remind itself that it must submit a license amendment request to the NRC, and then NRC must approve the request, to change the RSO named on the license prior to the new RSO serving as the RSO.

The NRC has concluded that information regarding the reason for the violation, the corrective actions taken and planned to correct the violation and prevent recurrence, and the date when full compliance will be achieved is already adequately addressed on the docket in this letter. Therefore, you are not required to respond to this letter unless the description herein does not accurately reflect your corrective actions or your position. In that case, or if you choose to provide additional information, you should follow the instructions specified in the enclosed Notice.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and any response you provide will be made available electronically for public inspection in the NRC's Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC's website at <http://www.nrc.gov/reading-rm/adams.html>. To the extent possible, any response should not include any personal privacy, proprietary, or safeguards information so that it can be made publicly available without redaction.

Please feel free to contact Mr. Nieves of my staff if you have any questions regarding this inspection. Mr. Nieves can be reached at 630-829-9571.

Sincerely,



Signed by Kunowski, Michael
on 03/21/22

Michael Kunowski, Chief
Materials Inspection Branch
Division of Nuclear Materials Safety

Docket No. 030-38236
License No. 24-32774-01

Enclosure: Notice of Violation

cc w/encl: State of Missouri

Letter to D. Cunningham from M. Kunowski dated, March 21, 2022.

SUBJECT: NRC INSPECTION REPORT NO. 03038236/2021001(DNMS) – CENTRAL
MISSOURI PROFESSIONAL SERVICES, INC.

DISTRIBUTION w/encl:

Jack Giessner
Mohammed Shuaibi
Kathryn M. Brock
Joseph Nick
Shelbie Lewman
Kenneth Lambert
MIB Inspectors

ADAMS Accession Number: ML22076A218

| | | | | | | | | |
|--------|-----------|--|-----------|--|--|--|--|--|
| OFFICE | RIII-DNMS | | RIII-DNMS | | | | | |
| NAME | LNieves | | MKunowski | | | | | |
| DATE | 03/18/22 | | 03/21/22 | | | | | |

OFFICIAL RECORD COPY

NOTICE OF VIOLATION

Central Missouri Professional Services, Inc.
Jefferson City, MO

License No. 24-32774-01
Docket No. 030-38236

During a U.S. Nuclear Regulatory Commission (NRC) inspection conducted on December 15, 2021, with continued in-office review through March 1, 2022, one violation of NRC requirements was identified. In accordance with the NRC Enforcement Policy, the violation is listed below:

License Condition 12 of Amendment No. 3 of NRC License 24-32774-01 named an individual as the Radiation Safety Officer (RSO) for the license.

Contrary to the above, from November 2021 through January 20, 2022, the licensee failed to have the specific individual named in Condition 12 be the RSO for the license.

This is a Severity Level IV violation (Enforcement Policy Section 6.3).

The NRC has concluded that information regarding the reason for the violation, the corrective actions taken and planned to correct the violation and prevent recurrence, and the date when full compliance was achieved, is already adequately addressed on the docket in (this letter, the subject inspection report, etc.). However, you are required to submit a written statement or explanation pursuant to 10 CFR 2.201 if the description therein does not accurately reflect your corrective actions or your position. In that case, or if you choose to respond, clearly mark your response as a "Reply to a Notice of Violation, IR 03038236/2021001(DNMS) " and send it to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001 with a copy to the Regional Administrator, Region III, within 30 days of the date of the letter transmitting this Notice.

If you choose to respond, your response will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>. Therefore, to the extent possible, the response should not include any personal privacy, proprietary, or safeguards information so that it can be made available to the Public without redaction.

If you contest this enforcement action, you should also provide a copy of your response, with the basis for your denial, to the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001.

In accordance with 10 CFR 19.11, you may be required to post this Notice within two working days of receipt.

Dated this 21st day of March 2022.

Enclosure