Tuesday, February 15, 2022

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

LDS Church 4400 Presidential Dr. NE Ste A Albuquerque, NM 87109

To Specific Licensee:

SRB Technologies, Inc. 2580 Landmark Drive Winston-Salem, NC 27103 (336)-659-2610

Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)

2-28-2022

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name: LAND A Corragins

Signature: CARROLL

Phone Number: 6201796-1033

Sales Order #: 2234401

Case #: 00065594

Box 1 of 4

VEOLIA USE ONLY

RGA #: 999428 / Expires: 3/21/22 UCN: 8Y51386Z-1A58409B FedEx Tracking #: 776052798834

Box 1 of 4 / Ref #: 549

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	Safet Light Corp	U-20	629884	5/98	20Y
2.	Safety Light Corp	U-20	629885	5/98	20Y
з.	Safety Light Corp	U-20	615459	3/97	20Y
4.	Safety Light Corp	U-20	629882	5/98	20Y
5.	Safety Light Corp	U-20	608947	9/96	20Y
6.	Safety Light Corp	:U-20	629883	5/98	20Y
7.	Perm EX Mfg	T4001	86394	10/92	20Y
8.	Safety Light	SLX-60	267393	5/04	20Y
9.	Safety Light Corp	U-20	73408	3/88	20Y
10.	Safety Light Corp	U-20	73465	3/88	20Y

Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com	

	GENERATOR CER	TIFICATION		
Generator Signature:	Stacey Reynoso	Title:	Project manager	
Print Name:	Stacey Reynoso	Date:	10/19/2021	

	VEOLÍA INFORMATIO	N – DO NÓT WRITE IN THIS BOX
Date Received:	12-18-21	Checked In by: angie Klung



Sales Order #: 2234401

Case #: 00065594

Box 2 of 4

VEOLIA USE ONLY

RGA #: 999428 / Expires: 3/21/22 UCN: 6C51385D-8E58415F FedEx Tracking #: 776052809916 Box 2 of 4 / Ref #: 550

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	Safety Light Corp	U-20	73467	3/88	20Y
2.	Safety Light Corp	U-20	73464	3/88	20Y
3.	Safety Light Corp	U-20	7.3466	3/88	20Y
4.	Safety Light Corp	U-20	100270	2/89	20Y
5.	Safety Light	SLX-60	410650	5/07	20Y
6,	Safety Light	SLX-60	410651	5/07	20Y
7.	Safety Light	SLX-60	410648	5/07	20Y
8.	Safety Light	SLX-60	410655	5/07	20Y
9.	Safety Light	SLX-60	410653	5/07	20Y
10.	Safety Light	SLX-60	410654	5/07	20Y

Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com	

VIII	GENERATOR C	ERTIFICATION		,	2
Generator Signature: Print Name:	Stacey Reynoso Stacey Reynoso	Title:	Project manager 10/19/2021		

	VEOLIA INFORMA	TION - DO NOT WRITE IN THIS BOX
Date Received:	12-18-21	Checked in by: Angir Kun

Sales Order #: 2234401

Case #: 00065594

Box 3 of 4

VEOLIA USE ONLY

RGA #: 999428 / Expires: 3/21/22 UCN: 3G51384H-2l58428J FedEx Tracking #: 776052819424

Box 3 of 4 / Ref #: 551

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT of LIFE RATING
1.	Safety Light	SLX-60	410649	5/07	20Y
2.	Safety Light	SLX-60	440652	5/07	20Y
3.	Isolite	200	A921800	5/07	20Y
4.	Isolite	200	A921818	5/07	20Y
5.	Safety Light	SLX-60	410656	9/07	20Y
6.	Safety Light	SLX-60	430679	9/07	20Y
7.	Safety Light	SLX-60	430675	9/07	20Y
8.	Safety Light	SLX-60	430680	9/07	20Y
9.	Safety Light	SLX-60	430658	9/07	20Y
10.	Safety Light	SLX-60	430674	9/07	20Y

	GENERATOR CE	ERTIFICATION		e . · ·	
Generator Signature:	Stacey Reynoso	Title:	Project manager		
Print Name:	Stacey Reynoso	Date:	10/19/2021	-	

Customer Service | Toll Free: 1-888-669-9725 Monday-Friday — 8am to 5pm CST

Tritium Exit Sign Disposal Box | REV 06/2016

Describe any damaged units:

pak.ts@veolla.com

Date Received:

Please amail pictures of damaged signs to



Checked in by: angio Klim

Sales Order #: 2234401 Case #: 00065594

Box 4 of 4

VEOLIA USE ONLY

RGA #: 999428 / Expires: 3/21/22 UCN: 4K51381L-2M58436N FedEx Tracking #: 776052828863

Box 4 of 4 / Ref #: 552

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible.

DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS
FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	Safety Light	SLX-60	430659	9/07	20Y
2.	Safety Light	SLX-60	431808	9/07	20Y
3.	Safety Light	SLX-60	430676	9/07	20Y
4.	Safety Light	SLX-60	430657	9/07	20Y
5.	Safety Light	SLX-60	430673	9/07	20Y
		:			
! !					

Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com	

,,	GENERATOR CEI	RTIFICATION		,	
Generator Signature: Print Name:	Stacey Reynoso Stacey Reynoso	Title:	Project manager 10/19/2021	·	

	VEOLIA INFORMA	TION - DO NOT WRITE IN THIS BOX
Date Received:	12-18-21	Checked in by: Angu Kum

Sunday, February 06, 2022

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Church of Latter Day Saints 14415 369th Ave. NE Startup, WA 98294

To Specific Licensee:

SRB Technologies, Inc. 2580 Landmark Drive Winston-Salem, NC 27103 (336)-659-2610

Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was

shipped to Specific Licensee)

W vor

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name: UNA A Romans

Signature: 636/196-1033

Sales Order #: 2229094

Case #: 00061667

Box 1 of 2

JEOLIA USE ONLY

KGA #: 999446 / Expires: 4/18/22 UCN: 7Q51384R-5S59039T FedEx Tracking #: 775966357540

Box 1 of 2 / Ref #: 612

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NÜMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	Safety Light Corp	SLX60	036277	01/99	11.5
2.	Safety Light Corp	SLX60	036275	01/99	11.5
3.	Safety Light Corp	SLX60	036278	01/99	11.5
4.	Safety Light Corp	SLX60	036272	01/99	11.5
5.	Safety Light Corp	SLX60	036269	01/99	11.5
6.	Safety Light corp	SLX60	036271	01/99	11.5
7.	Safety Light Corp	SLX60	036270	01/99	11.5
8.	Safety Light Corp	SLX60	036279	01/99	11.5
9.	Safety Light Corp	SLX60	036252	01/99	11.5
10.	Safety Light Corp	SLX60	046121	11/87	11.5

	And the process of the control of th	The state of the s
Describe any damaged units:		
Please email pictures of damaged signs to		
pak.ts@veolia.com		

I hereby certify that all Information submitted on this form contains true and accurate descriptions of the exit signs.

GENERÁTOR AGREEMENT				
Generator Signature:	Michaelann Agoranos	Title:	VP Refresh Construction	
Print Name:	Michaelann Agoranos	Date:	12/07/21	
		-460.	12/0//21	

	VEOLIA INFORMA	TION - DO NOT WRITE IN THIS BOX
Date Received:	19-33-31	Checked in by: angu Kung

VEOLIA

Sales Order #: 2229094

Case #: 00061667

Box 2 of 2

VEOLIA	USE	ONLY
--------	-----	------

KGA #: 999440 / Expires: 4/18/22 UCN: 1U51387V-5W59042X FedEx Tracking #: 775966362583

Box 2 of 2 / Ref #: 613

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING	
1. Safety Light Corp	SLX60	cannot read	cannot read	20	
2. Safety Light Corp	SLX60	cannot read	cannot read	20	
3. Safety Light Corp	SLX60	cannot read	cannot read	20	
		:			
Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com					
i hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.					
,	GENERATOR AGREEMENT				
Generator Signature: Mic	haslann Agoran	Title: VP Refr	esh Construction		
Print Name: Mi	chaelann Agoranos	Date: 12/07	//21		

		VEOLIA INFORMATION -	DO NOT WRITE IN THIS BOX	
Date Received: 12-22-21 Checked in by: angu Kung	Date Received:	13-32-21	Checked in by: amgin Kum	

Customer Service | Toll Free: 1-888-669-9725 Monday-Friday – Bam to 5pm CST

Tritium Exit Sign Disposal Box | REV 06/2016



Sunday, February 06, 2022

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Church of Latter Day Saints 1301 N. Navajo Dr. Page, AZ 86040

To Specific Licensee:

SRB Technologies, Inc. 2580 Landmark Drive Winston-Salem, NC 27103 (336)-659-2610

Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)

2-25- 2002

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name: Lynn A Morbins

Signature: Lynn A Morbins

Phone Number: 630(796 1033

Sales Order #: 2229061

Case #: 00061602

Box 1 of 3

Describe any damaged units:

pak.ts@veolia.com

Please email pictures of damaged signs to

RGA #: 999447 / Expires: 4/25/22 UCN: 9051383P-7Q59094R FedEx Tracking #: 775966448034

Box 1 of 3 / Ref #: 618

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NÜMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1. Brandhurst Corp	B100	68584	02/88	20
2. Brandhurst Corp	B100	62504	11/87	20
3. SRB Technologies Inc	B100	62512	11/87	20
4. SRB Technologies Inc	B100	62507	11/87	20
5. SRB Technologies Inc	B100	62498	11/87	20
6. Brandhurst Corp	B100	65200	12/87	20
7. SRB Technologies Inc	B100	65255	12/87	20
8. SRB Technologies Inc	B100	62501	04/87	20
9. SRB Technologies Inc	B100	62499	11/87	20
10. SRB Technologies Inc	B100	62505	11/87	20

thereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.				
	GENERATOR AGR	EEMENT		
Generator Signature:	Michaelann Agoranos	Title: VP Refresh Construction		
Print Name:	Michaelann Agoranos	Date: 12/07/21		
	VEOLIA INFORMATION – DO N	OT WRITE IN THIS BOX		
Date Received:	12-22-21 Che	cked in by: angie Kung		

Customer Service | Toll Free: 1-888-669-9725 Monday-Friday — 8am to 5pm CST Tritlum Exit Sign Disposal Box | REV 06/2016

₩VEOLIA

Sales Order #: 2229061

Case #: 00061602

Box 2 of 3

RGA #: 999447 / Expires: 4/25/22 UCN: 5S51389T-1U59107V FedEx Tracking #: 775966450126

Box 2 of 3 / Ref #: 619

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN, DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

1	DESCRIPTION/MFR.		SERIAL NUMBER	DATÉ OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	SRB Technologies Inc	B100	62506	11/87	20
2.	SRB Technologies Inc	B100	62503	11/87	20
3.	SRB Technologies Inc	B100	62502	11/87	20
4.	SRB Technologies Inc	B100	62510	11/87	20
5.	SRB Technologies Inc	B100	62511	11/87	:20
6.	SRB Technologies Inc	B100	62509	11/87	20
7	Brandhurst Corp -	B100	68583	2/88	20
8	Brandhurst Corp	B100	65254	12/87	20
	The state of the s	 		4,4	ang ngangangan na ng pang dada digitan singgapan da mada ng
Table 1990					

Describe any damaged units; Please email pictures of damaged signs to	SRB Technologies sign 62500 is damaged inside "Exit" tubing broken
pak.ts@veolia.com	

t hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

	GENERATOR AGR		T is ,	inter disease and for the second second second second	ngalakankankan garan dipena sadilikada Ma	
Generator Signature:	Michaelann Agoranos	Title:	VP Refresh	Construction		
Print Name:	Michaelann Agoranos	Date:	12/07/21			
				mentaniana di pananana		

Kanara sana ana ana ana ana ana ana ana ana a	VEOLIA INFORMATION	– DO NOT WRITE IN THIS BO	OXI
Date Received:	12-22-21	Checked in by:	1.7
,	And the state of t	/ /	

ritium Exit Sign Disposal Box | REV 06/2016



Sales Order #: 2229061

Case #: 00061602

Box3 of 3

VEOLIA USE ONLY

RGA #: 999447 / Expires: 4/25/22 UCN: 5W51382X-8Y59116Z FedEx Tracking #: 775966452379

Box 3 of 3 / Ref #: 620

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible.

OO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS
FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER " UNIT or LIFE RATING		
1. SRB Technologies Inc	B100	62500	11/87	20		
	gy (an denge ar mengera) a de des des des des des de la company de la company de la		• •			
				-		
Simon por a disk accessor accessor and a six a			And the state of t			
		and the state of t	tentido de la compansa de la compans			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		-			
		N 100 (100 (100 (100 (100 (100 (100 (100				
1						
		-				
Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com	SRB Technologies sign 62500 is damaged inside "Exit" tubing broken					

	GENERÁTOR ÁGRE	EMENT	T .	
Generator Signature:	Michaelann Agoranos	Title:	VP Refresh Construction	
Print Name:	Michaelann Agoranos	Date:	12/07/21	
		ال المستحدة		

	VEOLIA INFORMATION -	DO NOT WRITE IN THIS BOX	(
Date Received:	12-22-21	Checked in by:	Kung	
		U		



Sunday, February 06, 2022

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Church of Latter Day Saints 7115 224th Ave. NE Redmond, WA 98053

To Specific Licensee:

SRB Technologies, Inc. 2580 Landmark Drive Winston-Salem, NC 27103 (336)-659-2610

Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)

2-1-2022

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name: Why A Cossins

Signature: Osol 796-(033)

Sales Order #: 2229070 Case #: 00061613

Box I of 4

RGA #: 999435 / Expires: 4/22/22 UCN: 8Y51386Z-1A59059B FedEx Tracking #: 775966399250 Box 1 of 4 / Ref #: 614

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS

FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even If there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERÍÁL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1. Splety Signs	B100	5715 92	03/94	20
2. Safety Signs	B100	57 1580	03/94	20
3. Gafety Signs	B100	571581	03/94	20
4 Safety Signs	B100	571585	03/94	20
5. Safety Signs	B100	571584	03/94	20
6. Isolite Safety Light Corp.	2040	A011213	1100	11.5
7. Safety light corp	5LX-60	046607	12/00	11.5
8. Safety Sins	8100	665668	02/01	20
9. Safety Signs	B100	665673	02/01	20
10. Safety Signs	B100	665672	02/01	20

Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com		

	GFNERATOR CERT	IFICATION	,	
Generator Signature:	_66	Title:	Site	Super
Print Name:	Guillermo Gomez	Date:	12-07	- sì

VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX					
Date Received:	12-16-21	Checked in by: angle Kung			

Sales Order #: 2229070

Case #: 00061613

Box 2 of 4

VEOLIA LISE ONLY

RGA #: 999435 / Expires: 4/22/22 UCN: 6C51385D-8E59065F FedEx Tracking #: 775966403256

Box 2 of 4 / Ref #: 615

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT of LIFE RATING
1. Safety Signs	B100	665676	02/01	20
2. Safety Signs	13100	665669	02/01	20
3. Safety Signs	B100	6657 46	02/01	20
4 Safety Signs	B100	665745	02/01	20
5. Safety Signs	Bloo	66 5674	02/01	20
6 Safety Signs	B100	665743	02/01	20
7. Safety Signs	B100	665744	02/01	20
8. Safety Signs	B100	571587	03194	20
9. Safety Signs	Bloo	571595	03/94	20
10. Safety Signs	3100	571588	03/94	20

Please email pictures of do pak.ts@veolia.com	maged signs to	
I hereby certify that all info	mation submitted on this form contains true a	and accurate descriptions of the exit signs.
	GENERATOR CE	CERTIFICATION
Generator Signature:	6-8	Title: Site Super
Print Name:	Guillermo Gomez	Date: 12-02-21
Print Name:	Gullermo Gomez	Date: 12-02-21

Date Received: 12-16-21 Checked in by: Grage Kung

Describe any damaged units:

Sales Order #: 2229070

Case #: 00061613

Box 3 of 4

RGA #: 999435 / Expires: 4/22/22 UCN: 3G51384H-2I59078J FedEx Tracking #: 775966405660

Box 3 of 4 / Ref #: 616

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	Safety Light Corp	SLX60	045119	12/00	11.5
2.	Safety Light Corp	SLX60	046122	12/00	11.5
3.	Safety Light Corp	SLX60	046109	12/00	11.5
4.	Safety Light Corp	SLX60	046110	12/00	11.5
5.	Safety Light Corp	SLX60	046104	12/00	11.5
6.	Safety Light corp	SLX60	046123	12/00	11.5
7.	Safety Light Corp	SLX60	046117	12/00	11.5
8.	Safety Light Corp	SLX60	046120	12/00	11.5
9,	Safety Light Corp	SLX60	046108	11/87	11.5
10.	Safety Light Corp	SLX60	046121	11/87	11.5

Describe any damaged units:	-	
Please email pictures of damaged signs to		
pak.ts@veolia.com		

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

	GFNERATOR CERT	FICATION			
Generator Signature:	66	Title:	Site	Super	
Print Name:	Guillermo Gomez	Date:	12-07	-21	

VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX

Date Received:

Checked in by:



VECTIA LISE ONLY

Sales Order #: 2229070

Case #: 00061613 BoX: 4 of 4

	USE	

RGA #: 999435 / Expires: 4/22/22 UCN: 4K51381L-2M59086N FedEx Tracking #: 775966404848

Box 4 of 4 / Ref #: 617

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PÉR UNIT or LIFE RATING
1. SAFETY STAN	60 B100	571594	03/94	20
2 Safety Sign	8100	571593	03/94	20
3. Safety Sign	B100	6656 70	02/01	20
? 				
<u> </u>				

Describe any damaged units Please email pictures of dam pak.ts@vealla.com						
I hereby certify that all Inform	nation submitted on this form contains true and accurate descriptions of the exit signs.					
	GENFRATOR CERTIFICATION					
Generator Signature:	Title: Site Super					
Print Name:	Guillermo Gomez Date: 12-02-21					
	VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX					
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
Date Received:	12-110-21 Checked in by: (Imale Klima					

Customer Service | Toli Free: 1-888-669-9725 Monday-Friday — 8am to 5pm CST

Tritium Exit Sign Disposal Box | REV 06/2016



Thursday, December 23, 2021

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

LDS Church 1065 Main St. Panaca, NV 89042

To Specific Licensee:

SRB Technologies, Inc. 2580 Landmark Drive Winston-Salem, NC 27103 (336)-659-2610

Radioactive Materials License #034-0534-2

Date of Transfer:
(Enter Date Disposal Box was shipped to Specific Licensee)

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name: LUNG A ROBSINS

Signature: 630 196-1033

Sales Order #: 2234758

Case #: 00065981

Box 1 of 2

RGA #: 999425 / Expires: 3/21/22 UCN: 8Y51386Z-1A58539B

FedEx Tracking #: 775595940168

Box 1 of 2 / Ref #: 562

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DEŠCRIPŤÍON/MFR.	MÖDEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT of LIFE RATING
1-SRB Technologies	V20 -	005057	3/01	20C
2 SRB Technologies	020	C165 C058	3/01	20C
3. SRB Technologies	UZO	UU51047	3/01	20C
4 SRB Technologies	020	0665050	3/01	ZOC.
5. SRB Technologies	020	U1051048	3/01	20C
5 SRB Technologies	U20	665662	3/01	20C
7. SPB Technologies	U20	Ce 65 600	a/01	20C
8 SRB Technologies	U20_	lele5 11103	3/01	200
9. SPB Technologies	U20	(ele5 ce52	2/01	zec
10. SRB Technologies	UZO	Celas Celay	2/01	20C

Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com	
puk.is@veona.com	

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

	GENERATOR GERTIFI	CATION
Generator Signature:	Michaelann Agoranoa	Title: VP Refresh Construction
Print Name:	Michaelann Agoranos	Date: 12/3/21

İ		VEOLIA INFORMATII	ON - DO NOT WRITE IN THIS BOX
8	Date Received:	12-18-21	Checked In by: amaia, 124m
l			

Customer Service | Toll Free: 1-888-669-9725 Monday-Friday -- 8am to 5pm CST

Tritium Exit Sign Disposal Box | REV 05/2016



Sales Order #: 2234758 Case #: 00065981

Box 2 of 2

RGA #: 999425 / Expires: 3/21/22

UCN: 6C51385D-8E58545F FedEx Tracking #: 775595945332

Box 2 of 2 / Ref #: 563

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible.

DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS
FOR REPERTIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MER:	MODELNUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT OF LIFE RATING
1SPB Technologies	020	Celes Celelo	2/01	20
25RB Technologies	020	CO105 (05 Co	2/01	20
3. SRB Technologies	U20	Ce45 655	2101	20
4 BRB Technologies	UZO	665653	2/01	Z0
5. SRB Technologics	UZÐ	1265665	n/n	20
6 SRB Technologies	UZO	1010510101	n/ n	20

Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolla.com	

TANK TANK	Generator Signature: Print Name:	GENERATOR GERTI Michaelann Ageranea Michaelann Ageranes	Title: VP Refresh Construction Date: 12/3/21
The second second	Date Received:		of Write IN THIS BOX

