

NRC FORM 591M
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Metals Testing Services, Inc
4942 West Shalecrest Road
Coeur d'Alene, ID 83814
REPORT NO.: 2022-001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd.
Arlington, Texas 76011-4511

3. DOCKET NUMBER

030-38893

4. LICENSE NUMBER

37-29406-02

5. DATE(S) OF INSPECTION

March 3, 2022

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.
2. Previous violation(s) closed.
3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s):
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Allyce Bolger	Digitally signed by Allyce B. Bolger Date: 2022.04.07 13:46:13 -05'00'	
BRANCH CHIEF	Lizette Roldán-Otero, PhD	Lizette Roldan-Otero Digitally signed by Lizette Roldan-Otero Date: 2022.04.30 07:29:20 -05'00'	

From: [Bolger, Allyce](#)
To: michaelp@mtsinspection.com
Subject: NRC Inspection Report
Date: Thursday, April 7, 2022 1:53:00 PM
Attachments: [NRC 591M - Metals Testing Services.pdf](#)

Michael,

As we just discussed on the phone, no violations were identified during our inspection of your facility in Coeur d'Alene, ID on March 2, 2022. The inspection report is attached for your records. Additional, the NRC recently revised NUREG-2155 "Implementation Guidance for 10 CFR Part 37" which you can find here <https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr2155/index.html>. Thank you for your support during the inspection and let me know if you have any questions.

Regards,

Allyce Bolger

(Pronouns: [She/Her](#))

Health Physicist

Division of Radiological Safety and Security

NRC Region IV

817-200-1197