






From: [Mel Fravel](#)
To: [VonEhr, Jason](#)
Subject: [External_Sender] Alarm system
Date: Tuesday, May 17, 2022 12:48:24 PM
Attachments: 

Good afternoon Jason,



The second part of this email is concerning the deletion of Selenium 75 (Se75) from our materials license. The intention in the beginning, which was during the last Ir192 shortage, was to have a “go-to” in case Ir192 was unobtainable. For this entire time since that change request, that has not been an issue, we have not had to alter our techniques using that isotope and have remained consistent with Ir192 and Co60. With our current methods, I feel Se75 will not be needed in the future, we should be able to perform our work with the types of equipment and materials we now possess. I ask for the license t be amended to reflect this change.

Thank you

*Mel Fravel
Director of Operations
Radiation Safety Officer*

****PLEASE MAKE NOTE OF MY NEW EMAIL ADDRESS**

mel@ctsinc.org



****HDGPR ** DIGITAL X-RAY ** CCTV HD PIPE INSPECTION SERVICES**

*Concrete Imaging Inc.
10005 Good Luck Road
Glenn Dale, MD 20769
Contact # (240) 723.3789
Field Station # (304) 725. 5688
E-Mail: mel@ctsinc.org*

WEBSITE: www.concreteimaginginc.com

*****NOW WITH FREE DIGITAL X-RAY VIEWING SOFTWARE DOWNLOAD!!**

This email message is for the sole use of the intended recipients and may contain confidential and privileged information. Any unauthorized review, use, copying, disclosure or distribution of contained information is prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message. Any views expressed in this message are those of the individual sender, except where the sender specifically states them to be the views of Concrete Imaging, Inc.