



Materials Inspection Report

1. Licensee/Location Inspected: Bowers & Associates 713 North High Street P.O. Box 52 Kirksville, MO 63501 Location Inspected: Seminole Generating Station Putnam County, Florida Report Number(s)	2. NRC/Regional Office Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------

3. Docket Number(s) 030-18219	4. License Number(s) 24-20301-01	5. Date(s) of Inspection 12/10/2021 to 5/19/2021
-----------------------------------------	--------------------------------------------	------------------------------------------------------------

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
 - 2. Previous violation(s) closed.
 - 3. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements, and were assessed at Severity Level IV, in accordance with the NRC Enforcement Policy.
- A. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy were satisfied.
 (Non-cited violation(s) was/were discussed involving the following requirement(s))

B. The following violation(s) is/are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Contrary to condition 13.A of NRC Materials License 24-20301-01, from January 18, 2021, to April 25, 2022, the licensee failed to perform leak tests on their Troxler Model 1351 nuclear gauges (serial number 214, 226), exceeding the 6 months interval stipulated in the certificate of registration.

The cause of the violation was lack of oversight. As corrective actions, the licensee performed a leak test on April 25, 2022, which showed no detectable contamination; to prevent re-occurrence, the licensee will use a

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE AND DATE
LICENSEE'S REPRESENTATIVE	Craig Bowers	6-9-2022
NRC INSPECTOR	Luis Nieves Folch	Luis A. Nieves Folch <small>Digitally signed by Luis A. Nieves Folch Date: 2022.06.08 08:06:09 -05'00'</small>
BRANCH CHIEF	Michael Kunowski	Michael A. Kunowski <small>Digitally signed by Michael A. Kunowski Date: 2022.06.08 09:01:19 -05'00'</small>

Materials Inspection Report (Continued)

digital calendar to remind him of the leak test due date.