



*Davis-Besse Nuclear Power Station  
5501 N. State Route 2  
Oak Harbor, Ohio 43449*

**Terry J. Brown**  
*Site Vice President, Davis-Besse Nuclear*

**419-321-7676**

June 22, 2022  
L-22-153

Mr. John Giessner  
Regional Administrator, Region III  
United States Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

Subject: Davis-Besse Nuclear Power Station, Unit 1  
Docket Number 50-346, License Number NPF-3  
Readiness for NRC Supplemental Inspection Required for a White Finding

In Letter EA-21-155 dated March 1, 2022 (reference NRC Inspection Report No. 05000346/2021092), the NRC finalized the significance of a White finding for the Davis-Besse Nuclear Power Station (DBNPS) regarding an Emergency Diesel Generator (EDG) speed switch. As a result, the NRC assessed the DBNPS to continue to be in the Regulatory Response Column of the NRC's Action Matrix and identified that a supplemental NRC inspection will be performed for this issue. As requested by this Assessment Follow-Up Letter, this letter is to inform the NRC staff that the Energy Harbor Nuclear Corporation (Energy Harbor) is ready for the supplemental inspection at the DBNPS in accordance with NRC Inspection Procedure 95001.

There are no regulatory commitments contained in this letter. If there are any questions or if additional information is required, please contact Mr. Robert W. Oesterle, Manager, Site Regulatory Compliance and Emergency Response, at (419) 321-7462.

Sincerely,

A handwritten signature in black ink, appearing to read "Terry J. Brown", written over a horizontal line.

Terry J. Brown

GMW

cc: NRC Document Control Desk  
NRC Senior Resident Inspector  
NRR Project Manager  
Utility Radiological Safety Board