NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
LICENSEE/LOCATION INSPECTED: US Army Public Health Center 8252 Blackhawk Road Aberdeen Proving Ground, MD 21010-5403			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713			
REPORT NUMBER(S)	202	2001		-		
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECT	ION
07000867		SNM-860		,	June 6, 2022	
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X						
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achi	ice with th	e requirements of 10 CFR	2.201 (correc	ctive steps alread	y taken, corrective steps v	hich will be taken,
Title		Printed Name		;	Signature	Date
LICENSEE'S REPRESENTATIVE						
NRC INSPECTOR						
BRANCH CHIEF						
*NRC FORM 591M PART 1 (07-2012)	(RI Rev. (09/12/2013) G:\WBL	Documents\W	/BL Inspection Re	ecords\RSNM-860.202200	1.591M-Part1.doc
SUNSI Review Completed By:	/ RA /	R. Ragland			x Public x	Non-Sensitive