Tier / Group	Randomly Selected K/A	Reason for Rejection
1/1	026/K2	No K/As listed for K2 category: CE randomly selected a new category with a replacement K/A - AK3.03.
1/1	056/AK1.03	038/EK1.01 also includes the use of steam tables. CE randomly selected AK1.01.
1/2	068/AA1.09	Facility procedures for control room evacuation do not involve synchroscope key. CE randomly selected AA1.29
2/1	010/A3.01	PORV testing is done in mode 5. PRT monitoring is not required. CE randomly selected A3.02
2/2	028/K4	No K/As listed for K4 category: CE randomly selected K3.01.
2/2	033/K5	No K/As >2.5 for K5 category: CE randomly selected K4.01.
		+