ADAMS Accession# ML22221A133

| NRC FORM 591M 10 CFR 2.201 | | U. | U.S. NUCLEAR REGULATORY COMMISSION | | | |
|--|----------------|-------------------|--|--------------------------|---|--|
| SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION | | | | | | |
| LICENSEE/LOCATION INSPECTED: Northern Geotechnical Engineering, Inc./Terra Firma 11301 Olive Lane Anchorage, AK 99515 REPORT NO.: 2022-001 | | | NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd. Arlington, Texas 76011-4511 | | | |
| 3. DOCKET NUMBER | | 4. LICENSE NUMBER | | 5. DATE(S) OF INSPECTION | | |
| 030- | 030-34741 | | 50-29121-01 | | 6/7/2022, 6/29/2022 | |
| LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image: the inspection of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image: the inspection findings, no violations were identified. Image: the inspection of the activities conducted under your be inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied. Image: Non-Cited Violation(s) was/were discussed involving the following requirement(s): | | | | | | |
| 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. | | | | | | |
| Statement of Corrective Actions | | | | | | |
| I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. | | | | | | |
| TITLE | PRINTE | D NAME | SIGNATURE | | DATE | |
| LICENSEE'S REPRESENTATIVE | Justin Andryj | owicz - RSO | | | | |
| NRC INSPECTOR | Leonardo | Wardrobe | Leonardo F. Ward | | lly signed by Leonardo F. Wardrobe 2022.06.29 11:22:54 -05'00' | |
| BRANCH CHIEF | Lizette Roldar | n-Otero, PhD | Lizette Roldan-C | | lly signed by Lizette Roldan-Otero 2022.07.30 04:13:58 -05'00' | |
| | | | | | | |

Mr. Andryjowicz,

The NRC conducted an inspection of the Northern Geotechnical Engineering, Inc./Terra Firma on 6/7/2022. As we discussed on 6/29/2022, the inspection did not identify any violations. The enclosed report presents the results of this inspection, please review the attached report and maintain a copy for your records.

Please reply to the email acknowledging your receipt.

Thank you,

Leo Wardrobe

Health Physicist Nuclear Regulatory Commission, Region IV Division of Radiological Safety and Security, Material Inspection Branch 1600 East Lamar Blvd. Arlington, TX 76011 Office: (817) 200-1429

leonardo.wardrobe@nrc.gov

http://www.nrc.gov/