FEDERAL NOTIFICATION LETTER

Friday, August 26, 2022

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Georgia Pacific Crossett LLC 100 Mill Supply Rd. Crossett, AR 71635

To Specific Licensee:

SRB Technologies, Inc. 2580 Landmark Drive Winston-Salem, NC 27103 (336)-659-2610

Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)

9-27-2022

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name: Sarah Ross
Signature: Sarah Ross
Phone Number: (870) 415-4363

VEOLIA U

SALES ORDER: 2269479 CASE #: 000107144

BOX: 1 of 2 REF #: 655 RGA #: 999764 / Expires: 11/10/22

UCN: 3G51384H-2I59468J

FedEx Tracking #: 691191700080761

Box 1 of 2 / Ref #: 655

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice. Please complete the lines below that contain numbers.

MFR	ĮŊĬŎDELINUMBER	SERIAL INUMBER	DATE OF	ÆURIES!!ŘER (UNITYOF)LIFE: (RATING		
1 Evenlite	201	1555F	Replace before	re 10.5		
			Efficient Lif 20 years	દ.		
·		-				
	To the second se	man di Pari da antara pi pana and a diamenta ana si sana antara antara di Agrico da Agrico da Agrico da Agrico				
Describe any damaged units:	· Faded Radiation Label					
Please email pictures of damaged signs to pak.ts@veolia.com	· Faded Radiation Label · Metal housing came apart so front and back are not connected.					

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

	The second secon	GENERATOR CERTIF	ICATION		, ,
Generator Signature:	Sarahm	RODD-	Title:	Environmental Leader	
Print Name:	Sarah R	loss	Date:	7-28-2023)
Property of the second	WEOUAINE	ORMATION'- DOMOI	WRITE IN TH	iis Box	ر اس " د د د
Date Received:	8-8-22	Checked in k	oy: ane	sie Kuns	
C	- U.C 1 000 CC0 070C			5 1 5 2 2 2 1 5 1 5 1 5 1 5 1 5 1	2004

Customer Service | Toll Free: 1-888-669-9725 M-F – 8am to 5pm CST

VEOLIA

Tritium Exit Sign Disposal Box | REV 03/2021

VEOLIA!

SALES ORDER: 2269479 CASE #: 000107144

BOX: 2 of 2 REF#: 656

RGA #: 999764 / Expires: 11/10/22 UCN: 4K51381L-2M59476N

FedEx Tracking #: 691191700080754

ud Box 2 of 2 / Ref #: 656

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN, DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice. Please complete the lines below that contain numbers.

Wife	iModelínumber,	SERIAL NUMBER	DATE OF IMANUFACTURE	CURIES RER UNIT OF LIFE RATING	
1 EVENLITE	201	1550F	Replace before	10.0	
			Efficient Lif 20 years	2.	
			,		
			and the second s		
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
			·		
			<u>.</u>		
	C1.		<u> </u>	: 1	
Describe and damaged units: Please email pictures of damaged	Sign was impacted by fire in the area so the plastic is expanded and bubbled up through sign facing.				
signs to pak.ts@veolia.com bubbled up through sign facing.					

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

		GENER/	TOR GERTLIEICAT	ION	
Generator Signature:	SarahM	ROOS	س	Title:	Environmental Leader
Print Name:	Sarah	Ross		Date:	7-28-2022
	(VEOL!)	AIINFØRMATII	on -(Do)(voit \vi	RITEINI	ŢĦŢSĪB ©X
Date Received:	8-8-22		Checked in by:	an	raie Kurz
Customer Service To	ll Frag: 1-888-669-97	125		Tri	tium Evit Sign Disposal Roy REV 03/2021

M-F - 8am to 5pm CST





Dear Customer,

US,

The following is the proof-of-delivery for tracking number: 691191700080761

Box 1 of 2

Delivery Information:				
Status:	Delivered	Delivered To:		
Signed for by:	JCOBLER	Delivery Location:		
Service type:	FedEx Ground			
Special Handling:	Package Returns Program		Winston-Salem, NC,	
		Delivery date:	Sep 27, 2022 14:17	
Shipping Information:		***************************************		
Tracking number:	691191700080761	Ship Date:	Sep 23, 2022	
		Weight:	2.0 LB/0.91 KG	
Recipient:		Shipper:		

GREENVILLE, WI, US,

Signature image is available. In order to view image and detailed information, the shipper or payor account number of the shipment must be provided.



Dear Customer,

Recipient:

US,

The following is the proof-of-delivery for tracking number: 691191700080754

Box 2 of 2

Delivery Information: Delivered Status: Delivered To: **JCOBLER** Signed for by: Delivery Location: Service type: FedEx Ground Special Handling: Package Returns Program Winston-Salem, NC, Delivery date: Sep 27, 2022 14:17 Shipping Information: Tracking number: Ship Date: 691191700080754 Sep 23, 2022 Weight: 2.6 LB/1.18 KG

Shipper:

GREENVILLE, WI, US,

Signature image is available. In order to view image and detailed information, the shipper or payor account number of the shipment must be provided.