



MOUNTAINSTAR

St. Mark's Hospital

11/9/22

Director, Office of Nuclear Safeguards  
Attn: Document Control Desk/GLTS  
US Nuclear Regulatory Commission  
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) (8), we hereby notify you that on 11/9/2022 we transferred the self-luminous exit signs listed on the attached spreadsheet to Curie Environmental Services, 4020 Vassar Drive, NE, Suite D, Albuquerque NM 87107, State of New Mexico Specific License RS500-05.

As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please reach me with the contact information listed below.

Sincerely,

Alyssa Stacey, Plant Operations Coordinator

St Mark's Hospital  
Attn: Plant Operations  
Alyssa.Stacey@mountainstarhealth.com  
801.268.7890

Encl.

NM5510  
NM55

St. Mark's Hospital  
1200 East 3900 South  
Salt Lake City, UT 84124  
StMarksHospital.com



General Licensed Exit Signs

**TRITIUM (H-3) EXIT SIGN INVENTORY**

Generator: St Mark's Hospit Customer: St Mark's Hospital  
 Curie RMA#: Unique ID #:  
 Receipt Date: UPS/FedEx # 1ZV299A69096783355  
 Curie Cont. # Box Number: 1 of 1

Item #	Manufacturer Name	Mfg. Date	Model #	Serial #	Reference Activity (Ci)	Decayed Activity (Ci) as of November 9, 2022	Comments
1	Safety Sign	7/1/06	BR	C053717	20.000	7.97	
2	Safety Sign	7/1/06	BR	C053718	20.000	7.97	
3	Safety Sign	7/1/06	BR	C053721	20.000	7.97	
4						0.00	
5						0.00	
6						0.00	
7						0.00	
8						0.00	
9						0.00	
10						0.00	
11						0.00	
12						0.00	
13						0.00	
14						0.00	
15						0.00	
16						0.00	
17						0.00	
18						0.00	
19						0.00	
20						0.00	
21						0.00	
22						0.00	
23						0.00	
24						0.00	
25						0.00	
26						0.00	
27						0.00	
28						0.00	
29						0.00	
30						0.00	
31						0.00	
Total Package Activity (must be <100 Ci per Curie return kit. Refer to instructions.)						23.91	

**NOTES:**

*For standard architectural exit signs, a maximum of 10 sign faces per box are allowed. Only aircraft articles may be >10 per box.*

*The customer/generator certifies there are no damaged or compromised exit signs in this container and all Curie packaging procedures have been followed. Additional surcharges will be assessed if undeclared damaged or compromised exit signs are present in the container upon receipt by Curie.*