



Philip Hansett
Site Vice President
River Bend Station
225-381-4374

RBG-48258

October 5, 2023

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Subject: Notification of Readiness for Supplemental Inspection

River Bend Station – Unit 1
NRC Docket Nos. 50-458
Renewed Facility Operating License No. NPF-47

Reference: NRC letter to Entergy, "EA-23-055: River Bend Station – Final Significance Determination of a White Finding, Notice of Violation, and Follow-Up Assessment Letter; NRC Inspection Report 05000458/2023091," (ADAMS Accession No ML23187A639) dated July 20, 2023

By letter dated July 20, 2023, the Nuclear Regulatory Commission (NRC) determined the performance at River Bend Station (RBS) to be within the Regulatory Response Column of the NRC's Action Matrix.

In the referenced letter, the NRC announced its intent to conduct a supplemental inspection in accordance with Inspection Procedure 95001 following a notification of readiness from RBS. This letter serves as the notification of readiness for the NRC to perform the supplemental inspection at RBS.

This document contains no commitments. Should you have any questions, please contact Mr. Randy Crawford, Regulatory Assurance Manager, at 225-381-4177.

Respectfully,

A handwritten signature in black ink, appearing to read 'Phil Hansett', with a stylized flourish at the end.

Philip Hansett
PH/twf

cc: NRC Region IV Regional Administrator - Region IV
NRC Senior Resident Inspector - River Bend Station