

FEDERAL NOTIFICATION LETTER

Thursday, March 21, 2024

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Veolia ES Technical Solutions
5736 W Jefferson St
Phoenix, AZ 85043

To Specific Licensee:

SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
(336)-659-2610
Radioactive Materials License #034-0534-2


| | |
|--|---------|
| Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee) | 3/29/24 |
|--|---------|

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

| | |
|----------------------|---|
| Printed Name: | Hilli A. Bechard |
| Signature: |  |
| Phone Number: | 510-529-9211 |

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

VEOLIA USE ONLY

SALES ORDER: 2323952
CASE #: 000163710
BOX: 1 of 1
REF #: 784

RGA #: 220518 / Issued: 2/1/24
UCN: 6C51385D-8E60755F
FedEx Tracking #: 775150607360
Box 1 of 1 / Ref #: 784

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice. Please complete the lines below that contain numbers.

| MFR | MODEL NUMBER | SERIAL NUMBER | DATE OF MANUFACTURE | CURIES PER UNIT or LIFE RATING |
|--|--------------|---------------|---------------------|--------------------------------|
| 1 Safety light corp | NA | # 1 | 10/09 | 7.5 |
| 2 SRB Technologies | BX | C008689 | 8/04 | 20 |
| 3 SRB Technologies | B100 | 679448 | 2/03 | 20 |
| 4 SRB Technologies | B100 | 679552 | 2/03 | 20 |
| 5 SRB Technologies | B100 | 679526 | 2/03 | 20 |
| 6 SRB Technologies | B100 | 679555 | 2/03 | 20 |
| 7 SRB Technologies | B100 | 679453 | 2/03 | 20 |
| Describe any damaged units: Please email pictures of damaged signs to pak.ts@veolia.com | | | | |

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

| GENERATOR CERTIFICATION | | | |
|-------------------------|-----------------------|--------|---------------------------|
| Generator Signature: | <i>Holly A Becher</i> | Title: | <i>Operations Manager</i> |
| Print Name: | Holly A Becher | Date: | 12/12/23 |

| VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX | | | |
|---|---------|----------------|-------------------------|
| Date Received: | 3/21/24 | Checked in by: | <i>Carissa Clifford</i> |

