



December 2, 2024

Director, Office of Nuclear Safetyguards
Attn: Document Control Desk/GLTS
US Nuclear Regulatory Commission
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) (8), we hereby notify you that on November 26, 2024 we transferred the self-luminous exit signs listed on the attached spreadsheet to Cure Environmental Services, 4020 Vassar Drive NE, Suite D, Albuquerque, NM 87107, State of New Mexico Specific License RS500.

As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Tom Myers at 906-235-8397.

Sincerely,

Tom Myers
Lead Environmental Coordinator, MQT

NMSS10
NMSS



General Licensed Exit Signs

TRITIUM (H-3) EXIT SIGN INVENTORY

Generator: Envoy Air, Inc. Customer: Envoy Air, Inc.
 Curie RMA#: Unique ID #:
 Receipt Date: UPS/FedEx #:
 Curie Cont. # Box Number: 1 of 1

Item #	Manufacturer Name	Mfg. Date	Model #	Serial #	Reference Activity (Ci)	Decayed Activity (Ci) as of December 2, 2024	Comments
1	SRB Technologies (Canada) INC.	11/1/19		9045001 CP002103	0.090	0.07	
2	SRB Technologies (Canada) INC.	11/1/18		9045001 CP001777	0.090	0.06	
3	SRB Technologies (Canada) INC.	12/13/02	Supplier PN - 1951001	Customer PN - 601R38774-3	1.710	0.50	DAMAGED
4	SRB Technologies (Canada) INC.	10/1/09	Supplier PN - 1951001	Customer PN - 601R38774-3	2.520	1.07	
5						0.00	
6						0.00	
7						0.00	
8						0.00	
9						0.00	
10						0.00	
11						0.00	
12						0.00	
13						0.00	
14						0.00	
15						0.00	
16						0.00	
17						0.00	
18						0.00	
19						0.00	
20						0.00	
21						0.00	
22						0.00	
23						0.00	
24						0.00	
25						0.00	
26						0.00	
27						0.00	
28						0.00	
29						0.00	
30						0.00	
31						0.00	
Total Package Activity (must be <100 Ci per Curie return kit. Refer to instructions.)						1.70	

NOTES:
 For standard architectural exit signs, a maximum of 10 sign faces per box are allowed. Only aircraft articles may be >10 per box.
 The customer/generator certifies there are no damaged or compromised exit signs in this container and all Curie packaging procedures have been followed. Additional surcharges will be assessed if undeclared damaged or compromised exit signs are present in the container upon receipt by Curie.