

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>RAI ID #</b> | <b>RAI Question #<br/>by SRP Section</b> | <b>RAI Accession #</b>              | <b>Response Accession #</b>         |
|-----------------|------------------------------------------|-------------------------------------|-------------------------------------|
| RAI-10133-R1    | 3.13-1                                   | ML24091A002 (NP)                    | ML24313A066 (NP)<br>ML24313A067 (P) |
| RAI-10167-R1    | 3.4.1-3                                  | ML24091A002 (NP)                    | ML24222A594 (NP)<br>ML24222A595 (P) |
| RAI-10135-R1    | 3.6.2.7-2                                | ML24062A002 (NP)                    | ML24281A018 (NP)                    |
| RAI-10177-R1    | 3.6.2-2                                  | ML24103A247 (NP)                    | ML24281A020 (NP)<br>ML24281A021 (P) |
| RAI-10134-R1    | 3.6.3-1                                  | ML24062A001(NP)                     | ML24240A141 (NP)<br>ML24240A142 (P) |
| RAI-10111-R1    | 3.9.2-1                                  | ML23325A262 (NP)                    | ML24353A029 (NP)<br>ML24353A030 (P) |
| RAI-10150-R1    | 3.9.3-11                                 | ML24069A014 (NP)                    | ML24313A121 (NP)<br>ML24313A122 (P) |
| RAI-10131-R1    | 3.9.4-8                                  | ML24075A188 (NP)                    | ML24205A156 (NP)<br>ML24205A156 (P) |
| RAI-10131-R1    | 3.9.4-9                                  | ML24075A188 (NP)                    | ML24313A052 (NP)                    |
| RAI-10269-R1    | 4.3-28                                   | ML24278A018 (NP)                    | ML25058A345 (NP)<br>ML25058A347 (P) |
| RAI -10189-R1   | 5.4.1.6.1-1                              | ML24198A035 (NP)                    | ML24354A160 (NP)<br>ML24354A161 (P) |
| RAI-10359-R1    | 6.2.1-1                                  | ML24290A192 (NP)<br>ML24290A193 (P) | ML25009A006 (NP)<br>ML25009A007 (P) |
| RAI-10081-R1    | 6.3-1                                    | ML23304A393 (NP)                    | ML25016A300 (NP)<br>ML25016A302 (P) |
| RAI-10350-R1    | 6.3-10                                   | ML24264A000 (NP)                    | ML24325A593 (NP)<br>ML24325A594 (P) |
| RAI-10350-R1    | 6.3-11                                   | ML24264A000 (NP)                    | ML24325A593 (NP)<br>ML24325A594 (P) |
| RAI-10350-R1    | 6.3-7                                    | ML24264A000 (NP)                    | ML24325A593                         |
| RAI-10350-R1    | 6.3-9                                    | ML24264A000 (NP)                    | ML24325A593 (NP)<br>ML24325A594 (P) |
| RAI-10085-R1    | 9.1.2-1.1                                | ML23291A050 (NP)                    | ML23363A186 (NP)<br>ML23363A187 (P) |
| RAI-10085-R1    | 9.1.2-1.2                                | ML23291A050 (NP)                    | ML23363A186 (NP)<br>ML23363A187 (P) |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>RAI ID #</b> | <b>RAI Question #<br/>by SRP Section</b> | <b>RAI Accession #</b>              | <b>Response Accession #</b>         |
|-----------------|------------------------------------------|-------------------------------------|-------------------------------------|
| RAI-10105-R1    | 9.1.5-3                                  | ML23322A002 (NP)                    | ML24108A122 (NP)                    |
| RAI-10105-R1    | 9.1.5-6                                  | ML23322A002 (NP)                    | ML24108A122 (NP)                    |
| RAI-10089-R1    | 9.2.2-1                                  | ML23291A051 (NP)                    | ML24122C615 (NP)                    |
| RAI-10089-R1    | 9.2.3-1                                  | ML23291A051 (NP)                    | ML24122C615 (NP)                    |
| RAI-10157-R1    | 9.3.4-1                                  | ML24080A510 (NP)                    | ML24205A210 (NP)                    |
| RAI-10157-R1    | 9.3.4-2                                  | ML24080A510 (NP)                    | ML24205A210 (NP)                    |
| RAI-10157-R1    | 9.3.4-3                                  | ML24080A510 (NP)                    | ML24205A210 (NP)                    |
| RAI-10106-R1    | 9.5.3-1                                  | ML23317A414 (NP)                    | ML24122C612 (NP)                    |
| RAI-10106-R1    | 9.5.3-2                                  | ML23317A414 (NP)                    | ML24122C612 (NP)                    |
| RAI-10106-R1    | 9.5.3-3                                  | ML23317A414 (NP)                    | ML24122C612 (NP)                    |
| RAI-10102-R1    | 9A.5-1                                   | ML23292A360 (NP)                    | ML24078A163 (NP)<br>ML24078A164 (P) |
| RAI-10083-R1    | 10.1-1                                   | ML23284A162 (NP)                    | ML23361A099 (NP)<br>ML23361A100 (P) |
| RAI-10101-R1    | 12.3.4.2-1                               | ML23292A344 (NP)                    | ML24037A134 (NP)                    |
| RAI-10101-R1    | 12.3-1                                   | ML23292A344 (NP)                    | ML24037A134 (NP)                    |
| RAI-10097-R1    | 13.3-1                                   | ML23286A307 (NP)                    | ML23352A361 (NP)                    |
| RAI-10097-R1    | 13.3-2                                   | ML23286A307 (NP)                    | ML23352A361 (NP)                    |
| RAI-10097-R1    | 13.3-3                                   | ML23286A307 (NP)                    | ML23352A361 (NP)                    |
| RAI-10357-R1    | 15.0.5-1                                 | ML24291A085 (NP)<br>ML24291A109 (P) | ML24348A113 (NP)<br>ML24348A114 (P) |
| RAI-10357-R1    | 15.0.5-4                                 | ML24291A085 (NP)<br>ML24291A109 (P) | ML25051A088 (NP)<br>ML25051A089 (P) |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>RAI ID #</b> | <b>RAI Question #<br/>by SRP Section</b> | <b>RAI Accession #</b>              | <b>Response Accession #</b>          |
|-----------------|------------------------------------------|-------------------------------------|--------------------------------------|
| RAI-10357-R1    | 15.0.5-5                                 | ML24291A085 (NP)<br>ML24291A109 (P) | ML25021A217 (NP)<br>ML25021A218 (P)  |
| RAI-10357-R1    | 15.0.5-6                                 | ML24291A085 (NP)<br>ML24291A109 (P) | ML24353A218 (NP)<br>ML24353A219 (P)  |
| RAI-10357-R1    | 15.1.1-7                                 | ML24291A085 (NP)<br>ML24291A109 (P) | ML24353A333 (NP)<br>ML24353A334 (P)  |
| RAI-10357-R1    | 15.1.1-8                                 | ML24291A085 (NP)<br>ML24291A109 (P) | ML24348A130 (NP)<br>ML24348A132 (P)  |
| RAI-10142-R1    | 15.4.6-1                                 | ML24062A009 (NP)                    | ML25056A423 (NP)<br>ML25056A424 (P)  |
| RAI-10142-R1    | 15.4.6-2                                 | ML24062A009 (NP)                    | ML25016A152 (NP)<br>ML25016A153 (P)  |
| RAI-10199-R1    | 17.4-11                                  | ML24146A001 (NP)                    | ML24215A211 (NP)<br>ML24271A282 (NP) |
| RAI-10115-R1    | 19.1.5-1                                 | ML23340A047 (NP)                    | ML24047A252 (NP)<br>ML24047A253 (P)  |
| RAI-10190-R1    | 19.1-52                                  | ML24135A387 (NP)                    | ML24226A402 (NP)                     |
| RAI-10185-R1    | 19.2-1                                   | ML24131A116 (NP)<br>ML24131A122 (P) | ML24327A149 (NP)<br>ML24327A150 (P)  |
| RAI-10185-R2    | 19.2-2                                   | ML24131A116 (NP)<br>ML24131A122 (P) | ML24327A149 (NP)<br>ML24327A150 (P)  |
| RAI-10185-R3    | 19.2-3                                   | ML24131A116 (NP)<br>ML24131A122 (P) | ML24327A149 (NP)<br>ML24327A150 (P)  |
| RAI-10185-R4    | 19.2-4                                   | ML24131A116 (NP)<br>ML24131A122 (P) | ML24327A149 (NP)<br>ML24327A150 (P)  |
| RAI-10146-R1    | 19.3-4                                   | ML24096B785 (NP)                    | ML24145A106 (NP)                     |
| RAI-10107-R1    | 19.5-1                                   | ML23286A230 (NP)                    | ML24089A212 (NP)<br>ML24089A213 (P)  |
| RAI-10113-R1    | 19.5-13                                  | ML23335A200 (NP)                    | ML23352A125 (NP)                     |
| RAI-10107-R1    | 19.5-2                                   | ML23286A230 (NP)                    | ML24089A212 (NP)<br>ML24089A213 (P)  |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>RAI ID #</b> | <b>RAI Question #<br/>by SRP Section</b> | <b>RAI Accession #</b> | <b>Response Accession #</b>         |
|-----------------|------------------------------------------|------------------------|-------------------------------------|
| RAI-10107-R1    | 19.5-3                                   | ML23286A230 (NP)       | ML24089A212 (NP)<br>ML24089A213 (P) |
| RAI-10107-R1    | 19.5-4                                   | ML23286A230 (NP)       | ML24089A212 (NP)<br>ML24089A213 (P) |
| RAI-10107-R1    | 19.5-5                                   | ML23286A230 (NP)       | ML24089A212 (NP)<br>ML24089A213 (P) |
| RAI-10107-R1    | 19.5-6                                   | ML23286A230 (NP)       | ML24089A212 (NP)<br>ML24089A213 (P) |
| RAI-10107-R1    | 19.5-7                                   | ML23286A230 (NP)       | ML24089A212 (NP)<br>ML24089A213 (P) |

| <b>Chapter 1</b>                      |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-1.6-1                               | ML24346A132                     |

| <b>Chapter 2</b>                      |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-2.5.4-7                             | ML24346A135                     |
| A-2.5.4-8                             | ML24346A136                     |

| <b>Chapter 3</b>                      |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-3.11.12-1                           | ML24215A079                     | A-3.8.5-10                            | ML24215A042                     |
| A-3.11.2.3-1                          | ML24215A073                     | A-3.8.5-12                            | ML24215A044                     |
| A-3.11-2                              | ML24215A072                     | A-3.8.5-8                             | ML24346A142                     |
| A-3.11-3                              | ML24215A074                     | A-3.8.5-9                             | ML24215A040                     |
| A-3.11-4                              | ML24215A075                     | A-3.9.1-2                             | ML23304A404                     |
| A-3.11-5                              | ML24215A076                     | A-3.9.2-1                             | ML24215A045                     |
| A-3.11-6                              | ML24215A078                     | A-3.9.2-10                            | ML23304A413                     |
| A-3.12.5.9-2                          | ML24215A080                     | A-3.9.2-11                            | ML23304A415                     |
| A-3.12-3                              | ML23304A438                     | A-3.9.2-12                            | ML23304A421                     |
| A-3.12-4                              | ML23304A439                     | A-3.9.2-13                            | ML24215A054                     |
| A-3.12-6                              | ML23304A443                     | A-3.9.2-18                            | ML24215A055                     |
| A-3.12-9                              | ML23304A444                     | A-3.9.2-19                            | ML24215A057                     |
| A-3.3.1.1-1                           | ML24215A003                     | A-3.9.2-2                             | ML23304A405                     |
| A-3.3-1                               | ML24215A002                     | A-3.9.2-21                            | ML24215A060                     |
| A-3.3-2                               | ML24215A004                     | A-3.9.2-22                            | ML24215A062                     |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| A-3.3-3                               | ML24215A005                     | A-3.9.2-25                            | ML24215A064                     |
| A-3.3-4                               | ML24215A006                     | A-3.9.2-26                            | ML24346A147                     |
| A-3.3-7                               | ML24215A007                     | A-3.9.2-26-F                          | ML24346A149                     |
| A-3.4.1-1                             | ML24215A009                     | A-3.9.2-27                            | ML23348A285                     |
| A-3.4.1-2                             | ML24215A010                     | A-3.9.2-28                            | ML24346A151                     |
| A-3.4.1-7                             | ML24215A012                     | A-3.9.2-3                             | ML23304A407                     |
| A-3.4.2-10                            | ML24215A017                     | A-3.9.2-33                            | ML24215A066                     |
| A-3.4.2-2                             | ML23304A398                     | A-3.9.2-34                            | ML24346A157                     |
| A-3.4.2-4                             | ML24215A013                     | A-3.9.2-35                            | ML24346A159                     |
| A-3.4.2-5                             | ML24215A014                     | A-3.9.2-5                             | ML24215A047                     |
| A-3.4.2-6                             | ML24215A015                     | A-3.9.2-7                             | ML24215A050                     |
| A-3.4.2-9                             | ML24215A016                     | A-3.9.2-8                             | ML24215A052                     |
| A-3.5.3-4                             | ML24215A020                     | A-3.9.2-9                             | ML23304A411                     |
| A-3.5.3-6                             | ML24215A021                     | A-3.9.4-1                             | ML23304A423                     |
| A-3.5.3-7                             | ML24215A022                     | A-3.9.4-2                             | ML23205A218                     |
| A-3.6.1-2                             | ML24215A023                     | A-3.9.4-4                             | ML23304A425                     |
| A-3.6.2-1                             | ML24215A025                     | A-3.9.4-5                             | ML23304A427                     |
| A-3.7.2.29                            | ML24215A037                     | A-3.9.4-6                             | ML24215A067                     |
| A-3.7.2-1                             | ML23304A399                     | A-3.9.4-7                             | ML24215A069                     |
| A-3.7.2-14                            | ML24215A027                     | A-3.9.6-1                             | ML23304A429                     |
| A-3.7.2-23                            | ML24215A028                     | A-3.9.6-12                            | ML23304A433                     |
| A-3.7.2-24                            | ML24215A031                     | A-3.9.6-13                            | ML23304A435                     |
| A-3.7.2-25                            | ML24215A032                     | A-3.9.6-14                            | ML23304A436                     |
| A-3.7.2-27                            | ML24215A034                     | A-3.9.6-15                            | ML24215A070                     |
| A-3.7.2-28                            | ML24215A036                     | A-3.9.6-16                            | ML23304A437                     |
| A-3.7.3-1                             | ML24215A038                     | A-3.9.6-5                             | ML23304A431                     |
| A-3.8.2-1                             | ML23304A402                     | A-3.9.6-9                             | ML23304A432                     |
| A-3.8.2-2                             | ML23304A403                     | A-3C.7-1                              | ML24215A084                     |

| <b>Chapter 4</b>                      |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| <b>Question</b>                       | <b>ADAMS ML#</b>                | <b>Question</b>                       | <b>ADAMS ML#</b>                |
| A-4.2-2                               | ML23304A446                     | A-4.4-3                               | ML24346A185                     |
| A-4.2-5                               | ML24346A165                     | A-4.5.1-3                             | ML24215A089                     |
| A-4.2-9                               | ML24346A167                     | A-4.5.1-4                             | ML24215A091                     |
| A-4.3-3                               | ML24346A169                     | A-4.5.2-3                             | ML24215A092                     |
| A-4.3-4                               | ML24215A087                     | A-4.5.2-4                             | ML24346A187                     |
| A-4.3-8                               | ML23304A447                     | A-4.6-1                               | ML23304A448                     |
| A-4.3-10                              | ML24346A169                     | A-4.6-3                               | ML24215A093                     |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| A-4.3-11                              | ML24215A088                     | A-4.Fluence.TeR-4                     | ML24215A096                     |
| A-4.3-25                              | ML24346A173                     | A-4.Fluence.TeR-5                     | ML24215A098                     |
| A-4.3-29                              | ML24346A174                     | A-4.Fluence.TeR-6                     | ML24215A100                     |
| A-4.3-30                              | ML24346A175                     | A-4.Fluence.TeR-7                     | ML24215A102                     |
| A-4.3-31                              | ML24346A176                     | 4.FuelCR.TeR-3                        | ML24346A193                     |
| A-4.3-32                              | ML24346A177                     | 4.FuelCR.TeR-6                        | ML24346A195                     |
| A-4.3-33                              | ML24346A178                     | 4.FuelCR.TeR-10                       | ML24346A197                     |
| A-4.4-1                               | ML24346A181                     |                                       |                                 |

| <b>Chapter 5</b>                      |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-5.1.3.4-1                           | ML24215A103                     | A-5.4.3.3.4-1                         | ML23205A220                     |
| A-5.2.1.1-3                           | ML23205A219                     | A-5.4.3-1                             | ML24215A125                     |
| A-5.2.1.1-4                           | ML23304A449                     | A-5.4.3-2                             | ML24215A127                     |
| A-5.2.1.1-5                           | ML23304A450                     | A-5.4.3-3                             | ML24346A204                     |
| A-5.2.1.2-3                           | ML23304A451                     | A-5.4.3-4                             | ML25035A089                     |
| A-5.2.3.4.2-1                         | ML24215A107                     | A-5.4.3-5                             | ML24346A205                     |
| A-5.2.4.1-2                           | ML24346A200                     | A-5.4.3-7                             | ML24346A207                     |
| A-5.2.5-2                             | ML24215A105                     | A-5.4.5-1                             | ML24346A209                     |
| A-5.2.5-6                             | ML24346A202                     | A-5.4-1                               | ML24215A112                     |
| A-5.3.1.5-1                           | ML24215A108                     | A-5.4-3                               | ML24215A114                     |
| A-5.3.2.2-1                           | ML24346A203                     | A-5.4-6                               | ML24215A115                     |
| A-5.3.2.3-1                           | ML24215A109                     | A-5.4-8                               | ML24215A116                     |
| A-5.3.2.4-1                           | ML24215A110                     | A-5.4-9                               | ML24346A211                     |
| A-5.4.1.2-4                           | ML24215A118                     | A-5.PTLR-10                           | ML24215A134                     |
| A-5.4.1.2-5                           | ML24215A119                     | A-5.PTLR-14                           | ML24215A135                     |
| A-5.4.1.2-7                           | ML24215A120                     | A-5.PTLR-17                           | ML24215A136                     |
| A-5.4.1.3-1                           | ML24215A121                     | A-5.PTLR-6                            | ML24215A130                     |
| A-5.4.1.4-1                           | ML24215A123                     | A-5.PTLR-8                            | ML24215A131                     |
| A-5.4.1.4-2                           | ML24215A124                     | A-5.PTLR-9                            | ML24215A133                     |
| A-5.4.1-1                             | ML24215A117                     |                                       |                                 |

| <b>Chapter 6</b>                      |                                 |                                       |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-6.1.1-1                             | ML24215A138                     | A-6.1.1-8                             | ML24215A140                     | A-6.3-6                               | ML24346A237                     |
| A-6.1.1-2                             | ML24346A214                     | A-6.2.5-1                             | ML24346A232                     | A-6.3-8                               | ML24346A240                     |
| A-6.1.1-3                             | ML24346A217                     | A-6.2-3                               | ML23205A222                     | A-6.3-10                              | ML25022A199                     |
| A-6.1.1-4                             | ML24346A219                     | A-6.2-4                               | ML25022A197                     | A-6.3-12                              | ML24346A242                     |
| A-6.1.1-5                             | ML24346A221                     | A-6.2-5                               | ML24215A141                     | A-6.4-1                               | ML24346A243                     |
| A-6.1.1-6                             | ML24346A222                     | A-6.3.2.2.1-1                         | ML24346A234                     |                                       |                                 |
| A-6.1.1-7                             | ML24346A230                     | A-6.3-5                               | ML24346A236                     |                                       |                                 |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>Chapter 7</b>                      |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-7.1-1                               | ML23304A452                     |

| <b>Chapter 8</b>                      |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-8.3-16                              | ML24346A244                     |

| <b>Chapter 9</b>                      |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-9.1.5-8                             | ML24242A213                     |
| A-9.2.9-2                             | ML23304A453                     |
| A-9.3.4-1                             | ML23304A454                     |
| A-9.5.1.2.4-1                         | ML23205A223                     |

| <b>Chapter 10</b>                     |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-10.3.6-1                            | ML23304A459                     |
| A-10.4-1                              | ML23304A460                     |
| A-10.2-1                              | ML23304A455                     |
| A-10.3-3                              | ML23304A457                     |
| A-10.3-1                              | ML23205A217                     |
| A-10.3-2                              | ML23304A456                     |
| A-10.4.5-6                            | ML23304A462                     |

| <b>Chapter 11</b>                     |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-11.1-2                              | ML23304A464                     | A-11.4-4                              | ML23304A472                     |
| A-11.1-3                              | ML23304A465                     | A-11.5-2                              | ML23304A475                     |
| A-11.3-2                              | ML23304A466                     | A-11.4-5                              | ML23304A473                     |
| A-11.4-1                              | ML23304A467                     | A-11.5-1                              | ML23304A474                     |
| A-11.4-2                              | ML23304A469                     | A-11.5-3                              | ML23304A476                     |
| A-11.4-3                              | ML23304A471                     | A-11.5-4                              | ML23304A477                     |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>Chapter 12</b>                     |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-12.2.1.8-1                          | ML23304A479                     | A-12.4.1.9-1                          | ML23304A487                     |
| A-12.2-1                              | ML23304A481                     | A-12.3.1.1-2                          | ML23304A485                     |
| A-12.2-2                              | ML23205A226                     | A-12.3.2.2-1                          | ML23304A486                     |
| A-12.2-3                              | ML23304A482                     | A-12-1                                | ML23205A227                     |
| A-12.2-5                              | ML23304A483                     |                                       |                                 |

| <b>Chapter 13</b>                     |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| None                                  | N/A                             |

| <b>Chapter 14</b>                     |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-14-3.2-1                            | ML24215A155                     |
| A-Part 8-3.12-5                       | ML24215A158                     |
| A-14.2.12-1                           | ML24215A154                     |
| A-Part 8-2.7-1                        | ML24215A157                     |

| <b>Chapter 15</b>                     |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-15.0.3.7-1                          | ML23205A228                     | A-15.4.3-2                            | ML24215A165                     |
| A-15.0.3.7-2                          | ML24346A247                     | A-15.4.3-3                            | ML24346A284                     |
| A-15.0.4-1                            | ML24346A257                     | A-15.4.3-5                            | ML24346A286                     |
| A-15.0.5-1                            | ML24346A258                     | A-15.4.7-1                            | ML24346A287                     |
| A-15.0.5-2                            | ML24215A159                     | A-15.4.7-4S2                          | ML24346A289                     |
| A-15.0.5-3                            | ML24346A260                     | A-15.4.8-5                            | ML24346A294                     |
| A-15.1.1-3                            | ML24346A262                     | A-15.4.8-6                            | ML24346A295                     |
| A-15.1.1-9                            | ML24346A264                     | A-15.5.1-1                            | ML23304A489                     |
| A-15.1.2-1                            | ML24346A270                     | A-15.6.2-2                            | ML24346A297                     |
| A-15.1.2-3                            | ML24346A272                     | A-15.6.3-1                            | ML23304A490                     |
| A-15.1.3-2                            | ML24346A273                     | A-15.6.5-1                            | ML24348A008                     |
| A-15.1.5-1                            | ML24346A274                     | A-15.6.5-13                           | ML24346A299                     |
| A-15.1.6-2                            | ML24346A276                     | A-15.6.5-14                           | ML24346A300                     |
| A-15.2.4-1                            | ML24346A277                     | A-15.9-1                              | ML25065A161                     |
| A-15.2.7-1                            | ML24215A161                     | A-15.9-2                              | ML24346A302                     |
| A-15.4.1-1S                           | ML24346A280                     | A-15.9-3                              | ML24346A303                     |
| A-15.4.1-2                            | ML24346A282                     | A-15-2                                | ML24346A245                     |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| A-15.4.1-2S                           | ML24346A283                     | A-EDAS.TeR-1                          | ML23304A366                     |
| A-15.4.3-1                            | ML24215A163                     |                                       |                                 |

| <b>Chapter 16</b>                     |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-16.3.5.4-1                          | ML24326A133                     | A-16.5.5.06-1                         | ML24215A204                     |
| A-16.3.3.1-7                          | ML24326A109                     | A-16.3.3.1-6                          | ML24215A194                     |
| A-16.3.3.1-9                          | ML24326A111                     | A-16.5.5.04-1                         | ML24215A184                     |
| A-16-13                               | ML24326A095                     | A-16-9                                | ML24326A093                     |
| A-16.3.5.3-3                          | ML24326A107                     | A-16.3.5.1-2                          | ML24215A200                     |
| A-16.3.5.1-4                          | ML24326A123                     | A-16.3.0-1                            | ML24215A185                     |
| A-16.3.5.1-5                          | ML24326A125                     | A-16-7                                | ML24215A176                     |
| A-16-14                               | ML24326A096                     | A-16.3.5.3-1                          | ML24215A189                     |
| A-16.3.0.4-1                          | ML24326A098                     | A-16.3.3.1-2                          | ML24215A192                     |
| A-16.3.6.3-1                          | ML24326A097                     | A-16.3.3-1                            | ML24215A201                     |
| A-16.2.1.2-2                          | ML24326A134                     | A-16.5.6.4-1                          | ML24215A202                     |
| A-16.3.1.9-2                          | ML24215A207                     | A-16.3.4-1                            | ML24215A171                     |
| A-16.3.1.9-3                          | ML24215A208                     | A-16.4.3.1-1                          | ML24215A170                     |
| A-16.3.3.1-5                          | ML24215A193                     | A-16-3                                | ML24215A174                     |
| A-16.3.1.3-1                          | ML24215A205                     | A-16-4                                | ML24215A177                     |
| A-16.1.1-4                            | ML24215A188                     | A-16-5                                | ML24215A175                     |
| A-16.3.0-2                            | ML24215A186                     | A-16.5.5.09-1                         | ML23304A494                     |
| A-16.5.6.4-2                          | ML24215A203                     | A-16.5.5.09-2                         | ML23304A495                     |
| A-16.3.1.9-1                          | ML24215A206                     | A-16.5.5.09-3                         | ML23304A496                     |
| A-16.3.4.3-1                          | ML24215A172                     | A-16.1.1-1                            | ML23304A493                     |
| A-16.1.1-2                            | ML24215A187                     | A-16-1                                | ML23304A492                     |
| A-16.3.4.7-1                          | ML24215A173                     | A-16-6                                | ML24215A179                     |
| A-16.3.3.1-1                          | ML24215A190                     | A-16.3.3-2                            | ML24326A126                     |
| A-16.3.5.1-1                          | ML24215A199                     | A-16.3.6.3-2                          | ML24326A135                     |
| A-16-10                               | ML24215A178                     | A-16.3.3.1-11                         | ML24326A112                     |
| A-16.3.1.2-1                          | ML24326A127                     |                                       |                                 |

| <b>Chapter 17</b>                     |                                 |
|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-17.4-1                              | ML23304A497                     |
| A-17.4-11                             | ML24215A211                     |

**APPENDIX E - Index of Responses to NRC Requests for Additional Information and Audit  
Items for Standard Design Approval  
(NP: Non-Proprietary; P: Proprietary)**

| <b>Chapter 18</b>                     |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-18.10-1                             | ML23304A514                     | A-18.5-1<br>A-18.5-1S                 | ML23304A506,<br>ML23304A507     |
| A-18.10-2                             | ML23304A515                     | A-18.6-2                              | ML23304A508                     |
| A-18.2-1                              | ML23304A499                     | A-18.7-4                              | ML23304A510                     |
| A-18.3-2                              | ML23304A500                     | A-18.7-5                              | ML23304A512                     |
| A-18.3-3                              | ML23304A501                     | A-18.7-6                              | ML23304A513                     |
| A-18.4-2                              | ML23304A503                     | A-18-1                                | ML23304A498                     |

| <b>Chapter 19</b>                     |                                 |                                       |                                 |
|---------------------------------------|---------------------------------|---------------------------------------|---------------------------------|
| <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> | <b>Audit Items by<br/>SRP Section</b> | <b>Response<br/>Accession #</b> |
| A-19.3-1                              | ML23304A522                     | A-19.1-51                             | ML24215A222                     |
| A-19.1-20                             | ML23304A516                     | A-19.1-53                             | ML24346A312                     |
| A-19.2.6-1                            | ML23205A232                     | A-19.1-55                             | ML24346A314                     |
| A-19.1-19                             | ML23205A230                     | A-19.1-56                             | ML24215A224                     |
| A-19.1-23                             | ML24215A212                     | A-19.1-60                             | ML24215A226                     |
| A-19.1-24                             | ML23205A231                     | A-19.1-62                             | ML24346A320                     |
| A-19.1-25                             | ML23304A517                     | A-19.1-63                             | ML24346A322                     |
| A-19.1-27                             | ML23304A519                     | A-19.1-61                             | ML24346A319                     |
| A-19.1-30                             | ML24215A214                     | A-19.1-64                             | ML24346A324                     |
| A-19.5-12                             | ML23304A524                     | A-19.1-65                             | ML24346A325                     |
| A-19.1-39                             | ML24215A216                     | A-19.1-66                             | ML24346A327                     |
| A-19.1-40                             | ML23304A521                     | A-19.2-32                             | ML24346A334                     |
| A-19.1-41                             | ML24215A217                     | A-19.2-33                             | ML24346A336                     |
| A-19.2-27                             | ML24215A227                     | A-19.2-34                             | ML24346A339                     |
| A-19.1-46                             | ML24215A218                     | A-19.1-37                             | ML24346A308                     |
| A-19.1-5                              | ML24346A306                     | A-19.1-52                             | ML24346A310                     |