

# NRC INSPECTION MANUAL

IRIB

---

## CHANGE NOTICE 26-001

---

### DELETED:

	<u>Number</u>	<u>Date</u>
1.	IMC 2600 App B	07/27/23
2.	IP 41500	06/13/95

### TRANSMITTED:

	<u>Number</u>	<u>Date</u>
	IMC 2600 App B	01/15/26
	IP 41500	01/15/26

TRAINING: No special training is required for documents issued with this Change Notice.

REMARKS: IMC 2600 Appendix B, "NRC Core Inspection Requirements." The HEU Security Measures Procedure Suite (81700 Series) has been updated to remove specific references to inspection hours and frequency. A new statement has been added directing users to Inspection Manual Chapter (IMC) 2681 as the authoritative source for inspection hours and frequency applicable to the IP 81700 series.

IP 41500, "Training and Qualification Effectiveness." Updated 1995 procedure to reference ROP. Modified the inspection thresholds to match current MOAs with INPO, EDO procedures, NRC IMCs, and interfaces with other IPs. Allowed procedure to be referenced as-needed by other inspections, especially supplemental inspections. Modified the actions for accreditation withdrawal so that the licensee can propose how they will comply with regulations, and the NRC can generate an inspection plan to fit the performance issues and the licensee's plan for compliance.

EDITORIAL REVISIONS FROM PREVIOUS CHANGE NOTICES (As Required):

### DISTRIBUTION:

- ☒ Standard  
☐ Official Use Only (OUO)-Security-Related Information

Please contact: \_\_\_\_\_

Email: \_\_\_\_\_

END