



Palo Verde Nuclear
Generating Station

William E. Ide
Vice President
Nuclear Production

TEL (623) 393-6116
FAX (623) 393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01058-WEI/DGM/REB
October 25, 1999

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS) Unit 2
Docket No. STN 50-529,
License No. NPF-51,
Special Report 2-SR-99-001-01**

Pursuant to PVNGS Technical Specification 5.6.8, enclosed is Supplement 1 to Special Report 2-SR-99-001. This supplement provides the complete results of the steam generator tube inservice inspection that was performed during the Unit 2 eighth refueling outage.

By copy of this letter and the enclosure, this Special Report is being provided to the NRC Region IV Administrator and the PVNGS Senior Resident Inspector.

No commitments are being made to the NRC by this letter. Please contact Daniel G. Marks at (623) 393-6492 if you have any questions or require additional information.

Sincerely,

WEI/DGM/REB/kg

Enclosure

cc: E. W. Merschoff (all with enclosure)
M. B. Fields
J. H. Moorman

A0011/

DGM A0011