

PECO Energy Company Limerick Generating Station PO Box 2300 Sanatoga, PA 19464-0920 610 718 2000

10CFR50.73

JE22'

October 22, 1999

Docket No. 50-352 License No. NPF-39

U.S. Nuclear Regulatory Commission

Attn.: Document Control Desk

Washington, DC 20555

SUBJECT: Licensee Event Report

Limerick Generating Station (LGS) - Unit 1

This LER reports a condition prohibited by the Technical Specifications in that a Unit 1 Reactor Core Isolation Cooling (RCIC) system primary containment isolation valve was inoperable for a period that exceeded the Technical Specification allowed outage time. This was due to personnel error during clearance review and approval.

Reference:

Docket No. 50-352

Report Number:

1-99-012

Revision Number:

00

Event Date:

September 25, 1999

Report Date:

October 22, 1999

Facility:

Limerick Generating Station

P.O. Box 2300, Sanatoga, PA 19464

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(i)(B).

Sincerely,

cc: H. J. Miller, Administrator Region I, USNRC

Michael Balley

A. L. Burritt, USNRC Senior Resident Inspector, LGS