

Telephone (412) 393-6000

Nuclear Group P.O. Box 4 Shippingport, PA 15077-0004

> October 22, 1999 L-99-160

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

NPDES Monthly Report, EPA Permit No. PA0025615

SUBJECT: Beaver Valley Power Station, Unit No. 1 and No. 2 BV-1 Docket No. 50-334, License No. DPR-66 BV-2 Docket No. 50-412, License No. NPF-73

Dear Sir:

Enclosed is a copy of the NPDES Monthly Report as submitted to the Pennsylvania Department of Environmental Protection.

Sincerely,


Kevin L. Ostrowski Division Vice President Nuclear Operations and

Kevin L. Ostrowski

Plant Manager

SLV/trs

cc: D. A. Orndorf
J. K Cool
M. S. Ackerman
Licensing File
Central File







Nuclear Group P.O. Box 4 Shippingport, PA 15077-0004 Telephone (412) 393-6000

October 22, 1999 NPD3VPO: 1057

United States Environmental Protection Agency Region III, Pennsylvania (3WM53) Water Permits Branch Water Management Division 1650 Arch Street Philadelphia, PA 19103-2029

NPDES Monthly Report, EPA Permit No. PA0025615

Dear Sir:

This letter forwards a copy of our NPDES Monthly Report as submitted to the Pennsylvania Department of Environmental Resources, Bureau of Water Quality Management.

Sincerely,

Kevin L. Ostrowski Division Vice President Nuclear Operations and

Kevin L. Ostrowski

Plant Manager

SLV/trs

Attachment

cc: D. A. Orndorf J. K. Cool M. S. Ackerman Licensing File Central File





Telephone (412) 393-6000

Nuclear Group P.O. Box 4 Shippingport, PA 15077-0004

> October 22, 1999 NPD3VPO: 1058

Attention: "DMR Clerk" Department of Environmental Protection Bureau of Water Quality Management 400 Waterfront Drive Pittsburgh, PA 15222

NPDES Monthly Report, EPA Permit No. PA0025615

#### Gentlemen:

NPDES Monthly Report for Duquesne Light Company, Beaver Valley Power Station for September 1999 is submitted for your consideration.

Sincerely,

Kevin L. Ostrowski Division Vice President Nuclear Operations and

Kevinh. Ostrowski

Plant Manager

SLV/trs

cc: D. A. Orndorf J. K. Cool M. S. Ackerman Licensing File Central File



Month:

Instructions: Year: 1. Complete monthly and submit with each DMR. Attach additional Permittee: DUQUESNE LIGHT COMPANY sheets and comments as needed for completeness and clarity. 2. Sludge production information will be used to evaluate plant Plant: REAVER VALLEY POWER STATION ... performance. Report only sludge which has been removed from NPDES: -PA 0025615 Municipality: SHIFFING PORT BURGUELL digesters and other solids which have been permanently removed County: HEAVER from the treatment process. Do not include sludge from other plants which is processed at your facility. For sludge that is incinerated: 3. In the disposal site section, report all sludge leaving your Pre-incineration weight = \_\_\_\_ dry tons
Post-incineration weight = \_\_\_\_ dry tons facility for disposal. If another plant processes and disposes of your sludge, just provide the name of that plant. If you dispose of sludge from other plants, include their tonnage in the disposal site section and provide their names and individual dry tonnage on the back of this form. 4. If no sludge was removed, note on form. SLUDGE PRODUCTION INFORMATION (prior to incineration) HAULED AS LIQUID SLUDGE HAULED AS DEWATERED SLUDGE (Conversion (Tons of Dewatered Sludge) X (% Solids) X (% Solids) X (.01) = Dry Tons (Gallons) X Factor) Dry Tons .0000417 14000 TOTAL = 1,17 TOTAL DISPOSAL SITE INFORMATION: List all sites, even if not used this month Site 3 Site 2 Site 4 Site 1 BOROVCH OF MONACA Name: SEWAUE TREATMENTILANT Permit No.: PA 00 20125 Dry Tons Disposed: Type: (check one) Landfill Agr. Utilization Other (specify) County: BEAVER

(SSR-1 3/21/91)

CHEMISTRY MANAGER 10

Month:	
Year:	

1	n	ď	ŧ	_		C	ŧ	1	Λ	n	c	٠
- 1	11	2	L	1	u	١.	L.	1	U	11		-

 Complete monthly and submit with each DMR. Attach additional sheets and comments as needed for completeness and clarity.

2. Sludge production information will be used to evaluate plant performance. Report only sludge which has been removed from digesters and other solids which have been permanently removed from the treatment process. Do not include sludge from other plants which is processed at your facility.

3. In the disposal site section, report all sludge leaving your facility for disposal. If another plant processes and disposes of your sludge, just provide the name of that plant. If you dispose of sludge from other plants, include their tonnage in the disposal site section and provide their names and individual dry tonnage on the back of this form.

Plant:	RIE AVIEK	VALL!Y 1	OWEK. STATION.
NPDES:	P.A UC	25615	
Municip	ality: 5#/	FRINGPORT	BURG WEll
County:	BEAVER		

For sludge that is incinerated:

Pre-incineration weight = \_\_\_\_\_ dry tons

Post-incineration weight = \_\_\_\_\_ dry tons

01:

4. If no sludge was removed, note on form.

	HAULED AS LI				AS DEWATERED SL	UDGE	
Gallons)	X (% Solids)	(Conversion X Factor)	≖ Dry Tons	(Tons of Dewatered Sludge)	X (% Solids)		Dry Tons
12000	2	.0000417	1.00			.01	
						<del> </del>	
<del></del>							
							4.44
						<u> </u>	***
						<del> </del>	
						<del> </del>	
		TOTAL	• 1.00		TOTA	<u> </u>	

DISPOSAL SITE INFORMATION: List all sites, even if not used this month Site 3 Site 4 Site 2 Site 1 BOROVOH OF MONACA SEWAUE TREATMENT (LANT Name: Permit No.: PA 00 20125 Dry Tons Disposed: Type: (check one) Landfill Agr. Utilization Other (specify) County: BEAVER

Signature

CHEMISTRY MANACER 10/27/99

412-393-5113

### THIRD QUARTER CLAMICIDE REPORT

The following aplications were done to small subsystems at Beaver Valley power Station during the third quarter of 1999.

Please note the following densities for liquid products:

Clamtrol CT-1 8.54 pounds per gallon Powerline 3627 8.14 pounds per gallon Betz DTS 10.1 pounds per gallon, 23% solids, 1 tote = 2800 pounds

### Unit 2 on 070799 from 1017 to 1925

### Molluscacide

Powerline 3627 Service Water System 24 gallons

### Detoxification (clay)

DTS Emergency Outfall (010) 1132 pounds DTG Cooling Tower (001) 600 pounds

### Unit 1 on 071499 from 0945 to 1900

#### Molluscacide

Clamtrol CT-1 Turbine Plant River Water System 280 gallons Powerline 3627 Reactor Plant River Water System 38 gallons

### Detoxification (clay)

DTS Catch Basin (403) 566 pounds DTS Cooling Tower 2262 pounds DTG Cooling Tower 1342 pounds

### Unit 2 on 072199 from 0356 to 1830

#### Molluscacide

Powerline 3627 Service Water System Train "B" 60 gallons

#### Detoxification

DTG Cooling Tower 1250 pounds DTS Cooling Tower 644 pounds DTS Emergancy Outfall (010) 644

### Unit 2 on 072399 from 1837 to 072499 0500

### Molluscacide

Powerline 3627 Service Water Train "A" 60 gallons

### Detoxification

DTG Cooling Tower 1250 pounds DTS Cooling Tower 644 pounds DTS Emergancy Outfall 644 pounds PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

BEAVER VALLEY POWER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNDORF

SHIPPINGPORT

PA 15077

Pa0025615 PERMIT NUMBER

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)
(17-19) 001 A DISCHARGE NUMBER

МО

DAY

30

MAJOR (SUBR 05)

Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

F - FINAL

UNITS 182 COOLG. TOWER BLADA.

\*\*\* NO DISCHARGE

NOTE: Read Instructions before completing this form.

MONITORING PERIOD **FACILITY** YEAR DAY YEAR MO . 4 LOCATION ख पु 03 -0.1TO FROM (26-27) (24-25) (22-23)(20-21)

(28-29) (30-31) ATTN: DAVID ORNDORF SAMPLE **QUANTITY OR CONCENTRATION** NO. FREQUENCY (4 Card Only) (3 Card Only) QUANTITY OR LOADING **TYPE** EX (54-61)(46-53)(38-45)(46-53) (54-61)ANALYSIS PARAMETER UNITS MAXIMUM (69-70) **AVERAGE** (64-68)MINIMUM UNITS (62-63) **MAXIMUM** (32-37)**AVERAGE** 12) **化学校设计等** 旅游旅游库岸 建建物橡胶的 GRAC 8.58 SAMPLE 1. 4 8.32 MEASUREMENT SHAP. WEEKLI G 14 (2 12 14 14 protog a 数ななな 6.0 2010/01/05 PERMIT 5 U. 00400 MAXIBUM MINIMUM 应应应贷 EFFLUENT GROSS VALUE REQUIREMENT (19)re re re re re re NIA **放 经股份收收** NIA 数据数据数据 NIA NIAAMMUNIA SAMPLE MEASUREMENT 5 7 8 15 SEKL) LEFOLE TOTAL (AS 74400 2 S 12 3 S 15 **第**中学学 2 (2 2) 22 (2 (2 2) 602000 0 PERMIT 00510 DAILY BY MG/L MO AVG 数数水水泵 REQUIREMENT EFFLUENT GROSS VALUE 存款收款款款 1. IA **抗 的股 在 床 在** 你你你你你你 NIA NIA CLAMTROL CT-1. TOTAL SAMPLE MEASUREMENT OMP 24 KEN WATER 4000000 at take 動物なな 664666 DISCH PERMIT-MG/L DAILY MX 04251 1 MO AVG **建设存款** VALUE REQUIREMENT GROSS 建建筑线路线 EFFLUERT 我就我就你你 ( 3) **家庭教育**家庭 CUNT FLOW, IN CONDUIT SAMPLE 51.51 60.77 PLANTMEASUREMENT JUNIAL THRU TREATMENT 70000 沙豆类 ALLY 3 12 (2 12 15 16 TRETORY REPORT 法联络特 PERMIT 50050 DATLY MX MGO NO AVG EFFLUENT GROSS VALUE REQUIREMENT ( 19) 经经济股份 经存款款款款格 海水水水水水 GRAC TOTAL 0.00 CHLORINE. SAMPLE 0.00 MEASUREMENT EERLYGEAD RESIDUAL 1.25 254500 医腹部 存章 经存款法 12 (2.5) 16 (2.5) 0 50060 PERMIT 8G/L INST MAX HO AVE 虚心电路 EFFLUENT GROSS VALUE REQUIREMENT (19) 存在收收存存 麻麻醇煙脂店 政治政治政治 ONT 1656 m SAMPLE CHLORINE. 0.00 0.00 MEASUREMENT CONTINECOR AVAILABLE . 3 表形的现在分词 海绵水水 /2 to 10 to 10 to 10 0000000 UOUS 0 50064 0 PERMIT MG/L MAXIMUM AVERAGE 医腺溶解 EFFLUEST GROSS VALUE REQUIREMENT (19)**李泰泰泰泰泰** NIA **医 经股股股股股 存款款款款贷** NIA NIA SAMPLE NIA HYDRAZINE MEASUREMENT BEEKLYGRAB 77/2019 namics a 放泳器 e war de DALLY HX MG/L 81313 0 PERMIT 非维维特 EFFLUENT GROSS VALUE REQUIREMENT DATE **TELEPHONE** I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OSTAINING THE INFORMATION, IS TRUE, ACCURATE AND COMPLETE. I AM AWARIE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. § 1001 AND 33 U.S.C. § 1319 (Paparilles under these statutes may include fines up in \$10,000 and or NAME/TITLE PRINCIPAL EXECUTIVE OFFICER David Orndorf 25 412 393-7459 99 10 SIGNATURE OF PRINCIPAL EXECUTIVE DAY

Chemistry Manager

§ 1319. (Penalties under these statutes may include fines up to \$10,000 and or meximum imprisonment of between 6 months and 5 years.)

OFFICER OR AUTHORIZED AGENT

YEAR MO NUMBER

TYPED OR PRINTED COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here) HYDRAZINE AND ARMONIA MONITORING TO APPLY DURING PERIODS OF WET LAYUP-REPORT THE DAILY MAXIMUM FOR BETZ D (THE LIMIT IS 35 MG/L AS A DAILY MAX.) (24 88. COMP.): T-I WHEN DISCHARGING

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

# **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," " Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

# **Legal Notice**

Form Approved. NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) OMB No. 2040-0004 DISCHARGE MONITORING REPORT (DMR) (2-16) MAJOR Approval expires 05-31-98 BEAVER VALLEY POWER STATION (SUBR 05) 002 A P x 0 0 2 5 6 1 5 ADDRESSP. D. BOX 4 DISCHARGE NUMBER F - FINAL PERMIT NUMBER ATTN: DAVID ORNDORF INTAKE SCREEN BACKRASH PA 15077 MONITORING PERIOD SHIPPINGPORT DAY YEAR MO МО DAY YEAR \*\*\* NO DISCHARGE |\_\_| LOCATION 30 UI TO FROM NOTE: Read Instructions before completing this form. (30-31) (24-25) (26-27) (28-29) (22-23) (20-21) ATTN: DAVID ORNDORF SAMPLE **QUANTITY OR CONCENTRATION** NO. FREQUENCY (3 Card Only) QUANTITY OR LOADING (4 Card Only) TYPE (54-61)EX OF (46-53)(38-45)(46-53)(54-61)PARAMETER **ANALYSIS** UNITS **AVERAGE** MAXIMUM MINIMUM (69-70)UNITS (64-68)**MAXIMUM** (32-37)**AVERAGE** 62-63) **法教院教育**章 农设置设备设 **建设设设设设** ( 03) IN CONDUIT OR EST SAMPLE  $\circ$ THRU TREATMENT PLANT MEASUREMENT 0.046 0.006 FSTIM 圖念 众 位 EEKLY 5.6 CONTRACTOR OF STREET REPORT REPORT 0 Ω 50050 PERMIT: ale all the title DAILY MX иср EFFLGENT GROSS VALUE REQUIREMENT MO AVG SAMPLE MEASUREMENT PERMIT REQUIREMENT DATE I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING TELEPHONE NAME/TITLE PRINCIPAL EXECUTIVE OFFICER THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 U.S.C. \$ 1219. (Papallias what these statutes may laplude fines up to \$10.000 and \$1.000 and \$ David Orndorf SIGNATURE OF PRINCIPAL EXECUTIVE 121393-7459

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

MO

DAY

YEAR

NUMBER

OFFICER OR AUTHORIZED AGENT

00027/990708-1124

§ 1319. (Penalties under these statutes may include fines up to \$10,000 and or

meximum imprisonment of between 6 months and 5 years.)

Chemistry Manager

TYPED OR PRINTED

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

### **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," " Permit Number," and "Discharge Number" where indicated (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

NAME BEAVER VALLEY POWER STATION

ADDRESSPACE BOX 4

ATTN: DAVID ORNDORF SHIPPINGPORT

LOCATION

PA 15077

		P	OTINON	RING	PERIO	<u> </u>	
	YEAR	MO	DAY		YEAR	MO	DAY
FROM	99	0.9	UI	TO	99	0.4	30
'	(20-21)	(22-23)	(24-25)		(26-27)	(28-29)	(30-31)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)
(2-16) (17-19)

003 A

DISCHARGE NUMBER

PA0025615

**PERMIT NUMBER** 

MAJOR (SUBR 05) Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

F - FINAL ON UNCONTAMINATED STORM WATER

\*\*\* NO DISCHARGE |\_\_ | \*\*\*

NOTE: Read Instructions before completing this form.

ATTN: DAVID ORNDORF			(20-21)	(22-23) (24-2	25) (26-27) (2	28-29) (30-31)	NOTE: Read Instr	uctions befor	e comb	neung uns	, IOIII.
PARAMETER		(3 Card Only) QUAN (46-53)	TITY OR LOADING		(4 Card Only) (38-45)	QUANTITY OR CONC (46-53)	CENTRATION (54-61)		NO. EX	FREQUENC OF	TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
FLOW, IN CONDUIT OF THEU TREATMENT PLANT	SAMPLE MEASUREMENT	0,021	6.013	( 03)	<b>非常敬敬等</b>	********	*****		0	2/30	25T
50050 1 0 0 EFFLUENT GROSS VALUE	PERMIT	REPORT HO AVG	DATEY HX	MGD		**************************************		<b>拉拉拉拉</b>	•	MONTH	
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT	P 11					1 <u>2</u>				
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT	2.76	1967	-							
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT	N AND								1	
	SAMPLE MEASUREMENT						<b>W</b> 250				
	PERMIT REQUIREMENT	4. S.					F4 17				
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT SAMPLE	### ## 12 13 15 15 15 15 15 15 15 15 15 15 15 15 15				ng (66					200
	MEASUREMENT PERMIT						The state of the s				
NAME/TITLE PRINCIPAL EXECUTIVE O	REQUIREMENT	TIFY UNDER PENALTY OF	LAW THAT I HAVE PER	SONALLY EXAM	MINED AND	Fr. 4 52 52 52 6		TELEPHO	NE		DATE
David Orndorf Chemistry Manager	AM F/ INQUI THE ACCU PENS	TIFY UNDER PENALTY OF MILIAR WITH THE INFORM RY OF THOSE INDIVIDUAL INFORMATION, I BELIEN RATE AND COMPLETE. LTIES FOR SUBMITHIN IBILITY OF FINE AND IMPF 9, (Penaities under these num imprisonment of between the submitted in th	MATION SUBMITTED HE LS IMMEDIATELY RESPO /E THE SUBMITTED   I AM AWARE THAT I IG FALSE INFORMA RISONMENT, SEE 18 U.S	REIN; AND BAS ONSIBLE FOR ( INFORMATION THERE ARE SI TION, INCLUE S.C. § 1001 ANI	SED ON MY DBTAINING IS TRUE, GNIFICANT DING THE D 33 U.S.C. SIGN	ADULE IATURE OF PRINCIPAL	LEXECUTIVE	12 393-7	459	99	10 25
TYPED OR PRINTED	§ 131 maxin	<ol><li>(Penaities under these num imprisonment of between</li></ol>	statutes may include fir en 6 months and 5 years.	nes up to \$10,0 )	000 and or OF	FICER OR AUTHORIZ	ED AGENT	AREA NUMB	ER	YEAR	MO DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

## **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," " Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

# **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME BEAVER VALLEY POWER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNUORF

FACILITY SHIPPINGPORT

LOCATION

PA 15077

PERMIT NUMBER YEAR

FROM

PAG025615

МО

DAY

771

DISCHARGE MONITORING REPORT (DMR) (17-19) 004 8 DISCHARGE NUMBER

DAY

3 V

YEAR MO

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

MONITORING PERIOD

·TOI

MAJOR (SUBR 05) Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

F - FINAL

UNIT ONE COOLS TOWER OVERFLOW

MAN NO DISCHARGE 1 1 PAR

NOTE: Read Instructions before completing this form.

	•		FROM (20-21)	(22-23) (24-2	25) (26-27) (2	28-29) (30-31)	NOTE: Read Instru	actions befor	e comp	leting this	form.
ATTN: DAVID ORNDORF PARAMETER	<b>N</b> /	(3 Card Only) QUAN (46-53)	ITITY OR LOADING	<u>'                                    </u>	(4 Card Only) (38-45)	QUANTITY OR CONC (46-53)	ENTRATION (54-61)		NO. EX	FREQUENCY OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
7.4	SAMPLE MEASUREMENT	<b>公本本会中</b> 在	<b>作的社会体验</b>		(m)	<b>经收收收收</b>	8.45	(12)	0	17	62M
00400 1 0 0 PFLUENT GROSS VALU	PERMIT		Application is	\$455 \$455	6.0 MINIMUM	600000	9.0 NAXIMUM	<b>S</b> U	*	EEKLY	RAD
LOG. TN COMBUIT OR			フフ	( 03)	****	<b>公本市场市场</b>	<b>非非非非非</b> 非			1/7	no g A
0050 1 0 0 OFFLUENT GROSS VALO	PERMIT	MEPORT	DALLY BY	MGD	<b>穿机和杂草</b> 等	62000A		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	*	EEKLY	ELKS:
HLORINE, TOTAL RESIDUAL	SAMPLE MEASUREMENT	t the talk to the	在中华市中中		· · · · · · · · · · · · · · · · · · ·	500	0.00	( 19)	್ತ	1/7	( KA
00050 1 0 0 EFFLUENT GROSS VALU	PERMIT: REQUIREMENT	ANAMAG.	ABACSO (	本本本本 本本本本	\$46374 2	HO AVE	INST MAX	MG/L		L. S.	
HLORINE, FREE	SAMPLE MEASUREMENT	TANK METERS OF	रक्ष भूक्षान देव देव देव		14 170 176 176 187 14 170 176 176 187	, G 60	0.00		Ö	1/7	684
50064 1 0 0 0 REFLUENT GROSS VALU	PERMIT REQUIREMENT	. Transco	ABBRAG.	****		AVERAGE	MAXIAUM	mG/L			
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	195) 2-74 7-4				
	SAMPLE MEASUREMEN	г						1			
	PERMIT REQUIREMENT						100000000000000000000000000000000000000				100
	SAMPLE MEASUREMEN	T									
	PERMIT REQUIREMENT	TIEV LINDED DEMALTY OF	ELAW THAT I HAVE BED	SONALLY FYAN	AINED AND	1.27		TELEPHO	DNE	1	DATE
David Orndorf	AM F. INQUITHE ACCU	AMILIAR WITH THE INFORMING OF THOSE INDIVIDUAL INFORMATION, I BELIE JRATE AND COMPLETE. ALTIES FOR SUBMITTI	MATION SUBMITTED HE LS IMMEDIATELY RESPO VE THE SUBMITTED I AM AWARE THAT I NG FALSE INFORMA	ONSIBLE FOR CONSIBLE FOR CONSIBLE FOR CONFIDENTIAL STREET OF THE STREET	DBTAINING IS TRUE, GNIFICANT DING THE	NATURE OF PRINCIPAL	LEXECUTIVE	12 293-		90	10.3
Chemistry Manager TYPED OR PRINTED	§ 13° maxin	SIBILITY OF FINE AND IMP 19. (Penalties under these num imprisonment of betwo	statutes may include fineen 6 months and 5 years.	nes up to \$10,	000 and or Ol	FFICER OR AUTHORIZ	ED AGENT IA	REA NUME		YEAR	MÖ D

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

## **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

Form Approved. PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR) OMB No. 2040-0004 NAME MAJOR BEAVER VALLEY POWER STATION Approval expires 05-31-98 (SUBR 05) PA0025615 006 ADDRESSP. D. BOX 4 PERMIT NUMBER DISCHARGE NUMBER F - FINAL ATTN: DAVID OREDORF AUX. INTAKE SCREEN BACKWASH PA 15077 SHIPPINGPORT **MONITORING PERIOD FACILITY** МО DAY YEAR MO DAY YEAR \*\*\* NO DISCHARGE | | \*\*\* LOCATION 30 W.L **FROM** NOTE: Read Instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) ATTN: DAVID ORNDORF SAMPLE QUANTITY OR CONCENTRATION NO. FREQUENCY (3 Card Only) QUANTITY OR LOADING (4 Card Only) (54-61)EX TYPE (46-53)OF (54-61)(38-45)PARAMETER (46-53) ANALYSIS (32-37) **MAXIMUM** UNITS **MAXIMUM** UNITS MINIMUM **AVERAGE AVERAGE** (69-70)(62-63) (64-68)RE RELIE DE LE LE **经数据数据** (0.3)IN CONDUIT OR SAMPLE EST THRU TREATMENT PLANT MEASUREMENT 0.002 0.016 经收款 EERLYESIIA REPORT . . . . . . . . . . . . 50050 1 0 0 PERMIT 存存单数 DAILY NX MGD HEFFLUENT GROSS VALUE REQUIREMENT BO AVO SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE **MEASUREMENT** PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT **TELEPHONE** DATE

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER

David Orndorf
Chemistry Manager
TYPED OR PRINTED

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. § 1001 AND 33 U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 and or maximum imprisonment of between 6 months and 5 years.)

SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT

412 393-7459 99 10 25 AREA OODE NUMBER YEAR MO DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

### **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent,""Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

## **Legal Notice**

Form Approved. NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) DISCHARGE MONITORING REPORT (DMR)
(2-16) (17-19) OMB No. 2040-0004 MAJOR Approval expires 05-31-98 BEAVER VALLEY POWER STATION (SUBR 05) 007 PA0025615 ADDRESSP.O. BOX 4 DISCHARGE NUMBER F - FINAL PERMIT NUMBER ATTN: DAVID ORNBORF AUX. INTAKE SYSTEM PA 15077 SHIPPINGPORT MONITORING PERIOD DAY YEAR MO YEAR MO DAY \*\*\* NO DISCHARGE 30 LOCATION 99 01 99 TO FROM NOTE: Read Instructions before completing this form. (28-29) (30-31) (26-27) (22-23) (24-25) (20-21) ATTN: DAVID ORNOORF SAMPLE NO. FREQUENCY **QUANTITY OR CONCENTRATION** (3 Card Only) QUANTITY OR LOADING (4 Card Only) TYPE (54-61)(46-53)(38-45)(54-61)(46-53) PARAMETER ANALYSIS MAXIMUM UNITS **AVERAGE** (69-70)MINIMUM UNITS (64-68)(32-37)MAXIMUM **AVERAGE** 经现款保险额 (12)**化学性化学性** 政治政策政策。 PH SAMPLE MEASUREMENT FERRING ALL 2.6 2006.6 18 18 18 18 0027606 bouba 0 PERMIT 1 MAKIBUM SU MINIMUM **建筑旅游** EFFLUENT GROSS VALUE REQUIREMENT 应应应应的存在 密路数路标准 **你这些你你你** ( 03) FLOW, IN CONDUIT OR SAMPLE THRU TREATMENT PLANT MEASUREMENT A PROPERTY OF THE PROPERTY OF 存立な 993466 COLUMN TAXABLE 10.10.10.10.10.10.10 MEDORT BEFORE () 50050 PERMIT 经保存货 EFFLUENT GROSS VALUE REQUIREMENT DAILY MA MCD MO AVG ( 19) 应收收收应应 of high tack in 放出旅游旅游 CHLORINE, TOTAL SAMPLE MEASUREMENT RESIDUAL **ELALY GRAD** . 23 2000000 . . . 医皮肤性皮肤 医腺溶液 u a p n a a . 0 0 50060 PERMIT INST MAX MG/L MO AVS 自身收收收 REQUIREMENT EFFLUENT GROSS VALUE ( 19) <u>ប្រុស្សស្រុស</u> of other factor 建筑建筑建筑 CHLORINE. SAMPLE MEASUREMENT AVAILABLE EXALTERAT CONTRACTOR de de state da la la 20 00 00 KANDODE 0 0 50064 1 PERMIT MG/L MAXIMUR AVERAGE fix di de de EFFLUENT GROSS VALUE REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT DATE **TELEPHONE** I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING NAME/TITLE PRINCIPAL EXECUTIVE OFFICER THE INFORMATION I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 U.S.C.

meximum imprisonment of between 6 months and 5 years.) TYPED OR PRINTED COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

MONITORING FOR FLOW, FREE AVAILABLE CHIDEINE, AND TOTAL RESIDUAL CHIORINE ARE REQUIRED ONLY DURING THOSE PERIODS OF DISCHARGE FROM THE ALTERNATE FLOW PATH OF THE REACTOR PLANT RIVER WATER SYSTEM.

§ 1319. (Penalties under these statutes may include fines up to \$10,000 and or

David Orndorf

Chemistry Manager

MO

DAY

YEÁŘ

AREA NUMBER

SIGNATURE OF PRINCIPAL EXECUTIVE

OFFICER OR AUTHORIZED AGENT

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

# **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," " Permit Number," and "Discharge Number" where indicated (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent,""Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

## **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME

BEAVER VALLEY POWER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNDORF

PA 15077

FACILITY SHIPPINGPORT LOCATION

MONITORING PERIOD DAY YEAR MO DAY YEAR мо . 01

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

PA0025515

**PERMIT NUMBER** 

DISCHARGE MONITORING REPORT (DMR)

008 8

DISCHARGE NUMBER

MAJOR (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

UNIT 1 COOLING TOWER PUMPHOUSE

par NO DISCHARGE I\_\_ | \*\*\*

NOTE: Read Instructions before completing this form.

ATTN: DAVID ORNDORF			(20-21)	(22-23) (24-2	25) (26-27) (2	28-29) (30-31)	NOTE: Read Instr	uctions beloi				
PARAMETER		(3 Card Only) QUAN (46-53)	ITITY OR LOADING (54-61)		(4 Card Only) (38-45)	QUANTITY OR CONC (46-53)	ENTRATION (54-61)		NO. EX	FREQUENCY OF	SAM	
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-	70)
PH	SAMPLE MEASUREMENT	\$\$\$\$\$\$\$	0 00000		(A) (D)	# # # # # # # # # # # # # # # # # # #	8,92	(-3.2)	10	1/30	62	74.00
00400 1 0 0	PERMIT	. Comment	seconde d	\$\$\$ \$\$\$\$	6.U ± ± MINIMUM €	o white or	MAXIBUM	<b>5</b> 0		WICE/ MONTH	GRA	J
EFFLUENT GROSS VALUE SOLIDS, TOTAL	SAMPLE MEASUREMENT	<b>***********</b>	बहेर अहेराहित वहेर द्वेर द्वेर		教育等的作品	27.7	11.3	(19)	0	2/30	1	ı
SUSPENDED 00530 1 0 0	PERMIT .	004690	CONCER C	ស្នប្ ស្នប្ប	444446	MO AVG	DAILY WX	MC/L	E-02/200900000000000000000000000000000000	WICEY MONTH		đ
EFFLUENT GROSS VALUE OIL & GREASE	SAMPLE MEASUREMENT	ale ale sin te de en	\$ \$5 \$5 \$ \$		5.8	1. 1.	6.6	(19)	0	3/30		RAB
00556 1 C 0 EFFLUENT GROSS VALUE	PERMIT	-400000	teace :	\$\$\$ \$\$\$\$	15 MO AVG	DATEY WX	30 INST MAX	****	1	WICE/ MOWER	GRA	U.
FLOW, IN CONDUIT OR THRU TREATMENT PLANS	SAMPLE		20.001	( 03)	<b>化学学的</b>	<b>安安安安</b> 泰	the effective size ye		ن	1/7	85	
50050 1 0 C EFFLUENT GROSS VALUE	PERMIT	KFROMI	DATLY MX	MGD	20000	Sec. 10 and 10		· · · · · · · · · · · · · · · · · · ·		EBAL)		* **
	SAMPLE MEASUREMENT		·									200
	PERMIT REQUIREMENT						4					
	SAMPLE MEASUREMEN	Г										
	PERMIT REQUIREMENT				1 4 4 E	11 THE ST. 12	1227-01-152					
	SAMPLE MEASUREMEN	г										
	PERMIT REQUIREMENT				INED AND	52 2 6 6 6 6 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8		TELEPHO	NF	-	DATE	
NAME/TITLE PRINCIPAL EXECUTIVE		ITIFY UNDER PENALTY OF AMILIAR WITH THE INFOR IRY OF THOSE INDIVIDUA				NO 0.	. / / F	I Eleke I I C	,,,,,			
David Orndorf Chemistry Manager	THE ACCU	AMILIAR WITH THE INFON IRY OF THOSE INDIVIDUA INFORMATION, I BELIE JRATE AND COMPLETE. ALTIES FOR SUBMITTI SIBILITY OF FINE AND IMP	VE THE SUBMITTED I I AM AWARE THAT T NG FALSE INFORMAT PRISONMENT, SEE 18 U.S	NFORMATION HERE ARE SI FION, INCLUDE S.C. § 1001 ANI	IS TRUE, GNIFICANT DING THE D 33 U.S.C. SIGN	IATURE OF PRINCIPAL	_ EXECUTIVE	12 393-7			10	25
TYPED OR PRINTED		19. (Penalties under these num imprisonment of between			000 and of OI	FFICER OR AUTHORIZ	ED AGENT	ODE NUME	BER	YEAR	МО	DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

# **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent,""Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

## **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME

BEAVER VALLEY POWER STATION ADDRESSP. G. BOX 4

ATTN: BAVID ORNOORF

PA 15077

SHIPPINGPORT LOCATION

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR) (17-19)

010 A PAG025615 PERMIT NUMBER DISCHARGE NUMBER MAJOR (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

**MONITORING PERIOD** DAY YEAR MO YEAR MO DAY 30 01 FROM

UNIT 2 COOLING WATER

ARR NO DISCHARGE |\_\_ | AAR

NOTE: Read Instructions before completing this form.

NOTE: Read Instructions bef	iore com	pleting this	
CONCENTRATION (54-61)	NO.	FREQUENCY OF	SAMPLE TYPE
GE MAXIMUM UNITS	(02-03)	ANALYSIS (64-68)	(69-70)
7,82 (12)	0	17	GRAS
NAXINUK SO		EEKLY	SHAB
N/A (19)	MA		N/A
G INST MAX MG/L		DISCU	LOME 2
京教教 - 教教教教教教	0	1/7	INFAS
· · · · · · · · · · · · · · · · · · ·		MERUPI	18.X5R
( 19 ( 19	<u>'</u>	117	GRAP
G INST MAX CG/L	2.00000	#FFALT	BRAU
0,00		1/7	GRAF
GE MAXIMUM MG/L			
		1.	
TELEDI	- LONE		DATE
NCIPAL EXECUTIVE			
	INCIPAL EXECUTIVE	TELEPHONE  TELEPHONE  AREA SHIPMER 9	INCIPAL EXECUTIVE

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

REPORT THE DAILY MAXIMUM FOR BETZ DT-1 WHEN DISCHARGING (24 BR. COMP.) :

MG/L.

(THE LIMIT IS 35 M

S/L AS A DAILY MAX.)

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

### **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

# **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME BEAVER VALLEY POWER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNBORF

FACILITY SHIPPINGPORT

LOCATION

PA 15077

MONITORING PERIOD YEAR MO DAY YEAR MO DAY 91 (3.7 30 **FROM** (28-29) (30-31) (20-21) (26-27)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)
(2-16) (17-19)

PA0025615

**PERMIT NUMBER** 

MAJOR (SUBR 05) F - FINAL

Ď

DISCHARGE NUMBER

Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

MAR NO DISCHARGE |\_\_ | ###

DIESEL GEN & TURBINE DEAINS

ATTN: DAVID ORNDORF			(20-21)	(22-23) (24-	25) (26-27) (2	8-29) (30-31)	NOTE: Read Instr	uctions befor	e comp	oleting this	orm.
PARAMETER		(3 Card Only) QUAN (46-53)	ITITY OR LOADING (54-61)		(4 Card Only) Q (38-45)	UANTITY OR CONC (46-53)	CENTRATION (54-61)		NO. EX	FREQUENCY OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
FLOW, IN CONDUIT OR THRU TREATMENT PLANT	SAMPLE MEASUREMENT	0.602	0.002	( 03)	Be the Be the Co.	故故故故称故	<b>经存货的</b> 经收款		្	1/7	EST
50050 1 0 0 EFFLUENT GROSS VALUE	PERMIT	RZPORT MO AVG	REPORT DATES BX	MGD		<b>444.00</b>	*****	****	¥	ELKLY	STAMA
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT						TIVE				
	SAMPLE MEASUREMENT						Total Control				1.
	PERMIT REQUIREMENT SAMPLE			<u> </u>							
	MEASUREMENT PERMIT					-27	7			-	1
	REQUIREMENT SAMPLE		-				To the second				
	MEASUREMENT PERMIT		7 15 15 15 15 15 15 15 15 15 15 15 15 15				177 177 184				
	REQUIREMENT  SAMPLE  MEASUREMENT					<u> </u>					
	PERMIT REQUIREMENT						721 123 123 123 123 123 123 123 123 123 1				
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT	100								-	
NAME/TITLE PRINCIPAL EXECUTIVE C	OFFICER I CERT	TFY UNDER PENALTY OF MILIAR WITH THE INFORM BY OF THOSE INDIVIDUAL	LAW THAT I HAVE PERS MATION SUBMITTED HER S IMMEDIATELY RESPO	SONALLY EXAM REIN; AND BAS INSIBLE FOR C	MINED AND SED ON MY DETAINING	100	· /	TELEPHO	NE	D/	ATE
David Orndorf Chemistry Manager	THE ACCU PENAL POSSI	IFY UNDER PENALTY OF MILIAR WITH THE INFORM RY OF THOSE INDIVIDUAL NORMATION, I BELIEVARATE AND COMPLETE. TIES FOR SUBMITTIN BILITY OF FINE AND IMPROPERS OF THE AND IMPORTANT OF	/E THE SUBMITTED II I AM AWARE THAT TI IG FALSE INFORMAT RISONMENT, SEE 18 U.S	NFORMATION HERE ARE SIGNON, INCLUDE I.C. § 1001 AND	IS TRUE, GNIFICANT DING THE D 33 U.S.C. SIGNA	ATURE OF PRINCIPAL	EXECUTIVE			99 ]	.0 25
TYPED OR PRINTED	§ 1319 maxim	(Penalties under these um imprisonment of between	statutes may include fin en 6 months and 5 years.)	es up to \$10,0	OFF	FICER OR AUTHORIZE	D AGENT	ODE NUMBI	427	YEAR N	10 DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

### **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

## **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME BEAVER VALLEY POWER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNDORF SHIPPINGPORT

PA 15077

**FACILITY** LOCATION

MONITORING PERIOD YEAR MO DAY YEAR MO DAY 30 **FROM** 

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

PA0025615

**PERMIT NUMBER** 

DISCHARGE MONITORING REPORT (DMR) (2-16) (17-19)

012 A

DISCHARGE NUMBER

MAJOR (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

see NO DISCHARGE | \_\_ | \*\*\*

BLOWDOWN FROM THE HVAC UNIT

NOTE: Read Instructions before completing this form.

TTN: DAVID ORNDORF			(20-21)	(22-23) (24-2	25) (26-27) (2	8-29) (30-31)	NOTE: Read Instru	Ctions beloi			
PARAMETER		(3 Card Only) QUAN (46-53)	TITY OR LOADING		(4 Card Only) Q (38-45)	UANTITY OR CON( (46-53)	CENTRATION (54-61)		NO.	FREQUENC OF	TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70
H	SAMPLE MEASUREMENT	在中央中心	作的社会协会		ଚ. ଚନ	\$\$\$\$\$\$	8.88	(12)	Ú	1/30	144
0400 1 0 0 FPLUENT GROSS VALUE	PERMIT	ten person	enange i	ល់ល់ល លំល់លំល	o.O in mon	****	NUMIXAM	50	Ü	NCE/ MONTI	SKAD
LOW, IN CONDUIT OR HRU TREATMENT PLANT	SAMPLE		10.001	( 03)	<b>\$\$\$\$\$</b> \$	<b>非政策收收</b> 集	र्श्वर प्रोहर प्रोहर प्रोहर प्रोहर प्रोहर		0	1/30	<i>§</i> 51
0050 1 0 0 FELUENT GROSS VALUE	PERMIT	REPORT	REPORT DAILY MX	MGD	<b>00000</b>	* * * * * * * * * * * * * * * * * * *	- ************************************	State State	*	NONT	571
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT					3 - E	20				=
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT			<u> </u>			100 mag				
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT	4				2 2 7 2 2	117	<u> </u>			
	SAMPLE MEASUREMENT PERMIT										
	REQUIREMENT										
	MEASUREMENT PERMIT										
NAME/TITLE PRINCIPAL EXECUTIVE O	REQUIREMENT	TIEV LINDED DENALTY OF	LAW THAT I HAVE PERS	SONALLY EXAM	IINED AND	F. G. Stranger	7247 cm - 63	TELEPHO	NE		DATE
David Orndorf		MILIAR WITH THE INFOR RY OF THOSE INDIVIDUA INFORMATION, I BELIA INFORMATION, I BELIA INFORMATION, I BELIA INFORMATION INFORMATION INFORMATION INFORMATION INFORMA				Duntos					
Chemistry Manager					ONG THE OSSIGN	ATURE OF PRINCIPAL FICER OR AUTHORIZ		12 393-7		99 YEAR	10 D
TYPED OR PRINTED	mexin	a. (Ferialities under these num imprisonment of betwe	en 6 months and 5 years.		UF UF	FIGER OR AUTHORIZ	0	ODE   NOME		T I FVII	1410 L

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

# **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

## **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME BEAVER VALLEY POWER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNDORF

FACILITY SHIPPINGPORT

PA 15077

LOCATION

MONITORING PERIOD YEAR МО DAY YEAR MO DAY 30 91 **FROM** (28-29) (30-31) (26-27)

PA0025615

**PERMIT NUMBER** 

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR) (2-16)

013

DISCHARGE NUMBER

MAJOR (SUBR 05)

F - FIRAL

OUTFALL 013

Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

CAS NO DISCHARGE | \_\_ | \*\*\*

NOTE: Read Instructions before completing this form.

ATTM: DAVID ORNDORF		* * * * * * * * * * * * * * * * * * *	(20-21)	(22-23) (24-2	25) (26	3-27) (28	-29) (30-31)	NOTE: Read ins	il dedorio pere			
PARAMETER		(3 Card Only) QUAN (46-53)	TITY OR LOADING (54-61)		(4 Card Only) (38-4	(5)	UANTITY OR CONC (46-53)	ENTRATION (54-61)		NO.	FREQUENC OF	Y SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMU	JM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
PH	SAMPLE MEASUREMENT	中国政治政治	<b>多本的多多</b>		6.4	4	<b>你你你你你你</b>	7.69	( 1.2)	ပ	1/7	GRAS
00400 1 0 0 EFFLUENT GROSS VALUE	PERMIT REQUIREMENT	000000 1000000000000000000000000000000	ACTIONS O	\$\$\$\$ \$\$\$\$	6.0 MINIM	UM		WVXIMIK 3.0		K	PEKLY	DRAB
FLOW. IN CONDUIT OR THRU TREATMENT PLANT	SAMPLE	0.005	0.008	( 03)	के के दि		<b>经验存款收款</b>	存存存在存		0	1/7	257
50050 1 0 0 EFFLUERT GROSS VALUE	PERMIT	REPORT NO AVG	DAILY MX	MGD	0600		2040AA	<b>****</b>	经额额	*	EBRLI	25110
CHLORINE, TOTAL RESIDUAL	SAMPLE MEASUREMENT	होत क्षेत्र की की की की	经存货的证券			****	0131	0.74	( 19)	0	3/3c	CAL
50060 1 0 0 EFFLUENT GROSS VALUE	PERMIT: REQUIREMENT			物學學 物學學學。	****	***	HEPORT 10 AVS	REPORT INST MA	0000000 <b>1</b>	•	MONT:	
	SAMPLE MEASUREMENT											
	PERMIT REQUIREMENT							2 Carl				
	SAMPLE MEASUREMENT							:				
	PERMIT REQUIREMENT					-		10.2				
	SAMPLE MEASUREMENT											
·	PÉRMIT REQUIREMENT				-							
	SAMPLE MEASUREMENT											
	PERMIT REQUIREMENT	7.5		ONALLY EVAL	UNED AND		122	35-33	TELEPHO	NE.		DATE
NAME/TITLE PRINCIPAL EXECUTIVE O	AM FA	TFY UNDER PENALTY OF MILIAR WITH THE INFORM BY OF THOSE INDIVIDUAL	MATION SUBMITTED HEI S IMMEDIATELY RESPO	NSIBLE FOR C	OBTAINING	0	VO 0		i LLLI 110		† T	
David Orndorf						11	thill		(101303	71.60	00	10 2
Chemistry Hanager TYPED OR PRINTED	POSSI § 1318 maxim	NFORMATION, I BELIEN RATE AND COMPLETE. TIES FOR SUBMITTIIN BILITY OF FINE AND IMPI B. (Penalties under these um imprisonment of between	HISONMENT. SEE 18 U.S statutes may include fin en 6 months and 5 years.)	6.U. § 1001 AND 68 up to \$10,0	000 and or		TURE OF PRINCIPAL FICER OR AUTHORIZE	D AGENT	412 393- AREA CODE NUMB	1434 ER	YEAR	MO DA

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

THERE SHALL BE NO DISCHARGE OF FLOATING SOLIDS OR VISIBLE FOAM IN OTHER THAN TRACE AMOUNTS.

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

## **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent,""Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

# **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME BEAVER VALLEY FOWER STATION

ADDRESS O. BOX 4

ATTN: GAVID ORRDORF

FACILITY SEIPPINGPORT

PA 15077

PA0025615 PERMIT NUMBER DISCHARGE NUMBER

MAJOR (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

101 CHENICAL WASTE TREATMENT

YEAR MO DAY YEAR MO DAY \*\*\* NO DISCHASGE |\_\_ | \*\*\* LOCATION 30 99 UI. FROM NOTE: Read Instructions before completing this form. (24-25) (28-29) (30-31) (22-23) ATTM: DAVID ORNDORF NO. FREQUENCY SAMPLE CONTRACTOR OF THE PROPERTY OF LOADING QUANTITY OR CONCENTRATION (A Cord Only)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR) (17-19)

MONITORING PERIOD

PARAMETER		(3 Card Only) QUAN (46-53)	ITITY OR LOADING (54-61)		(4 Card Only) QUANTITY OR CONCENTRATION (38-45) (46-53) (54-61)				EX	OF	TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM		ITS (62-63)	ANALYSIS (64-68)	(69-70)
PH	SAMPLE MEASUREMENT	क्षेत्र के हैंद के हैंद है	<b>\$</b> \$\$\$\$\$\$\$		7.36	sin air rin his ga his	7,72	(1	1   0	1/~7 LEKLY	GRAS
OC400 1 0 0 EFFLUENT GROSS VALUE	PERMIT REQUIREMENT	oppose T		存在存储 存在存储	MINIMUM	# 00000 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	9.0 MAXIMUM	50		LANLI	TA A LO
SOLIDS, TOTAL SUSPENDED	SAMPLE MEASUREMENT		र्यं भंगते के में में		<b>企业业业业</b> 企	44	<4/r	( 1	0	1/7	Comp
00530 1 0 0 EFFLUENT GROSS VALUE	PERMIT REQUIREMENT	-> <b>4246</b>		ជាជាជ្ ជាជាជ្រ	\$\$\$\$\$	NO AVG	DAILY M.	0.000000000	1999 0000		
OIL & GREASE	SAMPLE MEASUREMENT		<b>有一种政府</b>		V 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	< 5 13	< 5 20			1/7	CRAS
00556 1 0 0 EFFLUENT GROSS VALUE		48444	A STATE OF A	推推	0.000000	NO AVG	DAILY &		L (3)		1
NITROGEN. ABMONIA TOTAL (AS H)	SAMPLE MEASUREMENT	\$ \$ \$ \$ \$ \$ \$ \$ \$		la se de	5. \$1. \$2. \$4. \$4. \$4. \$4. \$4. \$4. \$4. \$4. \$4. \$4	N/A	N/A	-	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	N/A	NA GRAB
00610 1 0 C EFFLUENT GROSS VALUE				**** ( 03)	****	*0 AVC	DAILY #	X MG/		$\delta aI$	*
FLOW, IN CONDUIT OR THEO TREATMENT PLANT 50050 1 0 0	SAMPLE MEASUREMENT	-atport	6.005 REPORT		44440	000000	44444	***		ALLY	7
EFFLUENT GROSS VALUE HYDRAZINE	PERMIT REQUIREMENT SAMPLE		DATLY MX	MGD ·	****	NIA	NIA	( 1	(\$) (	1/-7	0000
61313 1 0 0	MEASUREMENT PERMIT	1 302688	taboli i	· ·	<b>Ackan</b> o	REPORT	REPORT			ZEKL	GRAD CURRE
EFFLUENT GROSS VALUE	REQUIREMENT			<b>京本京</b> 章		HO AVG	DAILY M	X MG/	<u>'L</u>		
	MEASUREMENT PERMIT	T									
	REQUIREMENT		- AMERICA TO THE SECOND	ONALLY EVA	INED AND	1.4		TELE	PHONE		DATE
NAME/TITLE PRINCIPAL EXECUTIVE OFFICER  I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 U.S.C. SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT									393-7459		10 25
cillavid OrndorfoGhemi	stry Man Poss	BIBILITY OF FINE AND IMP 9. (Penalties under these	RISONMENT. SEE 18 U.S statutes may include fin	S.C. § 1001 ANI es up to \$10,0	0 33 U.S.C. SIGNA 000 and or OF	ATURE OF PRINCIPAL FICER OR AUTHORIZI	EXECUTIVE DAGENT	AREA N	IUMBER	YEAR	MO DAY

TYPED OR PRINTED

meximum imprisonment of between 6 months and 5 years.)

CODE NUMBER YEAR MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here) \* OVT FOR REPAIRS 9 121199 PYDRAZINE AND AMMONTA MONITORING TO APPLY DURIEG PERIODS OF WET LAYUP.

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

## General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

# **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) BEAVER VALLEY POWER STATION

ADDRESSP.D. BOX 4 ATTN: DAVID ORNDORF

FACILITY SHIPPINGPORT

LOCATION

PA 15077

MONITORING PERIOD YEAR МО DAY DAY YEAR МО 30 VI. TO FROM (28-29) (30-31) (26-27) (20-21) (22-23) (24-25)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

PAC025615

PERMIT NUMBER

DISCHARGE MONITORING REPORT (DMR)
(2-16) (17-19)

102 A

DISCHARGE NUMBER

MAJOR (SUBR US) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

\*\*\* NO DISCHARGE |\_\_ | \*\*\*

102 INTAKE SCHEENHOUSE

NOTE: Read Instructions before completing this form.

	£*\	the second second	(20-21)	(22-23) (24-2	••,	(20-28) (00-01)	NOTE: Read Ins	u uctions belor			
THE DAVID ORNBOR		(3 Card Only) QUANTITY OR LOADING (46-53) (54-61)			(4 Card Only) (38-45)	QUANTITY OR CONC (46-53)	ENTRATION (54-61)		NO.	FREQUENCY OF	TYPE
PARAMETER (32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70
	SAMPLE	沙海绵绵绵症	<b>原本政治政</b> 章		July July	常态容易存款	7.95	( 12)	10	2/20	62
	MEASUREMENT				7,89	NATURE .	9.0		T	WICE/	FAD
400 1 0 0	PERMIT	<b>有效物数数</b>	Actorist (	4444	MINIMUM		MAXIMUM	5 U		MONTH	
FLUENT GROSS VAL	SAMPLE	<b>李森林春春</b> 珍	赤蛇纹纹纹纹		<b>存在的现在分</b>		4.6	(13)	$\perp_{\circ}$	2/30	163
SPENDED	MEASUREMENT			S 30. No.		4,5	71.0		1	WICE7	GRAE
530 1 0 0	PERMIT	<b>建设存货条件</b>	panete (	A D D D	77	no ave	DATES M			MONTH	
PLUENT GROSS VAL L & GREASE	JUE REQUIREMENT	****	<b>化物色色谱器</b>		<b>电影电影电影</b>		J. James	( 19)	$\perp_{o}$	3/30	. Coric
L & GREASE	MEASUREMENT					45	40		7	WICE/	CRAE
556 1 0 0	PERMIT	000000	narionalis i	整数数数		HO AVG	DAILY K			MONTH	
FLUENT GROSS VAI	LUE REQUIREMENT	<u> </u>		( 03)	\$ \$ \$ \$ \$ \$ \$ \$	农水政务等介	***	<b>*</b>	6	2/30	185
HO TREATMENT PLA	MEASUREMENT	(0,001	40,001		ESD OF		4 5 4 5 5 5	***	1	WICE/	7 ST.
050 1 0 0	PERMIT	REPORT BO AVG	DATLY MX	ಕ್ರಾ	****	3.6		***		MONT	
FLUENT GROSS VAL	REQUIREMENT SAMPLE										
	MEASUREMEN	Г									
	PERMIT REQUIREMENT	4.0									
	SAMPLE										
	MEASUREMEN	T									
	PERMIT REQUIREMENT	r							-		+
	SAMPLE										
	MEASUREMEN PERMIT										
	BEOLUBEMEN	T			MINED AND		<u> </u>	TELEPHO	ONE		DATE
NAME/TITLE PRINCIPAL EXECUT	TIVE OFFICER I CEI	RTIFY UNDER PENALTY OF AMILIAR WITH THE INFO	IF LAW THAT I HAVE PER RMATION SUBMITTED HI ALS IMMEDIATELY RESE	RSUNALLY EXA EREIN; AND BA PONSIBLE FOR	SED ON MY OBTAINING	WO O					
	THE ACC	AMILIAR WITH THE INFOI JIRY OF THOSE INDIVIDU INFORMATION, I BELI URATE AND COMPLETE. ALTIES FOR SUBMITT	EVE THE SUBMITTED I AM AWARE THAT	INFORMATION THERE ARE S	I IS TRUE, SIGNIFICANT	Hauth	4	   412 <sub> </sub> 393 <i>•</i>	-745Q	99	10
David Orndorf	I POS	SIBILITY OF FINE AND IN	o statutas may include i	fines up to \$10	ND 33 U.S.C. SIG	NATURE OF PRINCIPA OFFICER OR AUTHORI	L EXÉCUTIVE ZED ÁGENT	AREA NUM		YEAR	10 MO
Chemistry Manager TYPED OR PRINTER	D § 13	mum imprisonment of betw	reen 6 months and 5 years	s.)				1 CODE 1			

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

# **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

# **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME

SEAVER VALLEY POWER STATION

ADDRESSp.O. BOX 4

ATTN: DAVID ORNDORF

FACILITY SHIPPINGPORT LOCATION

PA 15077

PERMIT NUMBER DISCHARGE NUMBER **MONITORING PERIOD** YEAR MO DAY YEAR MO DAY 99 UI UB jU FROM

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

PA0025615

DISCHARGE MONITORING REPORT (DMR) (17-79)

103

MAJOR (SUB# 05)

F - FINAL

Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

SLUDGE SETTLING SASIN

\*\*\* NO DISCHARGE |\_\_| \*\*\*

ATTN: DAVID ORRDORF			(20-21)	(22-23) (24-	25) (26-27) (2	8-29) (30-31)	NOTE: Read Instru	ictions befor	e com	oleting this	form.
PARAMETER		(3 Card Only) QUANTITY OR LOADING (46-53) (54-61)			(4 Card Only) (38-45) QUANTITY OR CONCENTRATION (46-53) (54-61)					OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
E H	SAMPLE MEASUREMENT	<b>海岸路路</b> 市	化 松松 作 体 体		804	\$7 \$6 \$3 \$6 \$4 \$5	8.13	( 12)	0	2/30	GRAB
004 <b>00 1</b> 0 0 Effluent gross <b>val</b> ue	PERMIT REQUIREMENT	2000000	tetoba u	ាល់ ភូមិស្ស ក្រុ	6.0 MINIMUK		9.0 MAXIMUN	รย	T	WICE/ MONTH	GRAN
SOLIDS. TOTAL SUSPENDED	SAMPLE MEASUREMENT	<b>非常教育等</b>	क्षेत्र में क्षेत्र के की की		教育學療育學	7.8	10.6	( 19)	0	3/30	
00530 1 0 0 EPFLUENT GROSS VALUE	PERMIT REQUIREMENT	******		特殊的 存款持续	A 63 (A)	MO AVG	77 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	MG/L		MONTH	COMP24
FLOW. IN CONDUIT OR THAU TREATMENT PLANT	SAMPLE MEASUREMENT	r <i>6.00</i> 2	0.003	(-03)	<b>养育体验</b> 软体	京市市市市市 <b>在企業</b>	######################################	Side strain	0	343 C	EST
50050 1 0 0 EFFLUENT GROSS VALUE			ERPORT DAILY HX	MGD	**************************************		7 H.J. (73)	× 4 * * *	•	MONTH	
	SAMPLE MEASUREMEN	Γ									
	PERMIT REQUIREMENT						And the second				
	SAMPLE MEASUREMEN	Г									
	PERMIT REQUIREMENT	22.00			7-12-12-13-13-13-13-13-13-13-13-13-13-13-13-13-	DEN N	1864 (1864) 1867 (1864)			*	2.344
	SAMPLE MEASUREMEN	г									
	PERMIT REQUIREMENT					12.77.00.23	2.5				
	SAMPLE MEASUREMEN	Г									
	PERMIT REQUIREMENT		I AW THAT I HAVE DEDO	ONALLY EXAM	INED AND	Services 32 The Services 32		TELEPHO	NF	Г	)ATE
NAME/TITLE PRINCIPAL EXECUTIVE OFFICER		AMILIAR WITH THE INFORI IRY OF THOSE INDIVIDUAL INFORMATION.   BELIEV	MATION SUBMITTED HER LS IMMEDIATELY RESPO /E THE SUBMITTED IN	EIN; AND BAS NSIBLE FOR C NFORMATION	ED ON MY BETAINING IS TRUE,	XO, 1		12221110	- 1		
David Orndorf Chemistry Manager	ACCU PENA POSS	ITIFY UNDER PENALTY OF AMILIAR WITH THE INFORI IRY OF THOSE INDIVIDUAL INFORMATION, I BELIE! INFATE AND COMPLETE. LITIES FOR SUBMITTIN INFORMATION IMPI SP. (Penalties under these num imprisonment of between IMPRISONMENT INFORMATION	I AM AWARE THAT THE IG FALSE INFORMAT RISONMENT. SEE 18 U.S	TERE ARE SIGN, INCLUD	INIFICANT NG THE 33 U.S.C. SIGNATURE OF PRINCIPAL EXECUTIVE			12 <sub> </sub> 393-			10 25
TYPED OR PRINTED		num imprisonment of betwe	en 6 months and 5 years.)	23 Up 10 \$10,0	OFF	DE NUMB	ER	YEAR	MO DAY		

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone. Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

## **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME BEAVER VALLEY POWER STATION ADDRESSP.O. BOX 4

ATTN: DAVID ORNDORF FACILITY SHIPPINGPORT

LOCATION

PA-15077

MONITORING PERIOD YEAR MO DAY YEAR MO DAY 99 UL FROM

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)
(2-16) (17-19)

PA0025615

PERMIT NUMBER

110 A

DISCHARGE NUMBER

ROLLE (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

UNIT 2 SERVICE WATER BACKWASH

\*\*\* NO DISCHARGE

			(20-21)	(22-23) (24-		28-29) (30-31)	NOTE: Read Instru	uctions befor	e comb	leting this	torm.	
ATTN: DAVID CRADORF PARAMETER		(3 Card Only) QUAN (46-53)	ITITY OR LOADING		-	QUANTITY OR CONC (46-53)	(54-61)			FREQUENCY OF	TY	
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-	·70)
FLOW, IN CONDUIT OR THRU TREATMENT PLANT	SAMPLE MEASUREMENT	REPORT	R#PORT	( 03)	****	化	**************************************	<u> </u>	ją:	EEKLY	£51.	IMA
50050 1 0 0 Effluent Gross value	PERMIT REQUIREMENT	and the second s	DATLY MX	หรอ	77 E		-	****			4	
	SAMPLE MEASUREMENT											
	PERMIT REQUIREMENT	1.00				14 14 14 17 14 17 14 17 18 18 18 18 18 18 18 18 18 18 18 18 18	44. 197				-	
	SAMPLE MEASUREMENT PERMIT						227					
	REQUIREMENT					-					+-	
	SAMPLE MEASUREMENT						10-					
	PERMIT REQUIREMENT				1.2	1 23 50 7T 123 4 <u>1</u>	The second of					
	SAMPLE MEASUREMENT						-					-
	PERMIT REQUIREMENT		7				= =				-	
	SAMPLE MEASUREMENT											
<u> </u>	PERMIT REQUIREMENT				1						+	
	SAMPLE MEASUREMENT											
	PERMIT REQUIREMENT				- AND			TELEPHO	NE	<del>                                     </del>	DATE	
NAME/TITLE PRINCIPAL EXECUTIVE O	FFICER I CER AM FA INQUI THE ACCU	TIFY UNDER PENALTY OF MILLAR WITH THE INFOR RY OF THOSE INDIVIDUAL INFORMATION, I BELIE RATE AND COMPLETE. LTIES FOR SUBMITH BILLITY OF FINE AND IMF9. (Penalties under these aum imprisonment of between the sum imprisonment of between millar information in the sum imprisonment of between impris	FLAW THAT I HAVE PER MATION SUBMITTED HE LLS IMMEDIATELY RESPO VE THE SUBMITTED I AM AWARE THAT I NG FALSE INFORMA	SONALLY EXAI REIN; AND BAS ONSIBLE FOR INFORMATION THERE ARE SI TION. INCLUI	MINICO AND SED ON MY OBTAINING IS TRUE, IGNIFICANT DING THE	Park	, 4	412393-7		99	10	2.5
Chemistry Manager TYPED OR PRINTED	POSS § 131 maxim	IBILITY OF FINE AND IMP 9. (Penalties under these num imprisonment of between	PRISONMENT. SEE 18 U.s statutes may include file een 6 months and 5 years.	S.C. § 1001 AN nes up to \$10, )	D 33 U.S.C. SIGN 000 and or OI	NATURE OF PRINCIPAL FFICER OR AUTHORIZ	EXECUTIVE	REA NUME			МО	DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

# General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

## **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSp.O. BOX 4

ATTN: DAVID ORNDORP

FACILITY SHIPPINGPORT

PA 15077

LOCATION

MONITORING PERIOD YEAR MO DAY YEAR MO DAY 99 VI FROM

PA0025615

**PERMIT NUMBER** 

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR) (17-19)

DISCHARGE NUMBER

MAJOR (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

111 DIESEL GENERATOR BLUG

\*\*\* NO DISCHARGE X \*\*\* NOTE: Read Instructions before completing this form.

ATTN: DAVID ORNDORF			(20-21)	(22-23) (24-2	25) (26-27) (28	8-29) (30-31)	NOTE: Read Inst	ructions before	e comp	neurig uns		
PARAMETER	(3 Card	Only) QUANT (46-53)	TITY OR LOADING (54-61)		(4 Card Only) <b>Q</b> (38-45)	UANTITY OR CONC (46-53)	ENTRATION (54-61)		NO. EX	FREQUENC' OF	SAMF TYP	
(32-37)	AV	/ERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-7	70)
	MPLE **	(数据的数据)	*****			इंट क्षेत्र के के के के		(12)				
00400 1 0 0 PE	RMIT CON	A CONTRACTOR	promise a	क्षेत्र क्षेत्र	5.0	322000	9.0		W	ERKLY	GHAR	
EFFLUENT GROSS VALUE REQUI				<b>企业股份</b>	MINIMUM		MAXIMUM	56			4	
SOLIDS, TOTAL SAI		· 神像學學(	<b>森 华尔特森</b>		\$\$\$\$\$\$\$\$			( 19)				
The state of the s	RMIT P	19904	949000	<b>建筑原</b>	****	30	100		*	EEKLI	<b>PRAD</b>	•
EFFLUENT GROSS VALUE REQUI	REMENT	4.0		****		MD AVC	DAILY MX	33.60			4	
DIL & GREASE SAI	IPLE REMENT	(你你你做你	作 维护 作格 零					(19)				
00556 1 0 0 PE	11711.6	4000	retroc t	1	15	20	30	10 0 / 7	W	EEALY	THAC	5
EFFLUENT GROSS VALUE REQUI	REMENT			ផ្ទុំជាប់	NO AVG	DAILY MA	INST CAN	80808			#=	
THRU TREATMENT PLANT MEASU	MPLE REMENT			( 03)	<b>多数数数数数</b>		24442					
50050 1 0 0 PE	RMIT 5	SPORT	BELLOBI		000000	******	The first age of the first	472.00 W	**	ENKLY	1	
EFFLUENT GROSS VALUE REQUI	REMENT #0	AVG	DATLY MX	MGD				3, 4, 5, 3,	-		4	
MEASL	MPLE REMENT							,				
	RMIT REMENT	7.			# (#)	7.7	34					
	MPLE PREMENT											
	RMIT REMENT					100						
	MPLE PREMENT	·										
	RMIT REMENT				450		44 LEST 199					
NAME/TITLE PRINCIPAL EXECUTIVE OFFICER		/ITH THE INFORM	LAW THAT I HAVE PERS ATION SUBMITTED HER	RFIN: AND BASI	ED ON MY I /			TELEPHO	NE	<del>                                     </del>	DATE	
David Orndorf		IOCE INDIVIDUALIA	S IMMEDIATELY RESPO E THE SUBMITTED IN I AM AWARE THAT TH G FALSE INFORMAT ISONMENT, SEE 18 U.S	NGIBLE FOR ()	HIAINING I I	Hande	1		1.EA	00	10	25
Chemistry Manager	PENALTIES FO	F FINE AND IMPR	ISONMENT, SEE 18 U.S	.C. § 1001 AND	33 U.S.C. SIGNA	ATURE OF PRINCIPAL	EXECUTIVE	412393-7		99		25
TYPED OR PRINTED	9 1319. (Penalti maximum impris	ies under triese s conment of betwee	statutes may include fine on 6 months and 5 years.)	20 up 10 \$10,0	OFF	FICER OR AUTHORIZE	DAGENT	AREA NUMBI	ER	YEAR	MO I	DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC:20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

## **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME BEAVER VALLEY POWER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNDORF

FACILITY SHIPPINGPORT

LOCATION

PA 15077

MONITORING PERIOD DAY YEAR MO DAY YEAR MO O.L **FROM** TO

PA0025615

**PERMIT NUMBER** 

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)
(2-16) (17-19)

DISCHARGE NUMBER

ROLAM (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

\*\*\* NO DISCHARGE | 1 \*\*\*

UNIT 2 SEWAGE THT PLANT

NOTE: Read Instructions before completing this form.

· · · · · · · · · · · · · · · · · · ·	MPLE UREMENT	(3 Card Only) QUAN (46-53) AVERAGE	(54-61) MAXIMUM		(4 Card Only) Q (38-45)	UANTITY OR CONC (46-53)	CENTRATION (54-61)	:	NO. EX	FREQUENCY OF	SAMPLE TYPE
(32-37)			MAXIMUM								– .
		ياك والو وكو والو بالدوار		UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
[ MEAS		1	<b>森 教授 陈 森 森</b>			<b>黎泰森安泰</b> 泰	7.80	( 12)	ं	9/30	GRAB
00400 1 0 0 PR BFFLUENT GROSS VALUE HEQL	ERMIT IREMENT	******	\$\$\$\$\$\$ B	数数数 数数数数	MINIMUM	000000	9.0 Maximum	5 U	Ι	MONIH	F.Ab
SOLIDS. TOTAL S	MPLE UREMENT	安全的中央中	数式的数像数		होंक बीट ग्रीट ग्रीट ग्रीट ग्रीट	15	16.3	( 19)	U	2/30	Cemp
00530 1 0 6 P	ERMIT IREMENT	44004		ជ្រុក ក្នុក្	**************************************	HO AVG		eG/l	200000000000000000000000000000000000000	MONTH	COMP - 8
	MPLE UREMENT	6.003	0.006	( 03)	<b>作作作作作</b> 作	<b>作物联络</b> 体格	<b>化香花丝胶料</b>	tar a	0	17/20	MIZAS
EPFLUENT GROSS VALUE REQU	ERMIT IREMENT	0.043 80 276	REFORT DALLY MX	mGD_				( 19)	*		194
RESIDUAL MEAS	MPLE UREMENT		a social di	4.4.4	to the state of the	0.51	0.97			13/30	GRAS
EFFLUENT GROSS VALUE REQU	,	· 政策的特殊的 · 放弃的条件		****	****	NO AVG	INST KAX	MG/L ( 13)		MONTH	
SERERAL MEAS	AMPLE UREMENT ERMIT		problem b	<b>建筑</b> 农	****	2002	adama s	[ /	္ •	MICE/	GARP
EFFLUENT GROSS VALUE REQU	EHMLI JIREMENT AMPLE		क्षा क्षाप्त की के के	(1) (1) (1) (1)	****	TO GROWA	*42	100ML ( 19)		MONTH	
05 DAY, 200 MEAS	UREMENT ERMIT	r Proposite	erecto v	्र इंट इंट इंट	nature.	'	50 50		ा		COMB-6
EFFLUENT GROSS VALUE REQ	JIREMENT			4004		NO AVG	DAILY BX	NG/L		MONTH	
	UREMENT ERMIT JIREMENT										150
NAME/TITLE PRINCIPAL EXECUTIVE OFFICER	LCER	TIFY LINDER PENALTY OF	LAW THAT I HAVE PERS	SONALLY EXAM	IINED AND			TELEPHO	NE	D	ATE
David Orndorf	INQU THE ACCU PENA POSS § 131	AMILIAR WITH THE INFORM IRY OF THOSE INDIVIDUAL INFORMATION, I BELIEV PRATE AND COMPLETE. TO SUBMITTIN SIBILITY OF FINE AND IMPERS. (Penalties under these unum imprisonment of between	S IMMEDIATELY RESPO E THE SUBMITTED IN I AM AWARE THAT TH G FALSE INFORMAT RISONMENT. SEE 18 U.S Statutes may Include fine	ONSIBLE FOR C NFORMATION HERE ARE SIG TON, INCLUD I.C. § 1001 AND 68 up to \$10,0	DBTAINING IS TRUE, GNIFICANT ING THE D 33 U.S.C. SIGN/	ATURE OF PRINCIPAL FICER OR AUTHORIZI	EXECUTIVE AN	1,21393-7		YEAR I	10 25 MÔ DẤY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSp. D. 80% 4

ATTN: DAVID ORNDORF

FACILITY SHIPPINGPORT

PA 15077

LOCATION

MONITORING PERIOD YEAR MO YEAR МО DAY DAY 61 30 FROM (28-29) (30-31) (26-27)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)
(17-19)

DISCHARGE NUMBER

PA0025615

PERMIT NUMBER

MAJOR (SUBR 05)

F - FINAL

Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

201 SOFTENER REGENERANTS

\*\*\* NO DISCHARGE

NOTE: Read Instructions before completing this form.

ATTN: DAVID ORNDORF			(20-21)	(22-23) (24-2	25) (26-27) (2	28-29) (30-31)	NOTE: Read Instit	ICTIONS DEION	e comp	noung uno	
PARAMETER		(3 Card Only) QUAN (46-53)	TITY OR LOADING (54-61)		(4 Card Only) Q (38-45)	UANTITY OR CONC (46-53)	CENTRATION (54-61)		Z Š	FREQUENCY OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
p y	SAMPLE MEASUREMENT	<b>企业市市市</b>	<b>使 经收收收收</b>			*********		( 12)			
00400 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	popular.	commiss S	存款法 存款证券	NIMIMUM		MAXINIM O.C	នប		WICE/ MONTH	RAB
SOLIDS, TOTAL SUSPENDED	SAMPLE MEASUREMENT	<b>我你你你你你</b>	<b>作 中华华华华</b>		के हुट के यह है। है			( 13)			
00530 1 0 0 Eptuent gross value	PERMIT REQUIREMENT	ayeock		ទី៩ជ ជូចក្នុ	*****	DVA CH	DAILY 5X	***	100000000000000000000000000000000000000	MICE/ MONTH	PRAD
DIL S GREASE	SAMPLE MEASUREMENT	非非非常特殊的	*****		*****	* -		( 19)	//	WICE/	
00556 1 0 0 EFFLUENT GROSS VALUE	PERMIT REQUIREMENT	puphan	<b>外在我们的作品</b>	がかな なななな マンスト	*****	NO AVG	DAILY MX	mG/L		MONIH	
FLOW, IN CONDUIT OR THRU TREATMENT PLANT				( 03)	<b>安存在</b> 存在 (1)	Fig. 4.2. Apr. 1/2. A.S. Fae		Tana Tana	-	7	
SOOSO 1 0 0 OFFLUENT GROSS VALUE	PERMIT REQUIREMENT	REPORT NO AVE	REPORT DATLY MX	MGD			Sept.	****		MONTH	
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT				127117	7 (200)	(00p) (00p)				-
	SAMPLE MEASUREMENT										-
	PERMIT REQUIREMENT				2.02						
	SAMPLE MEASUREMENT										
NAME/TITLE PRINCIPAL EXECUTIVE O	PERMIT REQUIREMENT	IFY UNDER PENALTY OF	LAW THAT I HAVE PERS	ONALLY EXAM	INED AND	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		TELEPHO	NE	ם	ATE
NAME/IIILE PHINCIPAL EXECUTIVE C	AM FAI INQUIF THE I	MILIAR WITH THE INFORM BY OF THOSE INDIVIDUAL NEORMATION, I BELIEV	MATION SUBMITTED HER S IMMEDIATELY RESPO E THE SUBMITTED IN	EIN; AND BASI NSIBLE FOR O NFORMATION	ED ON MY BTAINING IS TRUE,	AD) L	2JL				
David Orndorf Chemistry Manager	ACCUF PENAL POSSI § 1319	IFY UNDER PENALTY OF- MILIAR WITH THE INFORM BY OF THOSE INDIVIDUAL NORMATION, I BELIEV BATE AND COMPLETE. TIES FOR SUBMITTIN BILITY OF FINE AND IMPF I. (Penalties under these um Imprisonment of between	I AM AWARE THAT THE G FALSE INFORMATI ISONMENT. SEE 18 U.S. statutes may include fine	HERE ARE SIG ION, INCLUDI I.C. § 1001 AND ISS UP to \$10,0	ING THE 33 U.S.C. OO and or	ATURE OF PRINCIPAL FICER OR AUTHORIZE		12 393-7			10 25 MO DAY
TYPED OR PRINTED	meximu	ım imprisonment of betwee	on to months and 5 years.)				I CC	DE LINOINIDI	-11	112711	DAI

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

BEAVER VALLEY FOWER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNDORF

FACILITY SHIPPINGPORT

PA 15077

LOCATION

**MONITORING PERIOD** YEAR DAY YEAR MO DAY MO 99 30 **FROM** 0.1 (26-27) (28-29) (20-21) (22-23) (24-25) (30-31)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR) (17-19)

203 A

DISCHARGE NUMBER

PA0025615

PERMIT NUMBER

MAJOR (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

MAIN SEWAGE THT PLANT

\*\*\* NO DISCHARGE |\_\_ | \*\*\*

PARAMETER		(3 Card Only) QUAN (46-53)	TITY OR LOADING (54-61)		(4 Card Only) Q (38-45)	UANTITY OR CON (46-53)	CENTRATION (54-61)		NO.	FREQUENCY OF	SAMPL TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70
	SAMPLE MEASUREMENT	非旅游旅游旅游	<b>在中的市场中</b>		6,49	<b>教教教教教教</b>	7,31	( 12)	0	2/30	GRAI
0400 1 0 0	PERMIT:	7.44.24.24	26.000m 9	*** *****	5.0 MINIMUM	040409	MAXINUm	នប	1	KICE/ MONTH	
FLUENT CHOSS VALUE	SAMPLE	क्षा अंक्ष ग्रेड होंड होंड होंड	ক কক কৰে ক		****	16		(19)		2/30	Com
530 1 0 0	MEASUREMENT PERMIT	on unon	nempes o	ទីស៊ីជុំ ឃុំស្សាស្	****	1 (a. (c. 30 40 AVC	60 DAILY MX	BG/L	,		. 0.00
FLUENT GROSS VALUE	SAMPLE	0.005		( 03)	<b>建筑设设设</b>	########	***********	1767 &	6	1/7	MEA
0050 1 0 0		0.023	OLOGO FERORE ORIGE NA	MGD	******	\$\$\$\$n6	400000		*	EEKLY	
FILUENT GROSS VALUE	SAMPLE MEASUREMENT	80 AVC	6 444 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	n 0 0	मुंद बहुत होत होत महेत महेत होत	0.74	0.7.8	(19)	0	3/20	GRAI
RSIDUAL 1960 1 0 1 PFLUENT GROSS VALUE	PERMIT	7777	pencer p	杂杂格 杂杂杂称	\$\$\$\$\$\$	no AVS	INST MAX	MG/L	7	WICE/ MONTH	HAS
DLIFORM, FECAL	SAMPLE MEASUREMENT	****	. <b>\$</b> 400 00 00 0		***		****	( 13)	0	4/20	GRAG
1055 1 0 0 Privent Gross Value	PERMIT	0.0000 V	ABANABA A	arieni ipopolarie	\$ \$45 \$ \$450 \$ \$25 \$ \$160 \$ \$25	MO GEOMN		100%L	1	WICE/ MONTH	14.0
DD. CARBONACEOUS	SAMPLE MEASUREMENT	<b>安安市</b> 安全市	के संस्कृति के के		存在水本水水	1, 2,	4.5	(19)	0	3/30	(Cm
7082 1 0 0 FFLOENT GROSS VALUE	PERMIT	projektok	henana e	000 0000	**************************************	25 NO AVG	SO DAILY MX	MG/L	1	WICE/ MOSTH	
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT					142.1	44.44				
NAME/TITLE PRINCIPAL EXECUTIVE OF	FICER I CERTI	FY UNDER PENALTY OF MILIAR WITH THE INFORM Y OF THOSE INDIVIDUAL	LAW THAT I HAVE PERS MATION SUBMITTED HER S IMMEDIATELY RESPO	ONALLY EXAM EIN; AND BAS NSIBLE FOR O	INED AND ED ON MY BTAINING	100		TELEPHO	NE	D.	ATE
David Orndorf Chemistry Manager TYPED OR PRINTED	THE IN ACCUR	IT ONDER THE INFORM ILLAR WITH THE INFORM Y OF THOSE INDIVIDUAL VEORMATION, I BELIEV IATE AND COMPLETE. TIES FOR SUBMITTIN	E THE SUBMITTED IN I AM AWARE THAT TH G FALSE INFORMATI IISONMENT. SEE 18 U.S.	IFORMATION IERE ARE SIG ON, INCLUD	ING THE TOTAL	TURE OF PRINCIPAL		1 2 1 9 3 - 74		99	10 2

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSp.O. BOX 4

ATTN: DAVID ORNDORF

SHIPPINGPORT

LOCATION

PA 15077

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)
(2-16)

PAC025615 PERMIT NUMBER DISCHARGE NUMBER

MAJOR (SUBE 05) F - FINAL 211 TURBINE BLOG Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

**MONITORING PERIOD** YEAR MO DAY YEAR MO DAY FROM OT (26.27) (28.20) (20.21) (24-25)

\*\* NO DISCHARGE |\_ | \*\*\*

PARAMETER		(3 Card Only) QUAN (46-53)	TITY OR LOADING (54-61)		(4 Card Only) Q (38-45)	UANTITY OR CONC (46-53)	CENTRATION (54-61)		NO. EX	FREQUENCY OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
) <u> </u>	SAMPLE MEASUREMENT	भूत और ती भी भी भी	京 於於於 於 錄 錄		6.78	और योग और योग की योग	7.04	( 12)	0	1/7	GRA
0400 1 0 0 FFLUERT GROSS VALUE	PERMIT REQUIREMENT	aantet.		្ ស្ត្រូវ ស្ត្រូវ	6.0 MINIMUM		9.0 Maximum	50	la)	EEKLY	HAS
OLIDS, TOTAL USPENDED	SAMPLE MEASUREMENT	<b>安全市市市</b>	is this is is in		****	44	44	(19)	0	1/7	GRA
0536 1 6 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	_#### <b>#</b>		ស្ត្រ ស្ត្រស្	7. 00 P P C	MO AVG	DAILY MX		¥	EERLY	BAB
IL 8 GREASE	SAMPLE MEASUREMENT	海海野物學介	<b>\$1</b> 表的 \$1 \$2 \$2		45	くぢ	<b>45</b>	(19)	Ç	1/7	GRAL
0556 1 0 0 FFLUENT GROSS VALUE	PERMIT: REQUIREMENT	000000	compa	ទូ ទុំ ទុំ ទុំ	MO NAC	DALLY MX	30 INST MAX	86/L	¥	BEKLY!	HAB
LOW, IN CONDUIT OR BRU TREATMENT PLANT	SAMPLE MEASUREMENT	0.00%	0.00%	( 03)	के के के के के के के	<b>经验收货款</b>	<b>安徽</b> 黎森安徽		0	1/7	EST
50050 1 0 0 PPLOENT GROSS VALUE	PERMIT REQUIREMENT	REPORT do AVG	REPORT DATLY MX	MGD	(.ana.)		netween	******	4	ERRLY	5111
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT						12 (A SAN BERT 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT				ARREST S						
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT				NES AND					_	
NAME/TITLE PRINCIPAL EXECUTIVE O	DFFICER I CERT AM FAI INQUIP THE II ACCUI	IFY UNDER PENALTY OF MILIAR WITH THE INFORMATY OF THOSE INDIVIDUAL NFORMATION, I BELIEV RATE AND COMPLETE. TIES FOR SUBMITTIN. BILITY OF FINE AND IMPROVED IN INFORMATION OF THE BANGER OF THESS.	LAW THAT THAVE PERSI ATION SUBMITTED HER SIMMEDIATELY RESPOI E THE SUBMITTED IN I AM AWARE THAT TH	ONALLY EXAM EIN; AND BASE NSIBLE FOR O FORMATION IERE ARE SIG	INED AND BTAINING IS TRUE, INIFICANT	Pando		TELEPHO	NE	D/	ATE
Chemistry Manager TYPED OR PRINTED	PENAL POSSII \$ 1319	TIES FOR SUBMITTING BILITY OF FINE AND IMPR ). (Penalties under these : um imprisonment of betwee	G FALSE INFORMATION  SONMENT. SEE 18 U.S.  Statutes may include fine  on 6 months and 5 years.)	ON, INCLUDI C.§ 1001 AND S up to \$10,00	33 U.S.C. 00 and or OFF	TURE OF PRINCIPAL ICER OR AUTHORIZE	EXECUTIVE 4 D AGENT	1.2   393-7 REA   NUMBI	7459 FR	99 YEAR M	10 DA

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

## **Legal Notice**

SEAVER VALLEY POWER STATION

ADDRESSp.O. BOX 4

ATTR: DAVID ORNDORF

PA 15077

FACILITY SHIPPINGPORT LOCATION

**PERMIT NUMBER MONITORING PERIOD** YEAR МО YEAR DAY

09

ग्र

PA0025615

FROM

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR) (17-19) 213 A DISCHARGE NUMBER

DAY

30

МО

99

TO

MAJOR (SUBR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

UNIT 2 COOL TOWER PUMPHOUSE

\*\*\* NO DISCHARGE

PARAMETER		(3 Card Only) QUAN (46-53)	ITITY OR LOADING (54-61)		(4 Card Only) Q (38-45)	UANTITY OR CONC (46-53)	CENTRATION (54-61)		NO. EX	FREQUENCY OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
H	SAMPLE MEASUREMENT	旅游旅旅旅店	****			<b>有效的存储的</b>		( 12)			
0400 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	044000	********	**** ****	MININUM 0.0	*****	9.C MAXIMUM	s ü		WICE/O	RAB
OLIDS. TOTAL USPENDED	SAMPLE MEASUREMENT	<b>海海市市市市</b>	री कोही के के हैं		<b>海斯尔特拉伯</b>			( 19)			
0530 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	4 ganta		存存存 存存存存	**************************************	NO AVG	DAXLY HI	0.000,00		WICE/C	HAU
· · · · · · · · · · · · · · · · · · ·	SAMPLE MEASUREMENT		# 2020 # \$ C		<b>在在现在设</b> 存			( 19)			
0556 1 0 0 FFLUENT GROSS VALUE				igraja iga iga	*****	KO AYG	DAI <u>LY</u> MA	100000		WICE/O	RAE
LOW, IN CONDUIT OR ARU TREATMENT PLANT				( 03)	**************************************		******	.*		F.E.N.L.1	# . M
00050 1 0 0 PFLUFNT GROSS VALUE		HEPORT NO AVG	TROOPE XM YITAG	MGD			100010000	te de te de		<i></i>	
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT SAMPLE	Ŧ.,			5-54 (6.11)	12-20 Cashiri	i i i				
	MEASUREMENT PERMIT										
	REQUIREMENT SAMPLE										***
	MEASUREMENT PERMIT				100	=					
NAME/TITLE PRINCIPAL EXECUTIVE OF	REQUIREMENT	IFY UNDER PENALTY OF	LAW THAT I HAVE PERSO	DNALLY EXAM	NED AND		/ 1	TELEPHON	1Ε	DA	TE.
David Orndorf	INQUIF THE II ACCUF PENAL	IFY UNDER PENALTY OF MILIAR WITH THE INFORM BY OF THOSE INDIVIDUAL NFORMATION, I BELIEV BATE AND COMPLETE. TIES FOR SUBMITTIN BILLITY OF FINE AND IMPROPRIEM OF THE BURN BURN BURN BURN BURN BURN BURN BURN	IATION SUBMITTED HEHI S IMMEDIATELY RESPON E THE SUBMITTED IN I AM AWARE THAT TH G FALSE INFORMATION	EIN; AND BASE SIBLE FOR OI FORMATION I ERE ARE SIG ON, INCLUDI	BTAINING BTAINING IS TRUE, NIFICANT NG THE	Ruse		10 202 7	/ F.O.	00 3	25
Chemistry Manager TYPED OR PRINTED	POSSII § 1319	BILITY OF FINE AND IMPR  . (Penalties under these s	ISONMENT. SEE 18 U.S. Statutes may include fine	C. § 1001 AND s up to \$10,00	33 U.S.C. SIGNA	TURE OF PRINCIPAL ICER OR AUTHORIZE		12 393-74			0 25 O DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSP . O. BOX 4

ATTR: DAVID ORRDORF

FACILITY SHIPPINGPORT

PA 15077

LOCATION

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)
(2-16)

PAG025615 **PERMIT NUMBER** 

YEAR

DISCHARGE NUMBER

MAJOR (SUBR 05) F + FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

UNIT 2 AUX BOILER BLOWDOWN MONITORING PERIOD DAY YEAR MO DAY

\*\*\* NO DISCHARGE A\*\*

FROM 01 99 30 NOTE: Read Instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) appus hiern negange

МО

PARAMETER (6-53)  AVERAGE (6-5	TTN: DAVID ORNBORF				(22-23) (24-2		28-29) (30-31)	NOTE: Read IIIsu	actions belo			
SAMPLE MASHREMIT SERMIT SAMPLE MASHREMIT SERMIT SAMPLE MASHREMIT SAMPLE MASHREMIT SERMIT SAMPLE MASHREMIT SERMIT SER							QUANTITY OR CON				OF	SAMPLE TYPE
USPENDED MASSIRMENT PERMIT SAMPLE MASSIRMENT SAM	(32-37)				UNITS		AVERAGE	MAXIMUM		(62-63)		(69-70)
PERMIT REQUIREMENT CONSTRUCT CONTROL C		SAMPLE	<b>经</b> 数数据数据	教教教教學協		<b>建筑旅游旅游</b>			( 19)			
PRICENT GROSS VALUE RECORDENENT  DESCRIPTION OF THE CONTROL OF THE					చింది చ	2000000000	3 8			1	WICE/	G W A IS
SAMPLE RESUREMENT PERMIT REQUIREMENT SAMPLE REQUIREMENT SAMPLE REQUIREMENT REQ							MO AVG		MG/L			
PFFLUENT GROSS VALUE REQUIREMENT  LOW, IN COMPUTE OR SAMPLE (C3) CONTROL OF SAMPLE (C3) CON		SAMPLE	र्श्वत्यक्ष्म ग्रीड होते होते होते होते	*****		\$ \$ 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5			(19)			
LOW. IN CONDUIT OR SAMPLE HEADT TO BE SAMPLE HEADT TO BE SAMPLE HEADT TO BE SAMPLE HEADT TO AVG DAILY MOD TO AVG DAILY NOD TO			000000	<u>ក្នុងស្ថិសិ ម</u> ្	i	100 miles			MG/L	1	and the second second second	GRAU
PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  PERMIT REQUIREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT	LOW, IN COMPUTT OR	SAMPLE			( 03)	<b>维拉尔萨桑格尔</b>		*****				
MEASUREMENT PERMIT REQUIREMENT  SAMPLE MEASUREMENT PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  PERMIT REQUIREMENT	00050 1 0 0	PERMIT	AEPORT		MGÐ	14 10 24 1	000000	####### ## ***		ů.	EEKLY	STIM
REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  PERMIT REQUIREMENT  PERMIT REQUIREMENT  PERMIT REQUIREMENT												
MEASUREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  REQUIREMENT  PERMIT REQUIREMENT			1930 B. T.					200 mag				
REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT  SAMPLE MEASUREMENT  PERMIT REQUIREMENT				-							·	
MEASUREMENT PERMIT REQUIREMENT  SAMPLE MEASUREMENT PERMIT REQUIREMENT			2.1									i.a.
SAMPLE MEASUREMENT  PERMIT REQUIREMENT												
MEASUREMENT PERMIT REQUIREMENT							2 - 3 (Egyp - 1) - 4 (					1985
REQUIREMENT												
NAME/TITLE PRINCIPAL EXECUTIVE OFFICER  I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. § 1001 AND 33 U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 and or OFFICER OR AUTHORIZED AGENT.  AREA ANIMADED. VEAR. MO							0.0002E-15-12-12E-15-12					
David Orndorf  Chemistry Hanager  The information, I believe the Submitted information is true, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBmitting FALSE INFORMATION, INCLUDING THE PENALTIES FOR SUBmitting FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. § 1001 AND 33 U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 and or OFFICER OR AUTHORIZED AGENT.  AREA AND ADDRESS MADE TO THOSE INDIVIDUALS IMMEDIATELY REPONSIBLE FOR SUBMITTING TO STATE OF PRINCIPAL EXECUTIVE SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT.	NAME/TITLE PRINCIPAL EXECUTIVE O	FFICER I CERT	IFY UNDER PENALTY OF MILIAR WITH THE INFORM	LAW THAT I HAVE PERS	ONALLY EXAMI	NED AND D ON MY	10		TELEPHO	NE	D	ATE
\$ 1319. (Penalties under these statutes may Include fines up to \$10,000 and or OFFICER OF AUTHORIZED AGENT AREA NUMBER WEAR MO	<del>-</del>	INQUIF THE II ACCUF PENAL POSSII	RY OF THOSE INDIVIDUAL NFORMATION, I BELIEV RATE AND COMPLETE. TIES FOR SUBMITTIN BILITY OF FINE AND IMPE	SIMMEDIATELY RESPON E THE SUBMITTED IN I AM AWARE THAT TH G FALSE INFORMATI SONMENT, SEE 18 U.S.	NSIBLE FOR OI IFORMATION I IERE ARE SIG ON, INCLUDII C. \$ 1001 AND	S TRUE, NIFICANT NG THE 33 U.S.C.	XUUDA	EVECUTIVE 4	12 ,393-7	459	99 1	D 254
TYPED OR PHINTED   meximum imprisonment of between 6 months and 5 years.)	TYPED OR PRINTED	§ 1319 meximu	. (Penalties under these um imprisonment of between	statutes may include fine on 6 months and 5 years.)	s up to \$10,00	o and or OFF	FICER OR AUTHORIZE	D AGENT A	NUMBI	ER	YEAR I	MO DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

# General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSO . Q. BOX 4

ATTN: DAVID ORNDORF

FACILITY SHIPPINGPORT

LOCATION

PA 15077

		N	OTINON	RING	PERIO	)	
	YEAR	МО	DAY		YEAR	МО	DAY
FROM	99	9.3	71	то	34	09	30
	(20-21)	(22-23)	(24-25)		(26-27)	(28-29)	(30-31)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)

PA0025615

PERMIT NUMBER

303 A

DISCHARGE NUMBER

Form Approved. OMB No. 2040-0004 MAJOR Approval expires 05-31-98

(SUBR 05) F - FINAL

UNIT 1 OIL WATER SEPARATOR

\*\*\* NO DISCHARGE | \_ | \*\*\*

PARAMETER		(3 Card Only) QUAN (46-53)	TITY OR LOADING (54-61)		(4 Card Only) Q (38-45)	UANTITY OR CONC (46-53)	CENTRATION (54-61)		NO.	FREQUENCY OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
H	SAMPLE MEASUREMENT	<b>非非抗性的</b>	作 中华 作 東 東		7.67	विश्वीतक श्रीर प्रश्निक स्थापिक	8.19_	( 12)	0	1/7	GRA
OMCO 1 C O FFLUENT GROSS VALUE	PERMIT REQUIREMENT	000000	\$\$\$\$\$\$ \$	ជាទាប ជាទាជ្	6.0 MINIMUM	CONCAD.	MAXIMUM 9.0	SU	ļ	EEKLY	FAB
OLIDS. TOTAL	SAMPLE MEASUREMENT	भूक भूक और ग्रीप ग्रीप ग्रीप	<b>黎 漆魚 李 森 肇</b>		भूँच भूद्रिव भूँच प्रदेश गर्देश होत	4.9 B	6.9	( 19)	0	1/7	GRAG
0530 1 0 0 PFLUENT GROSS VALUE	PERMIT REQUIREMENT	110111111		\$\$\$ \$\$\$\$		RO AVG	DAILY MX	100	h	BEKLY	SNAB
IL & GREASE	SAMPLE MEASUREMENT	*****	យ្យុះជាល្បាល់ ជា		****	5,3	6.9	( 19)	0	1/7	GRAD
0556 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT		000000	经存货的		no ave	20 DAILY MX	mG/L	ķ	EEKLY	JRAB
LOW, IN CONDUIT OR HRU THEATMENT PLANT	SAMPLE MEASUREMENT	6.019	0,056	( 03)	****	ស្ដែលជាធិប់ល	444444		0	1/7	EST
0050 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	NEPORT MO AVE	REPORT DATES MX	ឌGD			500000 L	****	¥	EERLY	ESTIN
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT			<u> </u>							
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT						100 Table 1 1995				
NAME/TITLE PRINCIPAL EXECUTIVE OF		FY UNDER PENALTY OF MILIAR WITH THE INFORM Y OF THOSE INDIVIDUAL				A		TELEPHO	NE	I D	ATE
David Orndorf Chemistry Manager	THE IN ACCUR	NFORMATION, I BELIEV ATE AND COMPLETE. FIES FOR SUBMITTIN BILITY OF FINE AND IMPR	IATION SUBMITTED HER S IMMEDIATELY RESPON E THE SUBMITTED IN I AM AWARE THAT TH ISONMENT. SEE 18 U.S. statutes may include fine in 6 months and 5 years.)	FORMATION HERE ARE SIG ON, INCLUDI C. § 1001 AND	IS TRUE, NIFICANT NG THE 33 U.S.C.	TURE OF PRINCIPAL	EXECUTIVE (A)	2 (393-7	450	99 1	10 2

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," " Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSp.O. BOX 4

ATTN: DAVID ORNDORF

FACILITY SHIPPIEGPORT

LOCATION

PA 15077

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR) (17-19)

P#0025615 **PERMIT NUMBER** 

313 a DISCHARGE NUMBER MAJOR (SUSH 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

**MONITORING PERIOD** YEAR MO YEAR MO DAY DAY 99 99 ÚУ 30 FROM UL TO (26-27) (28-29) (30-31) (20-21) (22-23) (24-25)

\*\*\* NO DISCHARGE | \*\*\*

313 TURBINE BLOG DRAIN

ATTN: DAVID ORNDORF		1 (2 Court Out) OHAN	(20-21) ITITY OR LOADING	(22-23) (24-		28-29) (30-31) QUANTITY OR CONC	NOTE: Read Instru	ictions befor		FREQUENCY	
PARAMETER		(46-53)	(54-61)		(4 Card Only) (38-45)	(46-53)	(54-61)		EX	OF	TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
Н	SAMPLE MEASUREMENT	<b>超级的物物物</b>	<b>能 松松 格 俊</b> 俊		7.00	<b>安徽市政策</b>	7.35	( 12)	٥	1/7	C. RA.
0400 1 0 C FFLUENT GROSS VALUE	PERMIT REQUIREMENT	******	perce o	ទីទីទី ទូសិទីទី	6.0 MINIMUM		9.0 Maximum	នប	id	EEKLY	RAO
OLIDS, TOTAL USPENDED	SAMPLE MEASUREMENT	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	क्षेत्र श्रीवर्षेत्र की व्यक्त प्रेर		सीव सीव भीव जीव सीच भीव	4:3-	1.8 -5.+ 80)	( 19)	ं	1/7	GRA
0530 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	5 W O O O	1000000	存存的 存存存款	44004A	MO AVG	DAILY DX	MG/L	М	EEKLY	RAB
IL & GREASE	SAMPLE MEASUREMENT		\$ \$\$\$ \$\$\$		********	5.0	5.1	( 19)	Ö	1/7	GRAI
0556 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	004466	proces o	रिकेट क्षेत्रक	******	ND AVG	20 DAILY MX	76/L	ä	EEKLY(	RAB
LOW, IN CONDUIT OR HOU TREATMENT PLAN			0.00%	( 03)	<b>多分数分类数</b>	***	<b>李林林徐安</b> 俊		0	1/7	5 ST
OCSO 1 O O FFLUENT GROSS VALU	PERMIT REQUIREMENT	MO AVG	REPORT DATLY MX	ngd				******	W	EEKLY!	.511
	SAMPLE MEASUREMENT										
·	PERMIT REQUIREMENT						51.30 (57.8)				
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT					15 - 15 - 15 - 15 - 15 - 15 - 15 - 15 -					
	SAMPLE MEASUREMENT	-									
	PERMIT REQUIREMENT					HATHICA					
NAME/TITLE PRINCIPAL EXECUTIVE	OFFICER I CERT AM FA INQUI THE	IFY UNDER PENALTY OF MILLAR WITH THE INFORM RY OF THOSE INDIVIDUAL INFORMATION, I BELIEV RATE AND COMPLETE. TIES FOR SUBMITTIN BILITY OF FINE AND IMPERIOR OF THESE OF THE OF THESE OF THE OF THESE OF THE OF THESE OF THE O	LAW THAT I HAVE PERSI IATION SUBMITTED HER S IMMEDIATELY RESPOI É THE SUBMITTED IN	ONALLY EXAM EIN; AND BASI NSIBLE FOR O IFORMATION	INED AND ED ON MY BTAINING IS TRUE,	10:1		TELEPHO	VE	DA	TE
David Orndorf Chemistry Hanager	ACCUI PENAL POSSI \$ 1310	RATE AND COMPLETE.  TIES FOR SUBMITTIN BILITY OF FINE AND IMPE	I AM AWARE THAT TH G FALSE INFORMATION ISONMENT. SEE 18 U.S. Statutes may include fine	IERE ARE SIG ON, INCLUDI C. § 1001 AND	INIFICANT ING THE 33 U.S.C. SIGNA	ATURE OF PRINCIPAL	EXECUTIVE 4	2 <sub> </sub> 393-7		<del></del>	10 2
TYPED OR PRINTED	maxim	uni imprisoriment or betwee	ii o montro ana o yours.)		OFI	FICER OR AUTHORIZE	D AGENT AR	EA NUMBE	R	YEAR M	IO DA

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

#### **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSO. O. SOX 4

ATTN: DAVID OREDORF.

FACILITY SHIPPINGPORT

PA-15077

LOCATION

**MONITORING PERIOD** YEAR MO МО DAY YEAR DAY 09 **FROM** 99 UI 99 30 (20-21) (22-23) (26-27) (28-29) (30-31)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR) (2-16)

PA0025615 PERMIT NUMBER 401

DISCHARGE NUMBER

MAJOR (SUBR 05) P - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

CHEM. PEED AREA OF AUX BOILBRS

\*\*\* NO DISCHARGE 🔀 \*\*\*

NOTE: Read Instructions before completing this form.

TIN: DAVID ORNDORF				(22-23) (24-		· · · · · · · · · · · · · · · · · · ·	NOTE: Read Instru	ıctions befoi			
PARAMETER		(3 Card Only) QUAN (46-53)	ITITY OR LOADING (54-61)		(4 Card Only) Q (38-45)	UANTITY OR CONC (46-53)	CENTRATION (54-61)		NO.	FREQUENCY OF	SAMPL TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
· H	SAMPLE MEASUREMENT	# # # # # # #	15 25 25 25 25 25 25 25 25 25 25 25 25 25			作政権市政策		( 12)			
0490 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	14.45 14.41		erio Propre	MINIMUM C.O		MEPORT MAXINUM	្ ទីមី	1	WICZ/O	RAB
OLIDS, TOTAL USPENDED	SAMPLE MEASUREMENT	存在物质中的	<b>你 你你你你</b> 你		भूष क्षेत्र मृह मृह प्रदेश होते होते			( 19)			
0530 1 0 6 FFLUENT GROSS VALUE	PERMIT REQUIREMENT		6000000 1000000000000000000000000000000	\$\$\$\$ \$*\$\$\$\$		HOLAYS	DAIFA NX	MC/I	0.000.000.000.000	WICE/U	,KAS
IL & GREASE	SAMPLE MEASUREMENT	- 海森林春春春	ក្រុមស្តេច ប្រែក្		<b>\$\$\$\$\$</b> \$\$\$\$	:		( 19)			
0556 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	**************************************	atorya a	建筑铁铁	<b>DBND</b> \$2	to AVG	20 DAILY MX	AC/L		WICE/O	KAB
LOW, IN COMBUIT OR HRU TREATMENT PLANT	SAMPLE MEASUREMENT			( 33)	<b>探探探察探货</b>	<b>建筑设建筑等</b>	<b>经存在存货</b> 等	Sala straste			
0050 1 0 0 FFLUERT GROSS Value	PERMIT REQUIREMENT	REPORT MO AVG	DATTY HX	MGD	*******		**************************************	<b>建筑效益</b>	*	EEKLY.	311
	SAMPLE MEASUREMENT		·							-	
·	PERMIT REQUIREMENT					The Asset Services	2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -				17.79
	SAMPLE MEASUREMENT	•		,							
	PERMIT REQUIREMENT	2. 11170.41			2.27		PROFES AND ADDRESS OF THE PARTY				
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT				T.					_	
David Orndorf	OFFICER I CERT AM FA INQUIF THE I ACCUI PENAL	IIFY UNDER PENALTY OF MILLAR WITH THE INFORM RY OF THOSE INDIVIDUAL INFORMATION, I BELIEV RATE AND COMPLETE. TIES FOR SUBMITTIN BILITY OF FINE AND IMPF 3. (Penalties under these um imprisonment of between the submitted in the sum of the sum o	LAW THAT I HAVE PERSIMATION SUBMITTED HER SIMMEDIATELY RESPOISE THE SUBMITTED IN I AM AWARE THAT THE FALSE INFORMATION OF THE SUBMITTED THAT THE STALSE INFORMATION OF THE SUBMITTED THAT THE STALSE INFORMATION OF THE SUBMITTED THAT THE SUBMITTED THE SUBMITTED THAT THE SUBMITTED THE SUBMITTED THAT THE SUBMITTED THAT THE SUBMITTED THE SUBMITTED THAT THE SUBMITTED THAT THE SUBMITTED THAT THE SUBMITTED THE SUBMITTED THAT THE SUBMITTED THE SUBMITTED THE SUBMITTED THE SUBMITTED THE SUBMITTED THE SUBMITTED THE	ONALLY EXAM EIN; AND BASI NSIBLE FOR O IFORMATION IERE ARE SIG ON, INCLUDI	INED AND ED ON MY BTAINING IS TRUE, INIFICANT NO THE	Rud		TELEPHO			ATE
Chemistry Manager TYPED OR PRINTED	POSSI § 1318 maximi	BILLLY OF FINE AND IMPR 9. (Penalties under these a um imprisonment of between	IISONMENT, SEE 18 U.S. statutes may include fine on 6 months and 5 years.)	U. § 1001 AND IS up to \$10,0	33 U.S.C. SIGNA 00 and or OFF	TURE OF PRINCIPAL ICER OR AUTHORIZE	D AGENT AR	12 393- EA NUMBI			0 25 10 DA

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," " Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSp.O. BOX 4

ATTR: DAVID ORNDORF

FACILITY SHIPPINGPORT

PA 15077

LOCATION

MONITORING PERIOD YEAR MO DAY YEAR MO DAY ख्य 99 09 - Q <u>\$</u> 3 0 FROM

PA0025615

PERMIT NUMBER

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)

403 A

DISCHARGE NUMBER

MAJOR (SUBR 05) Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

f - FINAL CONDENSATE BLOWDOWN & RIVE WAT

\*\*\* NO DISCHARGE X \*\*\*

TTM: DAVID ORKDORF			(20-21)	(22-23) (24-	25) (26-27) (28-	29) (30-31)	NOTE: Read in:	structions befor	e com	oleting this	iorm.
PARAMETER		(3 Card Only) QUAN (46-53)	TITY OR LOADING (54-61)		(4 Card Only) QL (38-45)	JANTITY OR CONC (46-53)	ENTRATION (54-61)		NO. EX	FREQUENCY OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
H	SAMPLE	क्षेत्र प्रदेश होते होते होते होते हैं	- No state the ste ste			Sin this also also also also		( 1.2)			
·	EASUREMENT	- 44	AND MEDICAL IS	ofe six six	6.0				14	EEKLY	a H A B
OUOO 1 O O FFLUENT GROSS VALUERE	PERMIT EQUIREMENT			<b>建</b> 杂烷烷	MIWIMUM		MAXIMUM	รบ			
OLIDS, TOTAL USPENDED ME	SAMPLE EASUREMENT	<b>ន</b> ្ទាប់ក្នុង ប្រ	र्शन की तर्गन दीन दीन दीन		<b>有效效效效效</b>	· · · · · · · · · · · · · · · · · · ·		(19)			
0530 1 0 0 FFLUENT GROSS VALUE RE	PERMIT EQUIREMENT			ទល់ល សំណុលសំ	asaxaa	HO AVG	DAILY M	T T T T T T T T T T T T T T T T T T T	ļi	EEXLY	HAD
• <u>• • • • • • • • • • • • • • • • • • </u>	SAMPLE EASUREMENT	क्षेत्र महित भीत भीत मीत भीत -	के हिंदी के दे दे		<b>企业企业企</b>			( 19)			
CSS6 1 0 0 FFLUERT GROSS VALUE RE		989498	e de state de de la de de stein de de de	整体的 整体检查	2006024 2007 2007 2007 2007 2007 2007 2007 2	NO YAR	DAILY M	X MG/L	*	BEKLY	Pard
( , , , L , , , , , , , , , , , , , , ,	SAMPLE EASUREMENT	****		ी हो। हो। होता हो। हो।	0.00000	REPORT				EEKLI	a .
TFLOENT GROSS VALUE RE		<u> </u>		4444	te Ve ste ste ste ste etc	no Ave	DATEY				
LAMTROL CT-1, TOTAL WATER 4251 1 0 0	SAMPLE EASUREMENT	252535		<b>A</b>	negras.				5		COMF2
PFLUENT GROSS VALUE RE	PERMIT EQUIREMENT		2012	\$1.40.00	\$\$\$\$\$\$	NO AVG	DATLY N			DISCH	1 -
LOW, IN CONDUIT OR BRU TREATMENT PLANTME		:		( 03)		Se on the Se de de	44. 170 44. 4.4 4.4				
COSO 1 O U FFLUENT GROSS VALUE RE	PERMIT EQUIREMENT	REPORT MO AVE	REPORT DATLY MX	หตุก	ottor			मूह क्षेत्र क्षेत्र होत	,	C+5.4.1	
4. 07 42 37 47 1. 42	SAMPLE EASUREMENT	<b>ខ្</b> លុំខ្លុំខ្លុំ ទ	is to the left		Apr the the tipe disc fit			( 19)			
00060 1 0 0 FFLUENT CROSS VALUE RE	PERMIT EQUIREMENT	- <b>54555</b> 6	dediction of	存存存存	08484A	XII AVG	1.25 INST MA			EEKLY	
NAME/TITLE PRINCIPAL EXECUTIVE OFFICE  David Orndorf	CER I CERTI AM FAN INQUIR THE IN ACCUR	IFY UNDER PENALTY OF LANGUAGE AND THE INFORMATION, I BELIEVE LATE AND COMPLETE. TIES FOR SUBMITTING SUBMITTING PENALES AND IMPRICE OF THE OF THE AND IMPRICE OF THE AND IMPRICE OF THE OF THE AND IMPRICE O	AW THAT I HAVE PERS ATION SUBMITTED HER IMMEDIATELY RESPOI THE SUBMITTED IN I AM AWARE THAT TH	ONALLY EXAM EIN; AND BASI NSIBLE FOR O IFORMATION IERE ARE SIG	INED AND ED ON MY BTAINING IS TRUE, INIFICANT	Auso	4	TELEPHO	NE .	D/	ATE
Chemistry Manager TYPED OR PRINTED	PENAL POSSIE § 1319. maximu	TIES FOR SUBMITTING BILITY OF FINE AND IMPRI . (Penalties under these s im Imprisonment of between	SONMENT, SEE 18 U.S. tatutes may include fine in 6 months and 5 years.)	C. § 1001 AND IS up to \$10,0	33 U.S.C. SIGNAT	URE OF PRINCIPAL CER OR AUTHORIZE	EXECUTIVE D AGENT	AREA NUMBE			.0 25 MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

HYDRAZINE AND AMMONIA MONITORING TO APPLY DURING PERIODS OF WET LAYUP. REPORT THE DAILY MAXISUM FOR HETZ D MC/L. (THE LIMIT IS 35 MG/L AS A DATLY MAX.) T-1 WHEE DISCHARGING (24 HR. COSP.):

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," " Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

# **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSp.O. BOX 4

ATTN: DAVID ORNDORF

FACILITY SHIPPINGPORT

Pa 15077

LOCATION

MONITORING PERIOD MO YEAR МО DAY YEAR DAY -99 UI FROM (30-31) (20-21) (22-23) (24-25) (26-27) (28-29)

PR0025615

PERMIT NUMBER

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR)

A FOU

DISCHARGE NUMBER

ROLAS (50BR 05) F - FINAL Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

CONDENSATE BLOWDOWN E RIVE WAT

\*\*\* NO DISCHARGE IX NOTE: Read Instructions before completing this form.

ATTN: DAVID ORNDORF (3 Card Only) QUANTITY OR LOADING QUANTITY OR CONCENTRATION NO. FREQUENCY SAMPLE (4 Card Only) (54-61)TYPE (54-61) (46-53)PARAMETER **ANALYSIS** UNITS (32-37)UNITS MINIMUM **AVERAGE** MAXIMUM **AVERAGE** MAXIMUM (69-70)(64-68) 19) **电影电影电影** 数数数数数数数 在海绵松松 HYDRAZINE SAMPLE MEASUREMENT WEEKLYGRAS \*\*\*\* caanaa 医多数性皮肤 医水溶液 31313 **1** PERMIT DAILY MX MG/L NO AVS REFLUENT GROSS VALUE REQUIREMENT 化熔胶液 SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER

David Orndorf Chemistry Manager TYPED OR PRINTED I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN: AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 and or maximum imprisonment of between 6 months and 5 years.)

SIGNATURE OF PRINCIPAL EXECUTIVE **OFFICER OR AUTHORIZED AGENT** 

17 303-7450

**TELEPHONE** 

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT

HYDRAZINE AND AMMONIA MONITORING TO APPLY DUPING PERIODS OF WET LAYUP. REPORT THE DAILY MAXIMUM FOR BETZ D MG/L. (THE LIMIT IS 35 MG/L AS A DAILY MAX.) T-1 WHEN DISCHARGING (24 HR. COMP.):

DATE

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### **General Instructions**

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

## **Legal Notice**

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME BEAVER VALLEY PORER STATION

ADDRESSP.O. BOX 4

ATTN: DAVID ORNDORF

FACILITY ShippingPort

PA 15077

LOCATION

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)
(2-16) (17-19) PA0025615 PERMIT NUMBER

FROM

DISCHARGE NUMBER

MAJOR (SUBR 05)

F - FINAL

Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

MONITORING PERIOD DAY YEAR MO DAY YEAR MO 30 9 न TO

\*\*\* NO DISCHARGE

NOTE: Read Instructions before completing this form.

UBIT 1 GENETA SLADAN FILT BA

TTN: DAVID DRNDORF		(20-21) (22-23) (24-25) (26-27) (28-29) (30-31) NOTE: Read Instructions before completing this form.									
PARAMETER (32-37)	$\overline{}$	(3 Card Only) QUANTITY OR LOADING (46-53) (54-61)			(4 Card Only) QUANTITY OR CONCENTRATION (46-53) (54-61)			·		FREQUENCY OF	SAMPLE TYPE
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS (64-68)	(69-70)
OLIOS, TOTAL	SAMPLE	· 中央市市市中央市	क्षा क्षा क्षा क्षा क्ष		<b>化物物物物</b>			(19)			
USPENDED	MEASUREMENT									REALY	0 4 0
0530 1 0 0	PERMIT	000000	0000000	**** *****	****	MO AVG	DATLY 6)	MG/L		LLINEA	KAD
FPLUENT GROSS VALUE				( 03)	****	20 45 45 45 45 45 20 45 45 45 45 45 20 45 45 45 45 45 45 45 45 45 45 45 45 45	State Sta				
LOW, IN CONDUIT OR HRU TREATMENT PLANT	SAMPLE MEASUREMENT	,		\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	2)				į		
nno skaninemi plami 0050 1 0 0	PERMIT	1: 1: 2 O D T			5, E 7, B 7-7,		******	<b>建建</b> 能能	W	ESKLY	SIL
FFLUENT GROSS VALUE			DAILY MX	MGB				<b>数数数数</b>			
S. S. And S.J. and A. C. C. The Control of the Cont	SAMPLE										
*	MEASUREMENT			].							
	PERMIT	- 7				100					
	REQUIREMENT						-				
	SAMPLE			ļ				,			
	MEASUREMENT			1							
•	PERMIT REQUIREMENT						100				
	SAMPLE										
	MEASUREMENT					4				1	
	PERMIT										
	REQUIREMENT										<u> </u>
	SAMPLE										
	MEASUREMENT										
	PERMIT										
· · · · · · · · · · · · · · · · · · ·	REQUIREMENT			ļ					-		+
	SAMPLE MEASUREMENT										
	PERMIT										
	REQUIREMENT										
NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERT		IFY UNDER PENALTY OF	LAW THAT I HAVE PERS	SONALLY EXAM	INED AND		. / L	TELEPHO	NE	D,	ATE
was the form the first	AM FA INQUI	IIFY UNDER PENALTY OF MILIAR WITH THE INFORM RY OF THOSE INDIVIDUAL NFORMATION, I BELIEVATE AND COMPLETE. THES FOR SUBMITTIN BILLITY OF FINE AND IMPION. (Penaliles under these um Imprisonment of between the complex of the complex o	S IMMEDIATELY RESPO	NSIBLE FOR C	BTAINING IS TRUE	NO (	. Д Г				
David Orndorf Chemistry Manager	ACCU	RATE AND COMPLETE.	I AM AWARE THAT THE	HERE ARE SIC	ENIFICANT A	X 12.00					
	POSS 8 131	BILITY OF FINE AND IMPI	RISONMENT. SEE 18 U.S statutes may include fin	S.C. § 1001 AND	33 U.S.C. SIGNA	TURE OF PRINCIPAL	EXECUTIVE	<u> 412 393-</u>	<del>7459</del>	YEAR 1	76 BAY
TYPED OR PRINTED	mexim	um imprisonment of betwe	en 6 months and 5 years.)		OFF	TOER OR AUTHORIZE	ED AGENT	CODE NUMB	EH	YEAR	/IU   DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

# General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

#### **Legal Notice**

BEAVER VALLEY POWER STATION

ADDRESSp.O. BOX 4

ATTN: DAVID ORNDORF

PA 15077

FACILITY SHIPPINGFORT LOCATION

MONITORING PERIOD YEAR МО DAY YEAR MO DAY FROM UL

PACO25615

PERMIT NUMBER

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR) (2-16)

013 8

DISCHARGE NUMBER

SOLAS (SUSR 05)

P - FINAL

OUTFALL 013

Form Approved. OMB No. 2040-0004 Approval expires 05-31-98

\*\*\* NO DISCHARGE |

TTN: DAVID ORNDORF		(20-21) (22-23) (24-25) (26-27) (28-29) (30-31) <b>NOTE:</b> Read Instructions before completing this form.									
PARAMETER		(3 Card Only) QUANTITY OR LOADING (46-53) (54-61)			(4 Card Only) QUANTITY OR CONCENTRATION (38-45) (54-61)					FREQUENCY OF	SAMPLE TYPE
(32-37)		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	(62-63)	ANALYSIS 3) (64-68)	(69-70)
YANIOE, WEAR ACID.	SAMPLE MEASUREMENT	<b>泰森教育教</b> 会	के देश है के क		के कि के के के के	46.01	40.01	( 19)	6	9/90	CRAB
0718 1 0 0	PERMIT	terreprotests	40 Met (1) /	to hist	中海中华市市	REPORT	REPORT		Ī	WICE OTHLY	ChAb
FPLUENT GROSS VALUE VANIDE, TOTAL	SAMPLE	****	<b>乔 纳尔 华 华 坎</b>	<b>经验收收</b>	<b>\$\$\$\$\$\$</b>	<0.01	40.01	(19)	0	2/90	
(AS CM) 0720 1 0 0	MEASUREMENT PERMIT	27440B	*****	<b>本本</b> 章	404430	REPORT	852081		1	MICE	GRAG
PPLUENT GROSS VALUE STIMONY, TOTAL	REQUIREMENT SAMPLE	होट होट और कीर कीर कीर	ా చిల్లా చింది	<b>经收收款</b>	<b>表数数数数数</b>	ORTH AVS	DALLY #2	( MG/L ( 19)	2.	OTRLY OA	
(35 58)	MEASUREMENT	and the second	on the second of	in the the	12 12 12 12 12 12 12 12 12 12 12 12 12 1	2030	KO 90 REPORT			"HO	GRAC
1097 1 0 0 FFLUENT GROSS VALUE	PERMIT REQUIREMENT	100		经收收款		DATH AVG	DAILY M			QTHLY	
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT		200								
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT	4004			70 ( 1 1 7 1 1 2 2 )	BARTA					
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT					1 Think	A122				
	SAMPLE MEASUREMENT		, .								
	PERMIT REQUIREMENT						1. 12.				
NAME/TITLE PRINCIPAL EXECUTIVE O	FFICER I CERT	TIFY UNDER PENALTY OF MILIAR WITH THE INFORM	AATION OLIDIAITTED HED	251111111111111111111111111111111111111		10	/ [	TELEPHO	NE	C	ATE
David Orndorf	INQUII THE ACCU PENAI	RY OF THOSE INDIVIDUAL INFORMATION, I BELIEV RATE AND COMPLETE. TIES FOR SUBMITTIN	LS IMMEDIATELY RESPO /E THE SUBMITTED II I AM AWARE THAT TI IG FALSE INFORMAT	INSIBLE FOR C NFORMATION HERE ARE SIG 10N, INCLUD	DBTAINING IS TRUE, SNIFICANT ING THE	Standel	, 4 m				
Chemistry Manager POSSIE § 1319		WILLIAR WITH THE INFORMATION SUBMITTED THEREIN, AT THE INFORMATION IS TRUE, WY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING NFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, RATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT THES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE BILLITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. § 1001 AND 33 U.S.C. (Penatties under these statutes may include fines up to \$10,000 and or immprisonment of between 6 months and 5 years.)			33 U.S.C. SIGN 000 and or OF	SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT			7459 ER	YÉAR	MO D

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestion for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W. Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

#### General Instructions

- 1. If form has been partially completed by preprinting, disregard instruction directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and editing "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and Quality" as specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and Minimum" are normally extreme high and low measurements obtained during "Monitoring Period". (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurement during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurement" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g. Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g. Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions to be taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

#### **Legal Notice**