

Niagara Mohawk

Richard B. Abbott
Vice President
Nuclear Engineering

Phone: 315.349.1812
Fax: 315.349.4417

December 13, 1999
NMP1L 1489

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

RE: Nine Mile Point Unit 1
 Docket No. 50-220
 DPR-63

Subject: ***NUREG-0619 Inspection Reporting for NMP1 RPV Feedwater and CRDRL
Nozzle Examinations - 1999 Refueling Outage (RFO15)***

Gentlemen:

NUREG-0619, "BWR Feedwater Nozzle and Control Rod Drive Return Line Nozzle Cracking" (November 1980), requires that licensees submit a detailed report to the Commission discussing the inspections of the Feedwater and Control Rod Drive (CRD) return line nozzles. This report is required to be submitted within six months of completing an outage at which an inspection was performed. The Attachment to this letter provides the staff with the results of the subject inspections performed at Nine Mile Point Unit 1 (NMP1) during the Fifteenth Refueling Outage (RFO15).

Very truly yours,



Richard B. Abbott
Vice President Nuclear Engineering

RBA/JMT/jb
Attachment

xc: Mr. H. J. Miller, NRC Regional Administrator, Region I
 Mr. S. S. Bajwa, Section Chief PD-I, Section 1, NRR
 Mr. G. K. Hunegs, NRC Senior Resident Inspector
 Mr. D. S. Hood, Senior Project Manager, NRR
 Records Management

A001

DOR

ADDER 0500 1200

ATTACHMENT