



**Pacific Gas and  
Electric Company**

**James E. Tomkins**  
Manager  
Nuclear Safety Assessment  
and Licensing

Diablo Canyon Power Plant  
P.O. Box 56  
Avila Beach, CA 93424

805.545.4052  
Fax: 805.545.4234

December 17, 1999

PG&E Letter DCL-99-164

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555-0001


Docket 50-275, OL-DPR-80  
Docket 50-323, OL-DPR-82  
Diablo Canyon Units 1 and 2  
Licensing Action Implementation Summary

Dear Commissioners and Staff:

The attached enclosure provides the current status of implementation of licensing actions from March 1999 to November 1999. This report is provided for your information and use. The next report is expected to be issued in March 2000.

If you have questions regarding implementation activities, please contact Mr. Patrick T. Nugent at (805) 545-4872.

Sincerely,



James E. Tomkins

cc: Steven D. Bloom  
David L. Proulx

Enclosure

A001

PDL ADOW 05000275

**CURRENT STATUS OF IMPLEMENTATION OF LICENSING ACTIONS**

TAC Number	License Amendment Number	Subject	Approval Date	Implementation Date	Comments
M99463/ M99464	130/128	LAR 97-10 - Revision of Technical Specification 3/4.3.2, "Engineered Safety Features Actuation System Instrumentation," to Add Refueling Water Storage Tank Level Instrumentation	6/25/99	U2 - 10/31/99 U1 - 10/31/2000	Required implementation tasks have been completed for Unit 2. Implementation activities will be completed for Unit 1 during refueling outage 1R10.
M97914/ M97915	131/129	LAR 97-11 - Auxiliary Saltwater System Piping Bypass Unreviewed Safety Question	3/26/99	FSAR Update Issuance - May 2000	Required implementation tasks are still in progress.
MA0743/ MA0744	132/130	LAR 98-01 - Implementation of 230 kV System Improvements	4/29/99	FSAR Update Issuance - May 2000	Required implementation tasks are still in progress.
MA3573/ MA3574	133/131	LAR 98-06 - Revision of Technical Specification 3.4.9.1, Figures 3.4-2 and 3.4-3 - RCS Pressure/Temperature Limits and Request for Exemption from 10 CFR50.60	5/3/99	5/4/99	Required implementation tasks have been completed.
M98829/ M98830	134/132	LAR 97-05 - Revision of Technical Specification 3/4.3.7.1	5/13/99	FSAR Update Issuance - May 2000	Required implementation tasks are still in progress.
M98984/ M98985	135/135	LAR 97-09 - Improved Technical Specifications	5/28/99	5/31/2000	Required implementation tasks are still in progress.

**CURRENT STATUS OF IMPLEMENTATION OF LICENSING ACTIONS**

TAC Number	License Amendment Number	Subject	Approval Date	Implementation Date	Comments
MA4892/ MA4893	136/136	LAR 98-09 - Revision of Technical Specification 6.9.1.8 to Allow Use of NRC approved Addenda to WCAP 10054-P-A to Determine Core Operating Limits: Small Break Loss-of-Coolant Accident	11/15/99	2/13/2000	Required implementation tasks are still in progress.
MA4894/ MA4895		Inservice Inspection Relief Requests for Unit 1 Eighth Refueling Outage Weld Examination Limitations	9/29/99	9/29/99	Required implementation tasks have been completed.