



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064**

August 17, 2000

MEMORANDUM TO: K. E. Brockman, Director, Division of Reactor Projects

FROM: Linda Joy Smith, Chief, Project Branch E

SUBJECT: SECOND QUARTER 2000 REVIEW FOR WATERFORD STEAM
ELECTRIC STATION, UNIT 3

I have reviewed the 2Q/2000 Performance Indicators and inspection findings for Waterford Steam Electric Station, Unit 3. All performance indicators and inspection findings were green. No adverse trends in the licensee's performance were identified during this review. I recommend that no additional inspections beyond the baseline inspection program be performed.

However, based on a significant security finding from the old inspection program, DRS plans additional inspection in the security area. A letter to the licensee to schedule this inspection is being prepared, as required by Inspection Manual Chapter 0305.

cc via E-mail through ADAMS:

G. Pick (GAP)

J. Melfi (JFM1)

T. Farnholtz (TRF)

J. Keeton (JMK)

K. Kalyanam (NXX)