

March 2, 2011

Mr. Scott Daubert
Tyco Electronics
1396 Charlotte Highway
Fairview, North Carolina 28730

SUBJECT: TYCO ELECTRONICS RESPONSE TO NRC INSPECTION REPORT
99901397/2010-201, NOTICE OF NONCONFORMANCE

Dear Mr. Daubert:

Thank you for your letters dated November 9, 2011, February 4, 2011, and February 14, 2011, in response to the Notice of Nonconformance (NON) that were discussed in the U.S. Nuclear Regulatory Commission (NRC) Inspection Report 99901397/2010-201, dated October 6, 2010.

The NRC acknowledges the new completion date of May 4, 2011 presented by Tyco during the phone conference held on February 3, 2011. As previously identified in ML103270497, we found your response to Inspection Report 99901397/2010-201 addressed the identified issues. The staff determined during the inspection that Tyco's Policies and Procedures have the controls in place that would prescribe the process and requirements for corrective action completion. The letters dated February 4, 2011 and February 14, 2011, were not needed for the staff's determination that the proposed corrective actions were adequate and are being returned to you.

As previously stated, the staff may review the implementation of your corrective action during a future U.S. Nuclear Regulatory Commission staff inspection to determine that full compliance has been achieved and will be maintained.

If you or your staff have any questions regarding this matter, we will be pleased to discuss them with you. Please contact Mr. Aaron Armstrong at (301) 415-8396 or via electronic mail at Aaron.Armstrong@nrc.gov, if you have any questions or need assistance regarding this matter.

Sincerely,

/RA/

Patrick L. Hiland, Director
Division of Engineering
Office of Nuclear Reactor Regulation

Docket No. 99901397

March 2, 2011

Mr. Scott Daubert
Tyco Electronics
1396 Charlotte Highway
Fairview, North Carolina

SUBJECT: TYCO ELECTRONICS RESPONSE TO NRC INSPECTION REPORT
99901397/2010-201, NOTICE OF NONCONFORMANCE

Dear Mr. Daubert:

Thank you for your letters dated November 9, 2011, February 4, 2011, and February 14, 2011, in response to the Notice of Nonconformance (NON) that were discussed in the U.S. Nuclear Regulatory Commission (NRC) Inspection Report 99901397/2010-201, dated October 6, 2010.

The NRC acknowledges the new completion date of May 4, 2011 presented by Tyco during the phone conference held on February 3, 2011. As previously identified in ML103270497, we found your response to Inspection Report 99901397/2010-201 addressed the identified issues. The staff determined during the inspection that Tyco's Policies and Procedures have the controls in place that would prescribe the process and requirements for corrective action completion. The letters dated February 4, 2011 and February 14, 2011, were not needed for the staff's determination that the proposed corrective actions were adequate and are being returned to you.

As previously stated, the staff may review the implementation of your corrective action during a future U.S. Nuclear Regulatory Commission staff inspection to determine that full compliance has been achieved and will be maintained.

If you or your staff have any questions regarding this matter, we will be pleased to discuss them with you. Please contact Mr. Aaron Armstrong at (301) 415-8396 or via electronic mail at Aaron.Armstrong@nrc.gov, if you have any questions or need assistance regarding this matter.

Sincerely,

/RA/

Patrick L. Hiland, Director
Division of Engineering
Office of Nuclear Reactor Regulation

Docket No. 99901397

DISTRIBUTION:

dauberts@tycoelectronics.com KKavanagh

ADAMS Accession No.: ML110591046

OFFICE	NRR/DE/EQVB	NRR/DE/EQVB	NRR/DE/EQVB	NRR/DE/EQVB	NRR/DE
NAME	AArmstrong	JOrtega	PPrescott	MMurphy	PHiland
DATE	03/ 01 /2011	03/ 01 /2011	03/ 01 /2011	03/ 01 /2011	03/ 02 /2011

OFFICIAL RECORD COPY