

Dennig, Robert

24
78

From: Dennig, Robert *MR*
Sent: Tuesday, September 06, 2011 1:38 PM
To: Wilson, George; Clifford, Paul; Wood, Kent; Ulses, Anthony; Mendiola, Anthony
Cc: Bettie, Jerome; Karipineni, Nageswara
Subject: RE: North Anna

We believe that the licensee likely has a list of IST tests scheduled to be performed if a shutdown will exceed 72 hours. These tests would provide an adequate sample of valve functionality, absent any visible evidence of damage.

We recommend a general visual inspection of the containment consistent with Appendix J and industry guidance, NEI 94-01 and ANSI/ANS 56.8.

From: Wilson, George *MR*
Sent: Tuesday, September 06, 2011 10:15 AM
To: Clifford, Paul; Wood, Kent; Ulses, Anthony; Mendiola, Anthony; Dennig, Robert
Subject: North Anna

Bob please send me something on cnmt, and paul and Kent something on the feul and spent fuel

George Wilson
USNRC
EICB Branch Chief, Division of Engineering
Mail Stop O12H2
301-415-1711

D
78