



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005

August 30, 2005

Randall K. Edington, Vice
President-Nuclear and CNO
Nebraska Public Power District
P.O. Box 98
Brownville, NE 68321

**SUBJECT: MIDCYCLE PERFORMANCE REVIEW AND INSPECTION PLAN -
COOPER NUCLEAR STATION**

Dear Mr. Edington:

On August 4, 2005, the NRC staff completed its performance review of the Cooper Nuclear Station (CNS) for the first half of the calendar year 2005 assessment cycle. Our technical staff reviewed performance indicators (PIs) for the most recent quarter and inspection results over the previous 12 months. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility in order for you to inform us of any planned inspections that may conflict with your plant activities.

This performance review and enclosed inspection plan do not include physical protection information. A separate letter designated and marked as "Exempt from Public Disclosure in Accordance with 10 CFR 2.390" will include the physical protection review and resultant inspection plan.

Overall, CNS operated in a manner that preserved public health and safety. Plant performance for the most recent quarter was within the Licensee Response Column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all PIs indicating performance at a level requiring no additional NRC oversight (Green).

While plant performance for the most recent quarter was within the Licensee Response Column of the Action Matrix, CNS was in the Regulatory Response Column of the NRC's Action Matrix at the beginning of this assessment period. This was based on one finding of low to moderate significance (White) in the Mitigating Systems Cornerstone. This finding involved a significant number of licensed operator requalification written examination failures. A supplemental inspection determined the root cause, extent of condition, and associated corrective actions were appropriately performed to address the deficiencies noted in the operator requalification program. As a result, this finding was closed in NRC Inspection Report 05000298/2004015, dated March 16, 2005.

As updated in our 2004 annual assessment letter, dated March 2, 2005, we advised you of our continuing concerns associated with two substantive crosscutting issues in the areas of human

performance and problem identification and resolution. As discussed in that letter, the NRC acknowledged that the Nebraska Public Power District (NPPD) implemented actions to address these areas and some improvement was noted; however, human performance deficiencies and inconsistent implementation of the corrective action program continued to be identified.

During this assessment period, there were 13 Green findings identified in the area of human performance, most of which occurred during the past 6 months. A number of these findings involved the causal factor of personnel performance. Specifically, there were multiple Green findings involving instances of personnel failing to follow procedural guidance affecting the Mitigating Systems, Emergency Preparedness, and Occupational Radiation Safety Cornerstones. Examples include: a failure to follow an operability procedure for the service water system strainers; a failure to properly implement an emergency plan implementing procedure during a fire; and a failure to post and barricade two areas in the drywell as locked high radiation areas.

In the area of problem identification and resolution, one recurring theme, which also has been documented in previous NRC assessments, involves inadequate corrective actions resulting in repetitive problems which impact plant operation. During this assessment period, there were six Green findings involving problem identification and resolution, four of which involved the causal factor of corrective action. Recent examples include three findings within the last 6 months involving repetitive failures to correct adverse conditions affecting the Mitigating Systems and Barrier Integrity Cornerstones. These involved the failure to comprehensively address the rendering of the high pressure coolant injection system inoperable by operators during scram recovery actions, the failure to properly address the root cause of operating the reactor in excess of licensed thermal power, and the failure to promptly correct degraded conditions affecting a service water booster pump.

The NRC recognizes that NPPD continues to implement actions to improve human performance and improve the effectiveness of the corrective action program at CNS. Notwithstanding these improvements, there continues to be a number of findings across several cornerstones and the performance deficiency impacts plant operations. Focused NRC oversight of these areas through baseline inspections will continue until our inspections indicate that your actions have been effective in improving the level of procedural adherence and preventing repetitive or similarly recurring problems that significantly impact plant performance.


The enclosed inspection plan details the inspections, except those related to physical protection, scheduled through March 31, 2007. The inspection plan is provided to minimize the resource impact on your staff and to allow for the early resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 9 months of the inspection plan are tentative and may be revised at the end-of-cycle review meeting.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's

document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Wayne Walker at (817) 276-6523 with any questions you may have regarding this letter or the inspection plan.

Sincerely,



Arthur T. Howell III, Director
Division of Reactor Projects

Docket: 50-298
License: DPR-46

Enclosure:
Cooper Nuclear Station Inspection/Activity Plan

cc w/enclosure:

Michael T. Boyce, Nuclear Asset Manager
Nebraska Public Power District
1414 15th Street
Columbus, NE 68601

John C. McClure, Vice President
and General Counsel
Nebraska Public Power District
P.O. Box 499
Columbus, NE 68602-0499

P. V. Fleming, Licensing Manager
Nebraska Public Power District
P.O. Box 98
Brownville, NE 68321

Michael J. Linder, Director
Nebraska Department of
Environmental Quality
P.O. Box 98922
Lincoln, NE 68509-8922

Chairman
Nemaha County Board of Commissioners
Nemaha County Courthouse
1824 N Street
Auburn, NE 68305

Sue Semerena, Section Administrator
Nebraska Health & Human Services
Dept. of Regulation & Licensing
Division of Public Health Assurance
301 Centennial Mall, South
P.O. Box 95007
Lincoln, NE 68509-5007

Mike Wells, Deputy Director
Missouri Department of Natural Resources
P.O. Box 176
Jefferson City, MO 65101

Director, Missouri State Emergency
Management Agency
P.O. Box 116
Jefferson City, MO 65102-0116

Chief, Radiation and Asbestos
Control Section
Kansas Department of Health
and Environment
Bureau of Air and Radiation
1000 SW Jackson, Suite 310
Topeka, KS 66612-1366

Daniel K. McGhee
Bureau of Radiological Health
Iowa Department of Public Health
Lucas State Office Building, 5th Floor
321 East 12th Street
Des Moines, IA 50319

William J. Fehrman, President
and Chief Executive Officer
Nebraska Public Power District
1414 15th Street
Columbus, NE 68601

Jerry C. Roberts, Director of
Nuclear Safety Assurance
Nebraska Public Power District
P.O. Box 98
Brownville, NE 68321

Institute of Nuclear Power Operations (INPO)
Records Center
700 Galleria Parkway SE, Suite 100
Atlanta, GA 30339

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates Start	Planned Dates End	Inspection Type
1	ALARA3 - ALARA PLANNING AND CONTROLS		1			
	IP 7112102	ALARA Planning and Controls		08/22/2005	08/26/2005	Baseline Inspections
	OB-RQ - REQUAL INSPECTION		3			
1	IP 7111111B	Licensed Operator Requalification Program		11/14/2005	11/18/2005	Baseline Inspections
	PEB - MAINTENANCE RULE BIENNIAL		1			
1	IP 7111112B	Maintenance Effectiveness		04/10/2006	04/14/2006	Baseline Inspections
	EB02/17 - PERMANENT MODS/50.59		3			
1	IP 7111102	Evaluation of Changes, Tests, or Experiments		04/24/2006	04/28/2006	Baseline Inspections
1	IP 711117B	Permanent Plant Modifications		04/24/2006	04/28/2006	Baseline Inspections
	PEB - HX PERFORMANCE		1			
1	IP 7111107B	Heat Sink Performance		06/26/2006	06/30/2006	Baseline Inspections
	EP1 - EMERG PREPAREDNESS EXERCISE		3			
1	IP 7111401	Exercise Evaluation		07/17/2006	07/21/2006	Baseline Inspections
1	IP 7111404	Emergency Action Level and Emergency Plan Changes		07/17/2006	07/21/2006	Baseline Inspections
1	IP 71151	Performance Indicator Verification		07/17/2006	07/21/2006	Baseline Inspections
	ACRSA - ACCESS CONTROLS TO RAD SIGNIFICANT AREAS		1			
1	IP 7112101	Access Control to Radiologically Significant Areas		10/16/2006	10/20/2006	Baseline Inspections
	ALARA1 - ALARA PLANNING AND CONTROLS		1			
1	IP 7112102	ALARA Planning and Controls		10/30/2006	11/03/2006	Baseline Inspections
	ACRSA - ACCESS CONTROLS TO RAD AREAS		1			
1	IP 7112101	Access Control to Radiologically Significant Areas		03/19/2007	03/23/2007	Baseline Inspections

This report does not include INPO and OUTAGE activities.
 This report shows only on-site and announced inspection procedures.

- Electronic distribution by RIV:
 Regional Administrator (**BSM1**)
 DRP Director (**ATH**)
 DRS Director (**DDC**)
 DRS Deputy Director (**KMK**)
 Senior Resident Inspector (**SCS**)
 Branch Chief, DRP/C (**WCW**)
 Project Engineer, DRP/C (**RVA**)
 Team Leader, DRP/TSS (**RLN1**)
 RITS Coordinator (**KEG**)
 V. Dricks, PAO (**VLD**)
 W. Maier, RSLO (**WAM**)
 C. Gordon (**CJG**)
 DRS Branch Chiefs (**LJS, MPS1, REL, NFO**)
 S. Richards, Chief, NRR/DIPM/IIPB (**SAR**)
 M. Case, Deputy Dir. for Inspection and Programs (**MJC**)
 B. Sheron, Associate Dir. for Project Licensing and Technical Analysis (**BWS**)
 T. Bergman, Chief, TRPS/OEDO (**TAB**)
 H. Berkow, Director, LPD4, NRR/DLPM (**HNB**)
 D. Terao, Chief, PDIV-1, NRR/DLPM (**DXT**)
 M. Honcharik, NRR Project Manager (**MCH3**)

SISP Review Completed: wcw ADAMS: Yes No Initials: wcw
 Publicly Available Non-Publicly Available Sensitive Non-Sensitive

S:\DRP\DRPDIR\MIDCYCLE 2005\CNS.wpd

RIV:SPE/DRP/C	C:DRP/C	D:DRS	C:DRP/C	D:DRP
RVAzua	WCWalker	DDChamberlain	WCWalker	ATHowell
<i>/RA/</i>	<i>/RA/</i>	<i>KMKennedy for</i>	<i>RVA for</i>	<i>W</i>
8/24/05	8/24/05	8/25/05	8/28/05	8/28/05

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax