



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064**

March 4, 2002

Joseph E. Venable
Vice President Operations
Waterford 3
Entergy Operations, Inc.
17265 River Road
Killona, Louisiana 70066-0751

SUBJECT: ANNUAL ASSESSMENT - WATERFORD 3 (REPORT 50-382/02-01)

Dear Mr. Venable:

On February 12, 2002, the NRC staff completed its end-of-cycle plant performance assessment of Waterford 3. The end-of-cycle review for Waterford 3 involved the participation of all technical divisions in evaluating performance indicators for the most recent quarter and inspection results for the period from April 1 through December 31, 2001. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility. This will provide you an opportunity to prepare for these inspections and to inform us of any planned inspections which may conflict with your plant activities.

As discussed in our previous annual assessment letter, dated May 29, 2001, this inspection and assessment cycle consisted of three quarters (i.e., the second, third, and fourth quarters of Calendar Year 2001) instead of the usual four quarters. This change was implemented in order to align the inspection and assessment cycle with the calendar year beginning on January 1, 2002.

Overall, Waterford 3 operated in a manner that preserved public health and safety, and fully met all cornerstone objectives. Plant performance for the most recent quarter, as well as the first two quarters of the assessment cycle, was within the Licensee Response Column of the NRC's Action Matrix. This is based on all inspection findings being classified as having very low safety significance (Green) and all performance indicators indicating performance at a level requiring no additional NRC oversight (Green). Therefore, we plan to conduct only baseline inspections at your facility through December 28, 2002. In addition, the NRC staff will perform Temporary Instruction TI 2515-145, Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles (NRC BULLETIN 2001-01), during the upcoming refueling outage.

Immediately following the terrorist attacks on the World Trade Center and the Pentagon, the NRC issued safeguards advisories recommending that nuclear power plant licensees go to the highest level of security, and all promptly did so. With continued uncertainty about the possibility of additional terrorist activities, the Nation's nuclear power plants, including Waterford 3, remain at a high level of security. On February 25, 2002, the NRC issued an Order to all nuclear power plant licensees, requiring them to take certain additional interim

compensatory measures to address the generalized high-level threat environment. These additional compensatory requirements will provide the NRC with reasonable assurance that public health and safety and the common defense and security continue to be adequately protected in the current generalized high-level threat environment. These requirements will remain in effect pending notification from the Commission that a significant change in the threat environment occurs or until the Commission determines that other changes are needed following a more comprehensive re-evaluation of current safeguards and security programs. To date we have monitored Entergy Operations, Inc.'s actions in response to the terrorist attacks through a series of audits. With the issuance of the Order, we will evaluate Entergy Operations, Inc.'s compliance with these interim requirements.

The enclosed inspection plan details the inspections scheduled through March 31, 2003. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The last 6 months of the inspection plan are tentative and may be revised at the Midcycle Review meeting.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact me at (817) 860-8147 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

William B. Jones, Chief
Project Branch E
Division of Reactor Projects

Dockets: 50-382
Licenses: NPF-38

Enclosure:
Waterford 3 Inspection/Activity Plan

cc w/enclosure:
Executive Vice President and
Chief Operating Officer
Entergy Operations, Inc.
P.O. Box 31995

Entergy Operations, Inc.

-3-

Jackson, Mississippi 39286-1995

Vice President, Operations Support
Entergy Operations, Inc.
P.O. Box 31995
Jackson, Mississippi 39286-1995

Wise, Carter, Child & Caraway
P.O. Box 651
Jackson, Mississippi 39205

General Manager, Plant Operations
Waterford 3 SES
Entergy Operations, Inc.
17265 River Road
Killona, Louisiana 70066-0751

Manager - Licensing Manager
Waterford 3 SES
Entergy Operations, Inc.
17265 River Road
Killona, Louisiana 70066-0751

Chairman
Louisiana Public Service Commission
P.O. Box 91154
Baton Rouge, Louisiana 70821-9154

Director, Nuclear Safety &
Regulatory Affairs
Waterford 3 SES
Entergy Operations, Inc.
17265 River Road
Killona, Louisiana 70066-0751

Michael E. Henry, Administrator
and State Liaison Officer
Department of Environmental Quality
P.O. Box 82135
Baton Rouge, Louisiana 70884-2135

Parish President
St. Charles Parish
P.O. Box 302
Hahnville, Louisiana 70057

Winston & Strawn
1400 L Street, N.W.

Entergy Operations, Inc.

-4-

Washington, D.C. 20005-3502

Mr. Nickie Monica, President
St. John the Baptist
1801 W. Airline Hwy
LaPlace, Louisiana 70068

Federal Emergency Management Agency
Ron Castleman, Regional Director
Region VI, Federal Center
800 North Loop 288
Denton, Texas 76201-3698

Col. Michael L. Brown
Assistant Director
State Emergency Management
Military Department
Office of Emergency Preparedness
P.O. Box 44217
Baton Rouge, Louisiana 70804

Albert D. Laque, Parish President
St. Charles Parish
P.O. Box 302
Hahnville, Louisiana 70057

Electronic distribution from ADAMS by RIV:

- Regional Administrator **(EWM)**
 - DRP Director **(KEB)**
 - DRS Director **(ATH)**
 - Senior Resident Inspector **(TRF)**
 - Branch Chief, DRP/E **(WBJ)**
 - Senior Project Engineer, DRP/E **(GAP)**
 - Staff Chief, DRP/TSS **(PHH)**
 - RITS Coordinator **(NBH)**
 - B. Henderson, PAO **(BWH)**
 - W. A. Maier, RSLO **(WAM)**
 - C. J. Gordon **(CJG)**
 - DRS Branch Chiefs **(GMG, ATG, CSM)**
 - W. D. Travers, EDO **(WDT)**
 - M. Johnson, Chief, NRR/DIPM/IIPB **(MRJ1)**
 - R. K. Frahm, PPR Program Manager, NRR/DIPM/IIPB **(RKF)**
 - B. A. Boger, Associate Dir. for Inspection and Programs **(BAB2)**
 - B. W. Sheron, Associate Dir. for Project Licensing and Technical Analysis **(BWS)**
 - J. Shea, Chief, Regional Operations Staff, OEDO **(JWS1)**
 - S. Richards, NRR Project Director **(SAR)**
 - R. Gramm, Chief, Section 1, NRR/DLPM **(RAG)**
 - N. Kalyanam, NRR Project Manager **(NXK)**
- RidsNrrDipmlipb**

Hard Copy:
Records Center, INPO

S:\DRP\DRPDIR\EOC 2002\Assessment Letters\WAT.wpd

RIV:C:DRP/E	D:DRS	D:DRP	For signature	
WBJones;df	ATHowell	KEBrockman	WBJones	
/RA/	/RA/	/RA/	/RA/	
For review	2/27/02	3/4/02	3/4/02	

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

Waterford
Inspection / Activity Plan
03/01/2002 - 03/30/2003

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
				Start	End	
	PSB-RP7	- ALARA PLANNING AND CONTROLS	1			
3	IP 7112102	ALARA Planning and Controls		02/25/2002	03/01/2002	Baseline Inspections
	TI 145	- IEB 2001-01, VHP INSPECTION	1			
3	IP 2515/145	Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles (NRC Bulletin :		04/01/2002	04/05/2002	Safety Issues
	EMB	- INSERVICE INSPECTION	1			
3	IP 7111108	Inservice Inspection Activities		04/01/2002	04/05/2002	Baseline Inspections
3	IP 7111108	Inservice Inspection Activities		04/08/2002	04/12/2002	Baseline Inspections
	RP-1	- ACRSA AND PIV	1			
3	IP 7112101	Access Control to Radiologically Significant Areas		04/08/2002	04/12/2002	Baseline Inspections
3	IP 71151	Performance Indicator Verification		04/08/2002	04/12/2002	Baseline Inspections
	EMB	- HEAT SINK	1			
3	IP 7111107B	Heat Sink Performance		06/17/2002	06/21/2002	Baseline Inspections
	RP-3	- ALARA	1			
3	IP 7112102	ALARA Planning and Controls		07/15/2002	07/19/2002	Baseline Inspections
	PSB-EP1	- EP PROGRAM BASELINE INSPECTION	1			
3	IP 7111402	Alert and Notification System Testing		07/22/2002	07/26/2002	Baseline Inspections
3	IP 7111403	Emergency Response Organization Augmentation Testing		07/22/2002	07/26/2002	Baseline Inspections
3	IP 7111404	Emergency Action Level and Emergency Plan Changes		07/22/2002	07/26/2002	Baseline Inspections
3	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		07/22/2002	07/26/2002	Baseline Inspections
3	IP 71151	Performance Indicator Verification		07/22/2002	07/26/2002	Baseline Inspections
	PBE-PIR	- W3 PIR INSPECTION	4			
3	IP 71152B	Identification and Resolution of Problems		12/09/2002	12/20/2002	Baseline Inspections
	EMB	- BIENNIAL MR INSPECTION	1			
3	IP 711112B	Maintenance Rule Implementation		01/13/2003	01/17/2003	Baseline Inspections
	PSB-S1	- AACCESS AUTH/CONTROL, SEC PLAN, PIV	1			
3	IP 7113001	Access Authorization Program (Behavior Observation Only)		02/03/2003	02/07/2003	Baseline Inspections
3	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorizatio		02/03/2003	02/07/2003	Baseline Inspections
3	IP 7113004	Security Plan Changes		02/03/2003	02/07/2003	Baseline Inspections
3	IP 71151	Performance Indicator Verification		02/03/2003	02/07/2003	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.