

**ADVISORY COMMITTEE ON REACTOR SAFEGUARDS  
MEETING OF THE SUBCOMMITTEE ON  
POWER UPRATES  
ROOM T-2B3, 11545 ROCKVILLE PIKE, ROCKVILLE, MD  
July 8, 2008**

**Millstone Power Station, Unit 3 (MPS3)  
Stretch Power Uprate (SPU)**

ACRS Contact: David E. Bessette (301) 415-8065  
E-mail: [deb@nrc.gov](mailto:deb@nrc.gov)

**Tuesday, July 8, 2008**

Topic	Presenter	Time
Introduction	J. Sieber (ACRS)	9:00 – 9:10 AM
1. Opening Remarks	(NRR)	9:10 – 9:15 AM
2. Introduction	J. Lamb (NRR)	9:15 – 9:30 AM
3. MPS3 SPU Overview	(Dominion)	9:30 – 10:30 AM
*** BREAK ***		10:30 – 10:45 AM
4. Fuel and Core	(Dominion)	10:45 - 11:30 AM
5. Safety Analyses	(Dominion)	11:30 - 12:00 AM
6. Safety Analyses	B. Parks (NRR)	12:00 – 12:30 PM
**** LUNCH*****		12:30 – 1: 30 PM
***** CLOSED SESSION****		
7. Fuel & Safety Analyses	(Dominion & Westinghouse)	1:30 - 2:00 PM
8. Fuel & Safety Analyses	B. Parks (NRR)	2:00 - 2:30 PM
***** BREAK ****		2:30 – 2:45 PM
*****OPEN SESSION RESUMES****		
9. Containment Analyses	(Dominion)	2:45 - 3:15 PM
10. Containment Analyses	A. Sallman (NRR)	3:15 - 3:45 PM
11. Electrical	(Dominion)	3:45 – 4:15 PM
12. Electrical	S. Ray (NRR)	4:15 – 4:45 PM
13. Flow Accelerated Corrosion	(Dominion)	4:45 - 5:15 PM
14. Flow Accelerated Corrosion	M. Yoder (NRR)	5:15 - 5:45 PM
15. Committee Deliberations	ACRS	5:45 – 6:00 PM
Adjourn		6:00 PM

**Notes:**

1. Presentation time should not exceed 50% of the total time allocated for a specific item.
2. Number of copies of presentation materials to be provided to the ACRS and audience – 50.