

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 11

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 11

Facility Name: Beaver Valley 1 Docket (050- 00334)

Details	Department	Work Type	Docket/Report
Communications / IR			
53 - Communication LTA	D - Emergency Planning	D - Emergency Drill	050-00334/2004-008
53 - Communication LTA	D - Emergency Planning	D - Emergency Drill	050-00334/2004-008
Number of Items for this Docket: 2			
Percent of Total for this Docket: 18			
Management and Supervision / IR			
48 - Audits or problem identification LTA	D - Emergency Planning	D - Emergency Drill	050-00334/2004-008
Number of Items for this Docket: 1			
Percent of Total for this Docket: 9			
Procedures and Reference Document / IR			
12 - Procedure technical content LTA	I - Instrumentation & Control	C - Calibration	050-00334/2003-005
12 - Procedure technical content LTA	I - Instrumentation & Control	C - Calibration	050-00334/2003-005
12 - Procedure technical content LTA	T - Training	O - Control Room Ops	050-00334/2004-005
Number of Items for this Docket: 3			
Percent of Total for this Docket: 27			
Work Factors / IR			
83 - Work practice or craft skill LTA	I - Instrumentation & Control	S - Surveillance	050-00334/2003-005
84 - Non-conserv. decision / Questioning LTA	W - Work Control / Scheduling Outage Pla	M - Maint / Repair	050-00334/2004-005
84 - Non-conserv. decision / Questioning LTA	W - Work Control / Scheduling Outage Pla	S - Surveillance	050-00334/2004-005
91 - Verification / plant tours LTA	I - Instrumentation & Control	S - Surveillance	050-00334/2003-005
92 - Self check LTA	I - Instrumentation & Control	S - Surveillance	050-00334/2003-005
Number of Items for this Docket: 5			
Percent of Total for this Docket: 45			
Total Items for this Docket: 11			
