

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 17

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 17

Facility Name: Arkansas Nuclear 2 Docket (050- 00368)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	M - Mechanical	M - Maintenance / Repair	050-00368/2005-005
160 - No communication / information not communicated	M - Mechanical	M - Maintenance / Repair	050-00368/2005-005
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00368/2005-005
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00368/2005-005
Number of Items for this Docket: 4			
Percent of Total for this Docket: 24			
Human-System Interface & Environmnt / IR			
173 - Physical conditions LTA	H - Health Physics	H - Health Physics	050-00368/2005-005
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Problem Identification & Resolution / IR			
150 - Programmatic deficiency	O - Operations	O - Control Room Ops	050-00368/2006-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	C - Chemistry	T - Testing	050-00368/2006-003
185 - Procedural adherence LTA	D - Emergency Planning	D - Emergency Drill	050-00368/2006-003
186 - Failure to take action / meet requirements	X - Site-wide	X - Site-wide	050-00368/2006-002
186 - Failure to take action / meet requirements	X - Site-wide	X - Site-wide	050-00368/2006-002
186 - Failure to take action / meet requirements	X - Site-wide	X - Site-wide	050-00368/2006-002
186 - Failure to take action / meet requirements	X - Site-wide	X - Site-wide	050-00368/2006-002
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00368/2005-005
188 - Work practice or craft skill LTA	Q - Quality assurance / oversight	M - Maintenance / Repair	050-00368/2005-005
198 - Worker distracted / interrupted	O - Operations	O - Control Room Ops	050-00368/2005-005
Number of Items for this Docket: 9			
Percent of Total for this Docket: 53			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00368/2006-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 17
National Average: 43
2x National Average: 86
National Median: 24
Average for Selected Dockets: 17

Facility Name: Arkansas Nuclear 2 Docket (050- 00368)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / LER			
147 - Individual corrective action LTA	E - Electrical	M - Maintenance / Repair	050-00368/2006-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			

Total Items for this Docket: 17
