

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 18

---

**Facility Name: Beaver Valley 2 Docket (050- 00412)**

Details	Department	Work Type	Docket/Report
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00412/2006-008
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 6			
<b>Problem Identification &amp; Resolution / IR</b>			
146 - Evaluation LTA	G - Engineering	G - Design	050-00412/2006-004
146 - Evaluation LTA	G - Engineering	G - Design	050-00412/2006-004
150 - Programmatic deficiency	D - Emergency Planning	D - Emergency Drill	050-00412/2006-009
150 - Programmatic deficiency	H - Health Physics	H - Health Physics	050-00412/2006-009
<b>Number of Items for this Docket:</b> 4			
<b>Percent of Total for this Docket:</b> 22			
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00412/2006-002
187 - Action implementation LTA	G - Engineering	F - Modification	050-00412/2006-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00412/2006-003
187 - Action implementation LTA	H - Health Physics	H - Health Physics	050-00412/2006-003
188 - Work practice or craft skill LTA	E - Electrical	M - Maintenance / Repair	050-00412/2005-008
197 - Self-check LTA	O - Operations	B - Bal of Plant Ops	050-00412/2005-008
<b>Number of Items for this Docket:</b> 6			
<b>Percent of Total for this Docket:</b> 33			
<b>Oversight / LER</b>			
130 - Inadequate supervision / command and control	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
130 - Inadequate supervision / command and control	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
131 - Management expectations or directions LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
<b>Number of Items for this Docket:</b> 3			
<b>Percent of Total for this Docket:</b> 17			
<b>Problem Identification &amp; Resolution / LER</b>			
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 11			

---

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18  
National Average: 43  
2x National Average: 86  
National Median: 24  
Average for Selected Dockets: 18

---

**Facility Name: Beaver Valley 2 Docket (050- 00412)**

Details	Department	Work Type	Docket/Report
<b>Training / LER</b>			
100 - Training LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 6			
<b>Work Planning &amp; Practices / LER</b>			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 6			
<b>Total Items for this Docket: 18</b>			

---