

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 44

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 44

Facility Name: Prairie Island 2 Docket (050- 00306)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	D - Emergency Planning	Q - Fire Protection	050-00306/2006-009
170 - HSI or information availability / quality LTA	D - Emergency Planning	Q - Fire Protection	050-00306/2006-009
170 - HSI or information availability / quality LTA	O - Operations	B - Bal of Plant Ops	050-00306/2005-012
Number of Items for this Docket: 3			
Percent of Total for this Docket: 7			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	D - Emergency Planning	S - Surveillance	050-00306/2006-009
111 - Procedure / reference document technical content	I - Instrumentation & Control	S - Surveillance	050-00306/2006-002
113 - Procedure / reference document development and maintenance L	A - Administrative Support	A - Administrative	050-00306/2006-002
113 - Procedure / reference document development and maintenance L	A - Administrative Support	A - Administrative	050-00306/2006-013
113 - Procedure / reference document development and maintenance L	O - Operations	O - Control Room Ops	050-00306/2005-011
113 - Procedure / reference document development and maintenance L	O - Operations	O - Control Room Ops	050-00306/2006-013
Number of Items for this Docket: 6			
Percent of Total for this Docket: 14			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	I - Instrumentation & Control	S - Surveillance	050-00306/2006-002
142 - Operating experience (OE) review LTA	G - Engineering	G - Design	050-00306/2005-011
144 - Audit / self-assessment / effectiveness review LTA	G - Engineering	G - Design	050-00306/2005-011
144 - Audit / self-assessment / effectiveness review LTA	M - Mechanical	V - Troubleshooting	050-00306/2005-011
145 - Causal development LTA	G - Engineering	G - Design	050-00306/2005-011
146 - Evaluation LTA	G - Engineering	G - Design	050-00306/2006-003
147 - Individual corrective action LTA	M - Mechanical	B - Bal of Plant Ops	050-00306/2006-002
149 - No action planned	G - Engineering	G - Design	050-00306/2005-011
Number of Items for this Docket: 8			
Percent of Total for this Docket: 18			
<hr/>			
Training / IR			
101 - Training process problem	O - Operations	O - Control Room Ops	050-00306/2005-011
101 - Training process problem	O - Operations	O - Control Room Ops	050-00306/2006-013
101 - Training process problem	O - Operations	O - Control Room Ops	050-00306/2006-013
102 - Individual knowledge LTA	O - Operations	O - Control Room Ops	050-00306/2006-013

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 44

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 44

Facility Name: Prairie Island 2 Docket (050- 00306)

Details	Department	Work Type	Docket/Report
Training / IR			
103 - Simulator training LTA	O - Operations	O - Control Room Ops	050-00306/2005-011
Number of Items for this Docket: 5			
Percent of Total for this Docket: 11			
<hr/>			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	H - Health Physics	H - Health Physics	050-00306/2006-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00306/2006-004
185 - Procedural adherence LTA	Q - Quality assurance / oversight	A - Administrative	050-00306/2006-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00306/2006-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00306/2006-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00306/2006-009
188 - Work practice or craft skill LTA	D - Emergency Planning	Q - Fire Protection	050-00306/2005-012
188 - Work practice or craft skill LTA	D - Emergency Planning	Q - Fire Protection	050-00306/2005-012
188 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00306/2005-011
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00306/2006-004
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00306/2005-011
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00306/2006-002
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	Q - Fire Protection	050-00306/2006-004
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00306/2006-004
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	Q - Fire Protection	050-00306/2006-009
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00306/2005-011
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00306/2005-011
190 - Failure to stop work / non-conservative decision making	G - Engineering	Q - Fire Protection	050-00306/2005-012
190 - Failure to stop work / non-conservative decision making	G - Engineering	Q - Fire Protection	050-00306/2005-012
196 - Independent verification / plant tours LTA	O - Operations	S - Surveillance	050-00306/2005-012
198 - Worker distracted / interrupted	O - Operations	O - Control Room Ops	050-00306/2005-011
Number of Items for this Docket: 21			
Percent of Total for this Docket: 48			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 44
National Average: 43
2x National Average: 86
National Median: 24
Average for Selected Dockets: 44

Facility Name: Prairie Island 2 Docket (050- 00306)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00306/2006-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			

Total Items for this Docket: 44
