

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 18

Facility Name: Seabrook 1 Docket (050- 00443)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	F - Fuel Handling	R - Refueling	050-00443/2006-005
113 - Procedure / reference document development and maintenance L	P - Procedure Writers	P - Procedure Dev	050-00443/2007-004
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	G - Engineering	G - Design	050-00443/2006-006
146 - Evaluation LTA	G - Engineering	G - Design	050-00443/2006-005
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00443/2007-002
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00443/2007-002
Number of Items for this Docket: 4			
Percent of Total for this Docket: 22			
<hr/>			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	A - Administrative Support	A - Administrative	050-00443/2006-006
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00443/2006-005
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00443/2006-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00443/2006-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00443/2006-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00443/2007-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00443/2007-006
Number of Items for this Docket: 7			
Percent of Total for this Docket: 39			
<hr/>			
Oversight / LER			
130 - Inadequate supervision / command and control	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00443/2007-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
<hr/>			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00443/2007-002-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
<hr/>			
Work Planning & Practices / LER			
182 - Work package quality LTA	O - Operations	O - Control Room Ops	050-00443/2007-001-00
187 - Action implementation LTA	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00443/2007-001-00

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 18

Facility Name: Seabrook 1 Docket (050- 00443)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / LER			
196 - Independent verification / plant tours LTA	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00443/2007-001-00
Number of Items for this Docket: 3			
Percent of Total for this Docket: 17			

Total Items for this Docket: 18
