

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Byron 2 Docket (050- 00455)

Details	Department	Work Type	Docket/Report
Oversight / IR			
130 - Inadequate supervision / command and control	H - Health Physics	H - Health Physics	050-00455/2008-002
130 - Inadequate supervision / command and control	M - Mechanical	M - Maintenance / Repair	050-00455/2008-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 22			
Procedures & Reference Document / IR			
113 - Procedure / reference document development and maintenance L	P - Procedure Writers	P - Procedure Dev	050-00455/2008-009
Number of Items for this Docket: 1			
Percent of Total for this Docket: 11			
Problem Identification & Resolution / IR			
145 - Causal development LTA	D - Emergency Planning	Q - Fire Protection	050-00455/2008-002
146 - Evaluation LTA	G - Engineering	G - Design	050-00455/2008-009
Number of Items for this Docket: 2			
Percent of Total for this Docket: 22			
Work Planning & Practices / IR			
183 - Pre-job activities LTA	M - Mechanical	M - Maintenance / Repair	050-00455/2008-002
185 - Procedural adherence LTA	H - Health Physics	H - Health Physics	050-00455/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00455/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00455/2008-009
Number of Items for this Docket: 4			
Percent of Total for this Docket: 44			
Total Items for this Docket: 9			
