

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: La Salle 1 Docket (050- 00373)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / IR			
141 - Problem not properly classified or prioritized	S - Specialized task force	W - Assessment	050-00373/2007-006
142 - Operating experience (OE) review LTA	M - Mechanical	S - Surveillance	050-00373/2008-002
142 - Operating experience (OE) review LTA	Y - Shipping / transportation	Y - Shipping / transportatic	050-00373/2007-006
146 - Evaluation LTA	G - Engineering	G - Design	050-00373/2008-002
146 - Evaluation LTA	G - Engineering	G - Design	050-00373/2008-002
146 - Evaluation LTA	G - Engineering	G - Design	050-00373/2008-002
146 - Evaluation LTA	I - Instrumentation & Control	T - Testing	050-00373/2008-002
146 - Evaluation LTA	I - Instrumentation & Control	T - Testing	050-00373/2008-002
146 - Evaluation LTA	I - Instrumentation & Control	T - Testing	050-00373/2008-002
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00373/2008-002
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00373/2008-002
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00373/2008-002
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00373/2008-002
148 - Action not yet started or untimely	I - Instrumentation & Control	T - Testing	050-00373/2008-002
148 - Action not yet started or untimely	I - Instrumentation & Control	T - Testing	050-00373/2008-002
148 - Action not yet started or untimely	I - Instrumentation & Control	T - Testing	050-00373/2008-002
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00373/2007-006
Number of Items for this Docket: 17			
Percent of Total for this Docket: 59			

Work Planning & Practices / IR	Department	Work Type	Docket/Report
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00373/2008-002
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00373/2008-002
184 - Tag outs LTA	M - Mechanical	M - Maintenance / Repair	050-00373/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00373/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00373/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00373/2008-002
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00373/2008-002
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00373/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	S - Surveillance	050-00373/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00373/2007-006
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00373/2008-002

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: La Salle 1 Docket (050- 00373)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
196 - Independent verification / plant tours LTA	H - Health Physics	H - Health Physics	050-00373/2008-002
Number of Items for this Docket: 12			
Percent of Total for this Docket: 41			

Total Items for this Docket: 29
