

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: McGuire 1 Docket (050- 00369)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00369/2008-003
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00369/2008-009
Number of Items for this Docket: 2			
Percent of Total for this Docket: 7			
<hr/>			
Procedures & Reference Document / IR			
110 - No procedure / reference documents	O - Operations	O - Control Room Ops	050-00369/2008-002
111 - Procedure / reference document technical content	I - Instrumentation & Control	S - Surveillance	050-00369/2008-003
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00369/2008-003
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00369/2008-003
Number of Items for this Docket: 4			
Percent of Total for this Docket: 13			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00369/2008-008
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00369/2008-009
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00369/2008-009
141 - Problem not properly classified or prioritized	M - Mechanical	M - Maintenance / Repair	050-00369/2008-008
145 - Causal development LTA	M - Mechanical	M - Maintenance / Repair	050-00369/2008-008
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00369/2008-009
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00369/2008-003
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00369/2008-009
Number of Items for this Docket: 8			
Percent of Total for this Docket: 27			
<hr/>			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00369/2008-002
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00369/2008-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00369/2008-008
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00369/2008-009
187 - Action implementation LTA	G - Engineering	G - Design	050-00369/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00369/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00369/2008-008
187 - Action implementation LTA	G - Engineering	G - Design	050-00369/2008-009
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00369/2008-008

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: McGuire 1 Docket (050- 00369)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00369/2008-002
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00369/2008-002
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00369/2008-008
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00369/2008-009
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00369/2008-002
Number of Items for this Docket: 14			
Percent of Total for this Docket: 47			
<hr/>			
Oversight / LER			
131 - Management expectations or directions LTA	G - Engineering	F - Modification	050-00369/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Problem Identification & Resolution / LER			
148 - Action not yet started or untimely	G - Engineering	F - Modification	050-00369/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Total Items for this Docket: 30			
