

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

---

**Facility Name: Millstone 3 Docket (050- 00423)**

Details	Department	Work Type	Docket/Report
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	I - Instrumentation & Control	S - Surveillance	050-00423/2008-002
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00423/2008-003
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 22</b>			
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	O - Operations	Q - Fire Protection	050-00423/2008-003
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 11</b>			
<b>Problem Identification &amp; Resolution / IR</b>			
140 - Problem not completely or accurately identified	I - Instrumentation & Control	S - Surveillance	050-00423/2008-002
146 - Evaluation LTA	G - Engineering	Q - Fire Protection	050-00423/2008-003
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 22</b>			
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00423/2008-003
186 - Failure to take action / meet requirements	G - Engineering	Q - Fire Protection	050-00423/2008-003
187 - Action implementation LTA	G - Engineering	Q - Fire Protection	050-00423/2008-003
190 - Failure to stop work / non-conservative decision making	I - Instrumentation & Control	S - Surveillance	050-00423/2008-002
<b>Number of Items for this Docket: 4</b>			
<b>Percent of Total for this Docket: 44</b>			
<b>Total Items for this Docket: 9</b>			

---